FLEET TEAM DIGEST

737MAX-FTD-04-24001

Issue Title : 737NG/MAX Significant Event Reports

Airplane Model	ATA	Minor Model(s)
737MAX	0400-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
08/01/2024	10/30/2026	10/30/2026

Estimated Completion Date	Next Update Date
12/31/2030	01/31/2027

Revision Description

The Significant Events Report attachment has been added with reported events from 3Q2026.

Description

Several operators have requested that Boeing advise them of significant airplane interruptions/events for their review. Boeing will update this Fleet Team Digest (FTD) article for events that are reported to support Boeing's Continued Operational Safety Program (COSP) process and meet the following criteria:

- Selected ATBs, RTO, RTBs, AOGs, IFSDs, Fire/Heat Damage, Runway Events, and Diversions (DIV)
  - Caused by a significant or unique situation
  - Excludes: Medical emergencies, act of nature events, ground handling equipment damage
- Maintenance caused events resulting in any of the above
  - Including but not limited to: PDA, lockout pins, mis-installed parts, FOD, instrument coverings, etc.
- Any of the events above that lead to significant maintenance burden

Boeing will publish separate FTDs for information when an event relates to a safety or economic service related problem (SRP) or a new system introduction.

This report may not include all events where Boeing is providing technical assistance as a party to a regulatory investigation. In those cases, guidance prescribes that all investigation related information be released by the investigating agency and Boeing will strive to keep operators informed via other means while respecting ICAO Annex 13 standards.

Note: Some subjective judgement is part of identifying events to add to this significant event log. The Boeing 737NG/MAX Fleet Chief Deputies have decision authority on events to include or exclude.

Status

Boeing will periodically update this article to provide information to operators regarding significant in-service or maintenance events. The information is in a matrix attached to this article (Adobe PDF format) under the “attachments" portion of the FTD. This information is available for each significant event report:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- Date (Reported)
- ATA
- Airplane Type
- Hours/Cycles (Reported)
- Event Type (ATB, RTO, RTB, AOG, IFSD, DIV)
- Significant Event (Description of event)
- Action (Actions taken to Return to Service (RTS) the datum airplane)

The attachments are generated using an AI assistant and are based on available information at the time of the data pull. Responses may be incomplete or inaccurate and should not be treated as official Boeing guidance, engineering instructions, or a substitute for approved Boeing documentation. Verify important information with the appropriate Boeing source or qualified representative.

Interim Action

None required from information provided in this article. If an interim action is recommended regarding events discussed in this article, it will be published in separate documents (Fleet Team Digest, Maintenance Tip, Service Letter, BCS, Aircraft Maintenance Manual, Fault Isolation Manual, etc).

Final Action

None required from information provided in this article. If a final action is recommended regarding events discussed in this article, it will be published in separate documents (Fleet Team Digest, Maintenance Tip, Service Letter, BCS, Aircraft Maintenance Manual, Fault Isolation Manual, etc).

Milestones

None required from information provided in this article. If milestones are needed in regards to events discussed in this article, it will be published in separate documents (Fleet Team Digest, Maintenance Tip, Service Letter, BCS, Aircraft Maintenance Manual, Fault Isolation Manual, etc).

Related Categories

- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in
  Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs.
  High failure rate of costly/critical systems
- Significant Technical Flight Interruptions : Issues that cause in-flight events such as rejected takeoffs, air turnbacks, diversions, emergency landings, in-flight shutdowns, and abnormal stops

Attachments:

a) 737NG/MAX Significant Events - 3Q2026

b) 737NG/MAX Significant Events - 2Q2026

c) 737NG/MAX Significant Events - 1Q2026

d) 737NG/MAX Significant Events 4Q2025

e) 737NG/MAX Significant Events 3Q2025

f) 737NG/MAX Significant Events 2Q2025

g) 737NG/MAX Significant Events 4Q2024 + 1Q2025

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

h) 737NG/MAX Significant Events 3Q2024

i) 737NG/MAX Significant Events 2Q2024

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991