FLEET TEAM DIGEST

737MAX-FTD-20-25001

Issue Title : Torque Stripe Application on Circular and Coaxial Connectors

Airplane Model	ATA	Minor Model(s)
737MAX	2097-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
05/20/2025	05/20/2025	05/16/2025

Estimated Completion Date	Next Update Date

Description

This Fleet Team Digest Article is released to notify operators of a new Torque Stripe procedure implemented on circular and coaxial connectors installed during 737 MAX production. A procedure to apply a permanent Sharpie marker line across connector connections has been implemented in production.

As a quality improvement project, Boeing has implemented a Torque Stripe procedure on circular and coaxial connectors installed during 737 MAX production. The procedure instructs the manufacturing team to apply a permanent Sharpie marker line across connector connections after initial installation to indicate that the connectors were properly torqued and seated. This is also intended to be a visual check to determine if the connectors were disturbed in manufacturing after initial installation. Connectors that have safety wires and/or torque putty applied are excluded from this procedure.

Boeing is providing this notification to provide awareness to operators of this procedure as the marker lines are visible on the connectors after delivery. There are no requirements to add the marker lines when connectors are re-installed post-delivery. The manufacturing marker lines will fade through time and no re-application is necessary. Photos of these marker lines applied on connectors are included in the Attachment.

Status

Wire Bundle Installation General Notes Drawings 288A0003 Sheet 3 and 288A0004 Sheet 4 have been updated to include the Torque Stripe procedures on connector installation. Refer to the noted drawing sheets for procedure notes and example figures. This procedure has been implemented in 737 MAX production starting May 2025.

Interim Action

None. Information Only.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

None. Information Only.

Milestones

Drawings Released: May 2025 (Complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Drawing	288A0004 Sheet 3		
Drawing	288A0003 Sheet 3		

Related Categories

- Manufacturing Quality Issues : Issues related to airplane or component manufacturing quality

Attachments:

a) Example Pictures

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991