FLEET TEAM DIGEST

737MAX-FTD-23-18002

Issue Title : Required Installation of a Low Frequency (8.8 kHz) Underwater Locator Device (LF-ULD) to the Airframe

Airplane Model	ATA	Minor Model(s)
737MAX	2300-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
737NG, 747, 777, 787	9E991	

Originated Date	Last Revised Date	Created On
05/07/2018	08/02/2018	08/01/2018
Estimated Completion Date	**Next Update Date**	

Revision Description

Boeing Service Bulletin SB 737-23-1621 has been released.

FTD issue status changed to 'Closed'.

Applicability

All 737 airplanes that are required to have installed on the airframe a low frequency (8.8 kHz) underwater locator device (ULD).

Description

New mandates are going into affect that require a low-frequency (8.8 kHz) underwater locator device (LF-ULD) to be attached to the airframe to help aid in locating the airframe underwater.

Background

ICAO Annex 6 Part 1 recommended the addition of a low frequency underwater locator device to the airframe (fuselage) to aid in locating the airframe underwater. ICAO recommends compliance by 01 January 2018.

The European Aviation Safety Agency (EASA) mandates compliance to the ICAO recommendation by 01 January 2019.

Various other regulatory agencies have adopted the ICAO date (01 January 2018).

Status

Boeing is offering a Service Bulletin to install the LF-ULD onto the airframe (SB737-23-1605). In addition, Boeing is working with local regulatory agencies to provide mandate waivers to the 01 January 2019 implementation deadline.

Interim Action

Boeing offering retro-fit service bulletins to assist operators in retro-fitting their airplanes to include the LF-ULD (SB737-23-1605).

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

Airplane modification to attach the LF-ULD to the airframe.

Milestones

Boeing Service Bulletin Available: 08 June 2018

Operator Action

Incorporate Boeing Service Bulletin SB 737-23-1621

Part Information

Boeing kit number: 824A0099

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-23-1621		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Kit - ULD INSTL	824A0099		

Related Categories

- Regulatory : Issues mandated by airworthiness directive or other regulatory guidance material

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991