FLEET TEAM DIGEST

737MAX-FTD-34-18009

Issue Title : Rockwell Collins WXR-2100A NVRAM Download Tool and Return To Service Guide

Airplane Model	ATA	Minor Model(s)
737MAX	3441-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
10/02/2018	10/02/2018	08/23/2018
Estimated Completion Date	**Next Update Date**	

Applicability

Airplanes equipped with the Rockwell Collins WXR-2100A Weather Radar System.

Description

Rockwell Collins has released an operator WXR-2100A Processor Non-Volatile Memory (NVM) download tool and Boeing Installation Manual/Aircraft Return to Service guide.

Background

Some operators have experienced WXR-2100A Weather Radar System removals on their 737MAX airplanes. The Rockwell Collins NVM download tool and Return to Service guide can provide additional information when troubleshooting faults.

Status

The referenced Rockwell Collins tool and documentation consist of the following three items:

1) Health Monitor Port Tool (HMPT)(Customer Version)- P/N 072-2510-100 Rev -:

A software tool loaded on a laptop that when connected to the front of the WxR Processor RTP-2100 P/N 822-3150-101, allows the user to download the stored NVM memory.

2) Health Monitor Port Tool (HMPT) Quick Reference Guide - P/N 946-0TT1-001 Rev -:

A document with the instructions for using the Health Monitor Port Tool

3) WxR-2100A Boeing Installation Manual and Aircraft Return to Service Instructions - P/N 946-0FN8-001 Rev -:

A document with specific WxR Processor fault codes that can be used to help identify and troubleshoot WxR System faults

If interested in this capability, contact your local Rockwell Collins representative, or Rockwell Collins Technical Support directly at customersupport@rockwellcollins.com.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The HMPT and Guide can also be ordered from Rockwell Collins at the following:

Rockwell Collins

Customer Response Center

400 Collins Rd NE, M/S 133-100

Cedar Rapids, IA 52498-0001

TELEPHONE: 1.888.265.5467

INTERNATIONAL: 1.319.295.5467

FAX NO: 1.319.295.4941

Email: response@rockwellcollins.com

Interim Action

N/A

Final Action

N/A

Milestones

N/A

Operator Action

Contact Rockwell Collins regarding the NVM Tool/Instruction Manual and Installation/Return To Service Manual.

Part Information

WXR-2100A Weather Radar System tools:

-Health Monitor Port Tool (HMPT)(Customer Version)- P/N 072-2510-100 Rev -

-Health Monitor Port Tool (HMPT) Quick Reference Guide - P/N 946-0TT1-001 Rev -

-WxR-2100A Boeing Installation Manual and Aircraft Return to Service Instructions - P/N 946-0FN8-001 Rev -

Supplier Information

Rockwell Collins

Customer Response Center

400 Collins Rd NE, M/S 133-100

Cedar Rapids, IA 52498-0001

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Other	072-2510-100 - Health Monitor Port Tool	-	
Other	946-0TT1-001 - Health Monitor Port Tool Quick Ref	-	08/09/2018
Other	946-0FN8-001 - WxR-2100A Boeing Installation Man	-	01/27/2017

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- CRC - Component Reliability Collaboration : Collaborative process to eliminate component removals in production and the during the first year of new airplane in service
- New Equipment : Information on new parts available now or soon to be introduced

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991