FLEET TEAM DIGEST

737MAX-FTD-34-25001

Issue Title : 737 MAX In Service Nuisance In-Air Overrun Alert

Airplane Model	ATA	Minor Model(s)
737MAX	3449-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
04/30/2025	04/30/2025	01/16/2025

Estimated Completion Date	Next Update Date
05/31/2026	08/28/2025

Description

The Enhanced Ground Proximity Warning System (EGPWS) In-Air Overrun alert is intended to prevent runway overruns during landings with normal flap configurations. This is accomplished by providing a time-critical alert to the crew during approach or flare when the airplane will most likely not be able to stop on the available runway using maximum manual braking. Some operators with this option enabled in their 737NG/MAX fleet have experienced an In-Air Overrun nuisance alert “OVERRUN GO AROUND”. The nuisance alert activates below 50 feet AGL during takeoff, and is due to some derated takeoff thrust settings not exceeding the Throttle Resolver Angle (TRA) threshold required to disable the alert.

Status

Boeing is currently evaluating possible solutions for this issue.

Interim Action

This is a known nuisance alert, no maintenance action is required.

Final Action

Once the solution is developed, tested, and certified, a Boeing Service Bulletin will be released to update system software.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Root Cause Established: 11/2024

Solution Selected: TBD

Change Committed:TBD

Production Incorporation: TBD

Service Bulletin Available: TBD

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
EGPWS		Honeywell	69000940-106

Related Categories

- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991