FLEET TEAM DIGEST

737MAX-FTD-31-18004

Issue Title : Removal of Flight Number After Landing

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
08/23/2018	11/26/2025	11/04/2025
Estimated Completion Date	**Next Update Date**	

Revision Description

There is an update to the Milestone timeline for 737MAX-FTD-31-23002. This FTD will be closed. Please refer to 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2.

Description

Boeing has received reports and inquiries from operator flight crews that the Flight Number on the Auxiliary Outboard Display (AOB) disappears after landing. Boeing notes that this behavior is per design. Boeing has received requests to change this logic.

Background

The Flight Management Computer (FMC) provides the flight number to the Max Displays System (MDS) to display on the AOB. After landing, the FMC computes a completed flight leg and will cease to send this data to the displays.

Status

Boeing has fielded opinion from operators and our technical pilots on how long it would be desired to display the flight number. It was requested to display the flight number for longer than immediately after landing for ease of reference for flight crews.

Boeing is in the process of reviewing how to add the feature to retain the flight number displayed after the FMC computes a completed flight leg.

Boeing will be adjusting this feature so that the Flight Number on the Auxiliary Display is retained longer than right after landing. This improvement will be included in the next Max Displays System (MDS) Blockpoint Release, MDS BP 2, available via Service Bulletin 737-31-1929.

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2 and a list Fleet Team Digest (FTD) articles that are also addressed by the MDS BP 2 release.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

Boeing advises operators and their flight crews that the Flight Number removing from the AOB after landing is per design.

There is no mitigating action to prevent this from occurring.

Final Action

Incorporate MDS BP2.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: (Complete)

Solution Selected: October 2018 (Complete)

Change Committed (PRR 3M0203) 06-JUN-2019: (Complete)

Production Incorporation Available: See 737MAX-FTD-31-23002

Service Bulletin 737-31-1929: Release Schedule Available via 737MAX-FTD-31-23002

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-31-23002		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-18005		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-19001		
Fleet Team Digest Article (FTD)	737MAX-FTD-49-18001		
Production Revision Record (PRR)	3M0203		
Service Bulletin (SB)	737-31-1929		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-18004		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-21005		
Fleet Team Digest Article	737MAX-FTD-80-18001		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

(FTD)			

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Display Processing Computer		Rockwell Collins	822-3252-101

Related Categories

- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991