FLEET TEAM DIGEST

737MAX-FTD-31-20001

Issue Title : Digital Flight Data Acquisition Unit (DFDAU) Software Progression

Airplane Model	ATA	Minor Model(s)
737MAX	3100-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
12/14/2020	09/01/2026	05/19/2026

Estimated Completion Date	Next Update Date
12/31/2038	12/17/2026

Revision Description

Updated overall Formatting/Spacing

Added new Service Engineering DB: BCG27-S200-0011 and Service Letter: 737-SL-31-088 in 'Status'

Added reference to D243A301 Rev M in 'Description'

Description

There are several Digital Flight Data Acquisition Unit (DFDAU) software improvements and upgrades, including Airplane Condition and Monitoring System (ACMS), Digital ACMS Recording (DAR), Airplane Health Management (AHM) and Block Point software loads. This article provides clarification by identifying the associated service letters for each of the released software version.

Boeing Document Applicability for Baseline ACMS, DAR AMI, and Mandatory DB:

D226A101-6 Rev F = Mandatory DB TDY44-7095-2501 (737-8 data frame)

D226A101-6 Rev G = Mandatory DBs TDY44-7095-2501 (737-8 data frame) and BCG41-3131-5705 (737-8A data frame)

D243A301 Rev J = Baseline DB BCG3A-L200-0002 and DAR AMIs BCG26-R200-0000 (appendix B) and BCG24-R200-0002 (Appendix F)

D243A301 Rev K = Baseline DB BCG3B-L200-0003 and DAR AMIs BCG24-R200-0002 (appendix F) and BCG25-R200-0003 (Appendix G)

D243A301 Rev M = Baseline DB BCG3CL200-0004 and DAR AMIs BCG25- R200-0003 (appendix F) and BCG22-R200-0004 (Appendix G)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Note: D226A101-6 and D243A301 can be obtained in the MyBoeingFleet Common Download Service {E-Enabling Ground System Products -> e-EGS Documentation -> Airplane Data and Management -> Data Guides}

Status

The following is a list of the latest ACMS and Mandatory software loads and associated fleet publications.

ACMS Baseline DB

Software Part Number__Service Letter____SL Release Date

TDY4A-7095-2903 ..... Original part

BCG38-L200-0000 ..... 737-SL-31-067 ..... 07/24/2018

BCG39-L200-0001 ..... 737-SL-31-068 ..... 01/31/2019

BCG38-L200-0011 ..... 737-SL-31-073 ..... 02/12/2021

BCG3A-L200-0002 ..... 737-SL-31-076 ..... 02/12/2021 (BP 1.1)

BCG3B-L200-0003 ..... 737-SL-31-084 ..... 12/08/2023 (BP 1.3)

BCG3C-L200-0004 ..... 737-SL-31-093 ..... 01/27/2026 (BP 1.5)

ACMS DAR AMI

Software Part Number_Service Letter____SL Release Date

TDY41-7095-3101 ..... Original part

BCG26-R200-0000 ..... 737-SL-31-068 ..... 01/31/2020

BCG27-R200-0001 ..... 737-SL-31-077 ..... 02/12/2021

BCG24-R200-0002 ..... 737-SL-31-076 ..... 02/12/2021 (BP 1.1)

BCG25-R200-0003 ..... 737-SL-31-085 ..... 12/08/2023 (BP 1.3)

BCG22-R200-0004 ..... 737-SL-31-094 ..... 01/27/2026 (BP 1.5)

ACMS OPS

Software Part Number_Service Letter___SL Release Date

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

TDY49-7095-1802 ..... Original part (BP 0.0 Target System Software (TSS))

TDY48-7095-1803 ..... 737-SL-31-070 ..... 02/07/2019 (BP 1)

TDY4F-7095-1804 ..... 737-SL-31-079 ..... 02/12/2021 (BP 1.1)

TDY4E-7095-1805 ..... 737-SL-31-086 ..... 12/08/2023 (BP 1.4)

MANDATORY OPS

Software Part Number_Service Letter___SL Release Date

TDY48-7095-1902..... Original part (BP 0.0 Mandatory System Software (MSS))

TDY49-7095-1903.....737-SL-31-070..... 02/07/2019 (BP 1)

ACMS AHM DB

Software Part Number_Service Letter____SL Release Date

TDY40-7095-3001 ..... Original part

BSM27-H200-0001 ..... 737-SL-31-065-A 07/30/2018

BSM24-H200-0002 ..... 737-SL-31-065-B 01/08/2019

BSM25-H200-0003 ..... 737-SL-31-065-C 12/32/2019

BSM25-H200-0003 ..... 737-SL-31-065-D 03/31/2020

BSM25-H200-0003 ..... 737-SL-31-065-E 04/06/2020

BSM22-H200-0004 ..... 737-SL-31-065-F 06/02/2025

ACMS Service Engineering DB

Software Part Number_Service Letter____ Release Date

BCG27-S200-0000 ..... N/A..... May 2017

BCG26-S200-0001 ..... N/A..... August 2017

BCG25-S200-0002 ..... N/A..... October 2017

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

BCG24-S200-0003 ..... N/A..... January 2018

BCG23-S200-0004 ..... N/A..... August 2018

BCG22-S200-0005 ..... N/A..... December 2019

BCG21-S200-0006 ..... N/A..... September 2021

BCG20-S200-0007 ..... N/A..... May 2023

BCG2F-S200-0008 ..... N/A..... September 2023

BCG27-S200-0011 ..... 737-SL-31-088 ..... June 2026

ACMS OPERATOR AMI

Software Part Number_Service Letter____Release Date

BCG2C-X200-0000 ..... 737-SL-31-065 ..... 01/08/2019 (NULL AMI with no functionality)

MANDATORY DB

Software Part Number_Service Bulletin____SB Release Date

TDY44-7095-2501 ..... Original part (737-8 data frame)

BCG41-3131-5705 ..... SB 737-31-2114 .....04/26/2023 (737-8A data frame) (BP 1.2)

ACMS OSS

Software Part Number

BCG2C-U000-0359 ..... (DAR A717 and RS422 disabled)

BCG46-U000-01W3 ..... (DAR A717 and RS422 enabled)

Interim Action

Boeing recommends reviewing the referenced Service Letters for information concerning all the software part numbers and functionality.

Final Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing recommends installing the latest software available for the DFDAU.The following is a list of the latest software part numbers (P/N) and associated Service Letters/Bulletins.

ACMS Baseline DB

P/N: BCG3C-L200-0004 ... 737-SL-31-093

ACMS DAR AMI

P/N: BCG22-R200-0004 ... 737-SL-31-094

ACMS OPS

P/N: TDY4E-7095-1805 ... 737-SL-31-086

MANDATORY OPS

P/N: TDY49-7095-1903 ... 737-SL-31-070

ACMS AHM DB

P/N: BSM22-H200-0004 ... 737-SL-31-065

ACMS SERVICE ENGINEERING DB

P/N: BCG27-S200-0011 ... 737-SL-31-088

MANDATORY DB

P/N: BCG41-3131-5705 (737-8A data frame) ... SB 737-31-2114

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Milestones

None.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	737-SL-31-088		
Service Bulletin (SB)	737-31-2114		
Service Letter (SL)	737-SL-31-073		
Service Letter (SL)	737-SL-31-076		
Service Letter (SL)	737-SL-31-077		
Service Letter (SL)	737-SL-31-070		
Service Letter (SL)	737-SL-31-065		
Service Letter (SL)	737-SL-31-068		
Service Letter (SL)	737-SL-31-067		
Service Letter (SL)	737-SL-31-079		
Service Letter (SL)	737-SL-31-084		
Service Letter (SL)	737-SL-31-085		
Service Letter (SL)	737-SL-31-086		
Service Letter (SL)	737-SL-31-093		
Service Letter (SL)	737-SL-31-094		

Related Categories

- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991