FLEET TEAM DIGEST

737MAX-FTD-31-24006

Issue Title : INFO Display Format Manual Weight Entry

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
09/13/2024	08/28/2026	06/25/2026

Estimated Completion Date	Next Update Date
01/31/2030	06/30/2027

Revision Description

There are no updates to this issue at this time.

Applicability

All 737MAX Airplanes

Description

Boeing has identified an issue associated with the INFO Display format's logic to override FMC supplied gross weight during internal lab testing.

When the FMC provides a gross weight (regardless of the validity of the data), the display system will ignore a manually entered gross weight on the INFO display format and will not override the FMC gross weight. All other entries/data fields on the INFO display format are not affected and those values entered on the INFO display format override the FMC data as expected. If the FMC is not operative, the INFO display format selected values will be shown as expected.

Background

The INFO display format can control the flap maneuver bug positions on the speed tape among other speeds and N1 settings. The INFO display format is intended to be used when there is no operative FMC. Normally entered INFO display format data is expected to override the FMC data in all conditions.

This issue has no effect on the supplemental procedure described in section 10 of the FCOM titled “Setting Airspeed Bugs with No Operative FMC (Manual Airspeed Bug Setting)".

Status

There are no mitigations available or required. Flight Operations are not expected to be impacted by this issue.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

The crew should be made aware, whenever deemed necessary, that manually changing the weight on the INFO display format with an operative FMC will not update the flap maneuver bugs on the speed tape. The INFO display format will not override valid FMC data.

NOTE: Procedurally, the crew is not expected to use the INFO display format when the FMC is fully functional.

Final Action

There are currently no crew or maintenance actions that will fix the issue. A fix is expected to address this issue on the next Display Software revision, MDS BP3.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Complete
Solution Selected: Complete
Change Committed: TBD
Production Incorporation: TBD
Service Bulletin Available: TBD

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Flight Crew Operating Manual (FCOM)	SP.10.3		

Related Categories

- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991