FLEET TEAM DIGEST

737MAX-FTD-34-17001

Issue Title : Flight Management Computer System (FMCS) - Update 13.0 Operational Software 737 MAX

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
03/15/2017	05/10/2017	04/25/2017
Estimated Completion Date	**Next Update Date**	

Revision Description

Added U13 S/L release date and closed FTD.

Applicability

All 737 MAX airplanes.

Description

The U13 FMC software includes several new features unique to the MAX airframe. U13 also addresses in-service issues reported in previous FMC software installed on the 737NG airplane.

The following provides a list of the new features added in the U13 FMC software unique to the 737 MAX airplane. Additional details related to these features are provided in the attachment to this FTD:

Percent Derates and Variable Takeoff Derates.

New scratchpad message - FUEL DISAGREE.

Engine Logic – EPM/TRM & Takeoff Speeds.

Clock Input and Time & Date Entry.

TAT in-air check.

Displays- Data output on Ethernet to MDS.

Model Engine Database (MEDB) Revision, BCG-01T-A1.

Angle of Attack & Vref+40.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Fuel Alerting Logic.

BITE Network File Server (NFS).

The following lists 737NG in-service issues that are addressed in the U13 software. A complete list of problem reports that are addressed in U13 is provided in Boeing Fleet Team Digest article, 737NG-FTD-34-16006:

FMC Restart due to collapsed lateral offsets when accessing the RTE page.

Incorrect transfer of Arrival altitude / Speed constraints when a runway change is made.

On ground FMC restart after landing due to additional maintenance processing after flight complete.

Restart when a very long Direct To with large altitude change in conjunction with a receipt of an ADS contract report.

Restart when there is a hold at the end of a route (typical missed approach) with a receipt of an ADS contract report.

Nuisance display of Verify Takeoff Speeds message occurring at Engine Start.

Status

Update 13.0 will be basic on all 737 MAX airplanes. This is the basic installation and there will be no retrofit service bulletin required for the 737 MAX airplane.

Interim Action

No Interim Action required

Final Action

Final Action consists of delivery of U13 and release of the referenced Service Letter.
The Service Letter provides information of the changes associated with U13.

Operator Action

Operators are required to contact their Navigation Database (NDB) Supplier and advise of their intention to incorporate U13 into their 737 fleet. This will alert the NDB supplier to add U13 compatibility (set the U13 compatibility bit) in the custom NDB database subscription. Navigation Databases that do not have their U13 compatibility bit set will not load into FMCs configured with U13 operational software (Ref FTD, 737-FTD-34-11002).

Operators are encouraged to review the attachment to this FTD which provides details of new functionality not present in 737NG airplanes.

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737NG-FTD-34-11002		
Fleet Team Digest Article (FTD)	737NG-FTD-34-15001		
Service Letter (SL)	737-SL-34-240		04/26/2017

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Update 13 Operational Software	10-62225-1022/Media Set 559777-001		GE Aviation

Related Categories

- New Equipment : Information on new parts available now or soon to be introduced

Attachments:

a) U13 737-MAX added functions

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991