FLEET TEAM DIGEST

737MAX-FTD-25-18001

Issue Title : Improved Retention of 1st Observer Cup-Holder Assembly

Airplane Model	ATA	Minor Model(s)
737MAX	2511-00	-8
Other Model(s)	**ECCN**	
737NG	9E991	

Originated Date	Last Revised Date	Created On
03/22/2018	07/17/2018	07/11/2018
Estimated Completion Date	**Next Update Date**	

Revision Description

To References, added Other SAIB (Special Airworthiness Information Bulletin) NM-18-18, dated 02-JUL-2018.

Applicability

737 MAX airplane Line Numbers (LN) 5602-6640.

Description

Boeing recommends that operators improve the retention of the 1st Observer cup holder installation to prevent the possibility of Foreign Object Debris (FOD) from entering into the P6-11 Circuit Breaker Panel.

Background

* The 1st Observer cup holder installation, located to the right of the 1st Observer seat, is positioned above the P6-11 circuit breaker panel and can only be accessed when the 1st Observer seat is lowered from the stowed position.

* When removing a cup, it was found that the cup remained attached to the cup holder, providing an opening for FOD to pass into the P6-11 circuit breaker panel and increase the risk of an electrical short circuit.

Status

Boeing has released SB 737-25-1791 to create Cup Holder Assembly P/N 232A4262-5 by applying two (2) Adhesive Film P/N 232A4262-7 under the flange of Cup Holder Assembly P/N 232A4262-1.

Interim Action

At a convenient maintenance opportunity, determine if Cup Holder Assembly Part Number (P/N) 232A4262-1 is currently installed (if not, obtain and install it).

Final Action

Accomplish SB 737-25-1791.

Milestones

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Production Incorporation/Delivery (LN 6643 / 1B203): 22-Dec-2017 (complete)

SB 737-25-1791 Original Issue: 06-Apr-2018 (complete)

Operator Action

Perform Interim Action and/or Final Action.

Affected Documents

Aircraft Illustrated Parts Catalog (AIPC) 25-11-00-03

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Illustrated Parts Catalog (IPC)	25-11-00-03		
Service Bulletin (SB)	737-25-1791		
Other	SAIB NM-18-18		07/02/2018

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Retainer	232A4295-2 (sheet 2)		
1st Observer Cup Holder Installation	232A4222-5#B (sheet 10)		
Cup Holder Assembly	232A4262-5 (sheet 5)		
Cup Holder	232A4280-5 (sheet 4)		
Adhesive Film	232A4262-7 (sheet 7)		

Related Categories

- Regulatory : Issues mandated by airworthiness directive or other regulatory guidance material

Attachments:

a) 1st Observer Cup-Holder Retention

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991