FLEET TEAM DIGEST

737MAX-FTD-27-17005

Issue Title : Nuisance SPOILER LOAD ALLEVIATION Fault

Airplane Model	ATA	Minor Model(s)
737MAX	2761-45	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
10/10/2017	05/07/2019	04/23/2019

Estimated Completion Date	Next Update Date

Revision Description

Updated Milestones and change status to Closed.

Applicability

All 737MAX airplanes.

Description

On the ground, after the ADIRU's are aligned, if disruption to airplane power occurs for over 60 seconds, operators may experience MAINT LIGHT illumination with SPOILER LOAD ALLEVIATION status message.

Background

This nuisance fault has been found to occur on the ground if airplane power is interrupted after the ADIRU's have been aligned.

Status

Boeing has investigated the root cause of this nuisance message and assessed the appropriate Spoiler Control Electronics software change(s) to suppress these nuisance faults.

Boeing is releasing Service Bulletin SB 737-27-1309 for incorporation of the -0103 Spoiler Control Electronics (SCE) software in the airplane. This SCE software contains a software change which will prevent SPOILER LOAD ALLEVIATION nuisance faults from occurring in the future. The Service Bulletin and Illustrated Parts Catalog update is planned for May 2019.

Interim Action

If the fault occurs, maintenance should perform Existing Flight Deck Effects Check, TASK 46-13-02-700-803.

If SPOILER LOAD ALLEVIATION Status message does not have a correlated maintenance message, then perform Erase Latched Status Messages, TASK 31-65-00-710-010. Verify that the latched messages erase and no faults are present.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

Boeing is updating the SCE software to suppress nuisance faults when the aircraft is operating on battery/standby power. This software change is being implemented in 737-7 MAX SCE and is expected to be available to operators in May 2019.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

SRP Initiated: 17 Jan 2018 (Complete)

Service Bulletin Available: April 05, 2019 (Complete)

Illustrated Parts Catalog revision: May 15, 2019

Operator Action

Refer to the Service Bulletin for instructions on how to incorporate this airplane loadable software into the Spoiler Control Electronics.

Related Categories

- In Service Occurrences : null

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991