PTF ALL

Brakes Overheated During Stop - Fault Isolation

A. Description

(1) This task is for this observed fault:

(a) Brakes: overheated during stop.

(2) When the brakes are overheated, the flight deck indicators are:

(a) The BRAKE TEMP light on the multi-function panel is ON.

(b) The brake temperature readout is 5.0 or more, displayed in amber color.

(c) The brake temperature symbol is solid amber.

B. Initial Evaluation

(1) Do this task:

- High Energy Stop, AMM TASK 05-51-07-210-801.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details