PTF ALL

Volcanic Ash Condition - Fault Isolation

A. Initial Evaluation

(1) Do this task:

Volcanic Ash Operational Encounter Conditional Inspection, AMM TASK 05-51-31-210-801.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details