PTF ALL

Turbulence (Severe), Stall, Buffet, or Overspeed - Fault Isolation

A. Initial Evaluation

(1) Do this task:
Severe or Unusual Turbulence, Excessive Maneuver, Buffet, or Speeds More than the Design Limits Conditional Inspection, AMM TASK 05-51-04-210-801.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details