PTF ALL

Overspeed With Flaps/Slats Extended - Fault Isolation

A. Initial Evaluation

(1) Do the applicable task:

Phase I Inspection, AMM TASK 05-51-08-210-801,

- Phase II Inspection, AMM TASK 05-51-08-210-802.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details