PTF ALL

Maintenance Message 21-30281 - Fault Isolation

WHEELS ON GND SIGNAL FROM PSEU AIR/GND SYS 1 AND PSEU AIR/GND SYS 2 DO NOT AGREE
DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-2

CORRECTIVE ACTION SUMMARY

Correct Related Maintenance Messages
Repair Wiring D11138-D10740B
Repair Wiring D10988-D10740B
Replace Proximity Switch Electronics Unit [M2061]

A. Description

(1) This task is for this maintenance message:
  (a) WHEELS ON GND SIGNAL FROM PSEU AIR/GND SYS 1 AND PSEU AIR/GND SYS 2 DO NOT AGREE

B. Initial Evaluation

(1) Do this task:
  • Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Look in OMF Existing Faults, 32 Proximity Switch Electronic Unit for related maintenance messages.
  (a) If you find any related maintenance messages, then do these steps:
    1) Do the fault isolation task for each related maintenance message.
    2) Do the AMM test that you did at the start of this task.
    3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (b) If you do not find related maintenance messages, then continue.

(2) Do this check of the wiring:
  (a) Disconnect connector D11138 from the proximity switch electronics unit, M2061.
  (b) Remove the cabin pressure controller 2, M1654. This is the task:
    • Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.
  (c) Do a wiring check between this pin of connector D11138 at the proximity switch electronics unit and this pin of connector D10740B at the E1-1 rack (WDM 21-31-24):

D11138		D10740B
pin 12	.....	pin B1

  (d) If you find a problem with the wiring, then do these steps:
    1) Repair the wiring.
    2) Re-connect connector D11138 to the proximity switch electronics unit, M2061.
    3) Re-install the cabin pressure controller 2, M1654. This is the task:
      • Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
    4) Do the AMM test that you did at the start of this task.
    5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (e) If you do not find a problem with the wiring, then continue.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

(f) Re-connect connector D11138 to the proximity switch electronics unit, M2061.

(3) Do this check of the wiring:

(a) Disconnect connector D10988 from the proximity switch electronics unit, M2061.

(b) Do a wiring check between this pin of connector D10988 at the proximity switch electronics unit and this pin of connector D10740B at the E1-1 rack (WDM 21-31-24):

D10988		**D10740B**
pin 12	.....	pin B4

(c) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-connect connector D10988 to the proximity switch electronics unit, M2061.

3) Re-install the cabin pressure controller 2, M1654. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

4) Do the AMM test that you did at the start of this task.

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(d) If you do not find a problem with the wiring, then continue.

(e) Re-install the cabin pressure controller 2, M1654. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(4) Replace the proximity switch electronics unit, M2061. These are the tasks:
- Proximity Switch Electronics Unit Removal, AMM TASK 32-09-10-000-801,
- Proximity Switch Electronics Unit Installation, AMM TASK 32-09-10-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details