PTF ALL

Maintenance Message 21-30300 - Fault Isolation

LOW AIR SUPPLY OR HIGH FUSELAGE LEAKAGE

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Correct Related Maintenance Messages
Do the applicable AMM Task(s)

A. Description

(1) This task is for this maintenance message:

(a) LOW AIR SUPPLY OR HIGH FUSELAGE LEAKAGE

(2) This maintenance message does not indicate a fault with the digital cabin pressurization control system.

B. Initial Evaluation

(1) Do this task:

- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Look in OMF Existing Faults, 21 Air Conditioning for related maintenance messages.

(a) If you find any related maintenance messages, then do these steps:

1) Do the fault isolation task for each related maintenance message.

2) Do the AMM test that you did at the start of this task.

3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(b) If you do not find related maintenance messages, then continue.

(2) Look in OMF Existing Faults, 21 Cabin Pressure for related maintenance messages.

(a) If you find any related maintenance messages, then do these steps:

1) Do the fault isolation task for each related maintenance message.

2) Do the AMM test that you did at the start of this task.

3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(b) If you do not find related maintenance messages, then continue.

(3) Look in OMF Existing Faults, 36 Pneumatics for related maintenance messages.

(a) If you find any related maintenance messages, then do these steps:

1) Do the fault isolation task for each related maintenance message.

2) Do the AMM test that you did at the start of this task.

3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(b) If you do not find related maintenance messages, then continue.

(4) Do this task:

- Cabin Pressure Leak Test, AMM TASK 05-51-91-790-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details