Flight Compartment Heated Windshield (Mod S.O.O. 6187 and Mod 6/2045) – Maintenance Practices

1. Inspection/Check

A. Delamination Check

There are no technical limitations on delamination of the heated windshield. If delamination is observed, the serviceability of the windshield is dependent on the optical distortion caused by the delamination. The acceptance of optical distortion must remain with the pilot.

**This Page Intentionally Left Blank**