
## **CAMERA CALIBRATION TARGET**

Print at 100% scale - Do not scale to fit



## **CALIBRATION INSTRUCTIONS:**

1. Print this page at 100% scale (no scaling!)

2. Place on printer bed within camera view

50mm Scale Check

Measure with ruler to verify

correct print scale

3. Use "Calibrate Pixel Size" - draw 50mm line across center crosshair

- 4. Use "Center Camera" click on center dot to auto-center
- 5. Add reference points by clicking corner targets (TL, TR, BL, BR)