

Republic of the Philippines **Department of Information and Communications Technology** NATIONAL TELECOMMUNICATIONS COMMISSION

Regional Office No. VII

NETWORK RADIO STATION LICENSE

Form No. R7-13385-24 NEW 30 October 2024

LICENSEE:

CEBU ENERGY DEVELOPMENT CORPORATION

POSTAL ADDRESS:

Daanlungsod, Toledo City, Cebu

FREQUENCY(IES):

Tx:437.200MHz/Rx:432.200MHz

BANDWITH EMISSION:

F3E

NATURE OF SERVICE:

CV

EFFECTIVITY:

30 October 2024

TO

29 October 2025

SERVICE AREA:

within Toledo City and vicinity

	License No	Location	Call Sign	Power (kw) Equipment	Serial No
I	7PCV-29392-24	PORTABLE	4EA-8717	0.005 MOTOROLA XIR P6620i	867TZB6639
2	7PCV-29393-24	PORTABLE	4EA-8718	0.005 MOTOROLA XIR P6620	867TZB6641

-- nothing follows ----

OR NO: 1452788 DATE: 10/30/24 SUBTOTAL: 1,862.00 TOTAL: 2,204.00 LF: 960.00 CP: 0.00 IF: 480.00 AF: 360.00 SUF: 32.00 MF: 0.00 SUR: 0.00 DS: 30.00

By Authority of the mmissioner:

ATTY. ALAN FELIX J. MACARAYA JR.

Officer-In-Charge BY: RICCI ANGELA C. CANTOS the provisions of Act No. 3846, as amended and the regulations promulgated thereunder, and the

This license is valid only when the payment of the required fees is indicated hereon Renewal of this license should be filed Sixty (60) days before expiration

This license is issued subject to inspection of the radio station at any available time. Any discrepancy(ies) found at the time of inspection will cause the revocation of this license

The actual operation of this radio station be carried only at all times by duly licensed radio operator.

Issuance of this license is without prejudices to any administrative cases filed against these stations or may be filed for previously committed violations

"Elevating the Philippines as the leading ICT-driven economy in Asia"

Documentary Stamp Tax Paid

: Subangdaku, Mandaue City, Cebu Address E-mail: ntc regionvii@yahoo.com *: http://r7.ntc.gov.ph Telefax Nos.: (032) 346-0179; 345-0823; 422-6822 Page 1 of 1

NOTE:

Issued without inspection. Any discrepancy or non-availability of this license during inspection is a violation of R. A. 3846, as amended