## ELT MACTAN AVIATION TECHNOLOGY CENTER INC. **REI SHOP** APPROVED MAINTENANCE ORGANIZATION NO. 91-10 DATE OF TEST: WORK ORDER NUMBER: WORKSHEET ISSUE: November 30, 2024 102404 112404 AIRCRAFT MAKE AND MODEL: AIRCRAFT S/N: AIRCRAFT REGISTRY: 15281202 CESSNA 152 RP-C2790 AIRFRAME TIME: CUSTOMER: ADVENTURE FLIGHT EDUCATION AND SPORTS 8.321:02 Hrs. INSPECTION AND TEST DATA **ELT CHECK ELT SERIAL NUMBER ELT MODEL/PARTNUMBER ELT MANUFACTURER** 24521 AMERI-KING CORPORATION AK-451 FREQUENCY COUNTRY CODE **ELT Unique ID Number (HEX ID)** 406.028 MHz C486A B6E65 C0CD1 548 (Philippines) **BATTERY CHECK BATTERY CONDITION BATTERY OUTPUT BATTERY EXPIRY DATE** OK FEBRUARY 24, 2027 12.0 V FLT TESTER DATA **TESTER CAL DUE** ELT TESTER MODEL/PART NO. ELT TESTER SERIAL NO. **ELT TESTER MANUFACTURER** CHECK CAL DUE 17119 BT 406-03 AEROMARINE SRT LTD TEST: PASSED/FAILED TEST RESULT: BEACON ID: C486A B6E65 C0CD1 DETECTED ON: November 30, 2024 This is to certify that ELT installed in the aircraft indicated above was inspected in accordance with the applicable aircraft and ELT manufacturer's instructions, ADVISORY CIRCULAR (AC) 43.13-1B CHG 1 SECTION 12-22 (INSPECTION OF ELT - FOR PROCEDURE) OF FEDERAL AVIATION ADMINISTRATION, SEARCH AND RESCUE SATELLITE AIDED TRACKING (SARSAT) POLICY ON NON-DISTRESS TRANSMISSIONS, PART V - STANDARD 571 APPENDIX G (MAINTENANCE OF EMERGENCY LOCATOR TRANSMITTERS) OF FEDERAL AVIATION ADMINISTRATION AND/OR, MANUFACTURER RECOMMENDATION. All the mentioned standards and procedures meets requirements of PCAR Part 7 of the Civil Aviation Authority of the Philippines. TEST PERFOMED BY: APPROVED BY: MAINTENANCE MANAGER AMS TECHNICIAN

152977-AMS

JEFFERSON P. ALFORQUE

SYSVESTER CARNECER

101527-AMT