

## REPUBLIC OF THE PHILIPPINES NATIONAL TELECOMMUNICATION COMMISSION



## **RADIO STATION LICENSE**

License No.7PCV-17871-2019

**REN** Sep 10, 2025

anted this license to control of the	ocation E Longitude	A Radi Dana Class		ortable
ATION located at th the following parti Geographical Lo	culars.  ocation  E Longitude	<b>Dana</b> Class	of Station Pc	
ith the following parti	ocation E Longitude			
	E Longitude			
				/ (Private)
	Nilatituda			
	N Latitude	Call S	ign (See Below)	
			s of Operation	
FREQUENCIES	BANDWIDTH AND TYPE OF EMISSION	POWER	PARTICULARS OF ANTENNA	REMARKS
	F3E MHz		Height: Power Output: N/A Gain: Directivity: Diameter: Polarization: Beamwidth:	
	PAR	TICULARS OF EQ	UIPMENTS	FREQUENCY
1	<i>CALLSIGN</i> 4DCN-7180	<i>MAKE/TYPE/MODEL</i> Hytera BD508	<b>SERIAL NO</b> 16D06D0955	RANGE
2	4DCN-7181	Hytera BD508	16D06D0956	400-470
3	4DCN-7182	Hytera BD508	16D06D1211	400-470
4	4DCN-7183	Hytera BD508	16D06D1216	6 400-470

This license is issued subject to the provisions of the Radio Control Law. Act No. 3846 as Amended and the regulations promulgated thereunder and the Radio Regulations annexed to the International Telecommunications Convention in

ALAN FELIX MACARAYA, JR.

Regional Director, NTC VII

## Ву: Notes

O.R.

force.

No.

AMOUNT

Date:

1. The registration of the above-stated radio equipment during the said period shall not be construed as an authority to possess, construct and/or operate the same without the corresponding permits/licenses Any violation pertaining to the use of such registered equipment including its use by persons other than the registrant shall be ground for appropriate administrative sanctions and/or fines and penalties as be imposed by this Commission.

2. All radio equipment registered under this Memorandum Order shall be at the accountability of the

P1,230.00

registrant

3. The subsequent licensing of all radio equipment to be registered under and pursuant to this Memorandum Order shall be in accordance with existing rules and regulations and the usual licensing procedures.