

Quality Management System Overview

Purpose

This document defines the Quality Management System (QMS) at Acme Corporation. The QMS ensures that all products and services consistently meet customer requirements and regulatory standards.

Scope

This QMS applies to all manufacturing operations, quality assurance activities, and supporting processes across all production lines and facilities.

Quality Policy

Acme Corporation is committed to:

1. Delivering products that meet or exceed customer specifications
2. Continuously improving processes through data-driven decision making
3. Complying with all applicable regulatory and statutory requirements
4. Empowering employees to identify and resolve quality issues
5. Maintaining an effective Quality Management System aligned with ISO 9001

QMS Structure

Document Hierarchy

The QMS consists of four levels:

Level 1 — Quality Manual: Defines the quality policy, objectives, and QMS scope. Level 2 — Standard Operating Procedures (SOPs): Describe cross-functional processes and responsibilities. Level 3 — Work Instructions (WIs): Provide detailed task-level instructions for specific operations. Level 4 — Forms, Records, and Templates: Capture evidence and data.

Key Processes

The QMS governs the following key processes:

- Document Control (SOP-QA-002)
- Non-Conformance Management (SOP-QA-012)
- Corrective and Preventive Action (CAPA-004)
- Internal Auditing (SOP-QA-008)
- Supplier Quality Management (SOP-QA-015)
- Calibration Management (WI-019)
- Training and Competency (SOP-QA-007)

Organizational Structure

The Quality Assurance department reports to the Plant Director. Each production line has a designated QA Supervisor who is the first point of contact for quality-related issues. The QA Manager oversees the entire QA department and chairs the Quality Management Review meeting.

Management Review

Top management reviews the QMS quarterly. The review agenda includes:

- Status of corrective and preventive actions
- Audit results (internal and external)
- Customer feedback and complaints
- Process performance and product conformity
- Status of preventive actions
- Follow-up actions from previous management reviews
- Changes affecting the QMS

Continuous Improvement

Acme Corporation uses the Plan-Do-Check-Act (PDCA) cycle for continuous improvement. All employees are encouraged to submit improvement suggestions. The QA department tracks improvement initiatives through the CAPA system.

Document Control

This document is controlled. The current version is maintained by the QA department. Uncontrolled copies may be outdated. Verify the current version before use.

Related Documents

- SOP-QA-012: Non-Conformance Report Procedure
- CAPA-004: Corrective and Preventive Action Procedure
- SOP-QA-008: Internal Audit Procedure
- SOP-QA-015: Supplier Quality Management

Document Version 2.1 — Last Updated January 2026