

| Test no. | Normal stress        |              | Static / Cyclic stress ratio                         | Experimental method   | Drain condition | Sample size               | Fines content | Dry density                   | Density index | Void ratio | Number of load cycles | Liquefaction behavior   |
|----------|----------------------|--------------|------------------------------------------------------|-----------------------|-----------------|---------------------------|---------------|-------------------------------|---------------|------------|-----------------------|-------------------------|
|          | / Confining pressure |              |                                                      |                       |                 |                           |               |                               |               |            |                       |                         |
|          | $\sigma$ (kPa)       | $\tau$ (kPa) |                                                      |                       |                 |                           |               |                               |               |            |                       |                         |
|          |                      |              | $\tau/\sigma$ / CSR ( $\tau/\sigma$ or $q/2\sigma$ ) | Ring shear / Triaxial | Undrain / Drain | Mixture ( $D_{50}$ ) (mm) | FC (%)        | $\rho_d$ (g/cm <sup>3</sup> ) | $I_d$         | $e$        | $N_L$                 | C (Yes) / D-C (No)      |
| UT-1     | 150.00               | 0            | 0.500                                                | Ring shear            | Undrain         | 0.048                     | 0.0           | 1.2347418                     | 0.638554217   | 1.13       |                       | Yes (ru > 0.90)         |
| UT-2     | 150.00               | 13           | 0.500                                                | Ring shear            | Undrain         | 0.048                     | 0.0           | 1.2464455                     | 0.662650602   | 1.11       |                       | No (Small deformation)  |
| UT-3     | 150.00               | 26           | 0.500                                                | Ring shear            | Undrain         | 0.048                     | 0.0           | 1.2347418                     | 0.638554217   | 1.13       |                       | No (Small deformation)  |
| UT-4     | 150.00               | 40           | 0.500                                                | Ring shear            | Undrain         | 0.048                     | 0.0           | 1.228972                      | 0.626506024   | 1.14       |                       | No (Small deformation)  |
| UT-5     | 150.00               | 55           | 0.500                                                | Ring shear            | Undrain         | 0.048                     | 0.0           | 1.228972                      | 0.626506024   | 1.14       |                       | No (Small deformation)  |
| UT-6     | 150.00               | 70           | 0.500                                                | Ring shear            | Undrain         | 0.048                     | 0.0           | 1.2347418                     | 0.638554217   | 1.13       |                       | Yes (Large deformation) |
| UT-7     | 150.00               | 0            | 0.500                                                | Ring shear            | Undrain         | 0.04                      | 10.0          | 1.2583732                     |               | 1.09       |                       | Yes (ru > 0.90)         |
| UT-8     | 150.00               | 13           | 0.500                                                | Ring shear            | Undrain         | 0.04                      | 10.0          | 1.2644231                     |               | 1.08       |                       | No (Small deformation)  |
| UT-9     | 150.00               | 26           | 0.500                                                | Ring shear            | Undrain         | 0.04                      | 10.0          | 1.2464455                     |               | 1.11       |                       | No (Small deformation)  |
| UT-10    | 150.00               | 40           | 0.500                                                | Ring shear            | Undrain         | 0.04                      | 10.0          | 1.252381                      |               | 1.1        |                       | No (Small deformation)  |
| UT-11    | 150.00               | 55           | 0.500                                                | Ring shear            | Undrain         | 0.04                      | 10.0          | 1.2464455                     |               | 1.11       |                       | No (Small deformation)  |
| UT-12    | 150.00               | 70           | 0.500                                                | Ring shear            | Undrain         | 0.04                      | 10.0          | 1.2955665                     |               | 1.03       |                       | Yes (ru > 0.90)         |
| UT-13    | 150.00               | 0            | 0.500                                                | Ring shear            | Undrain         | 0.024                     | 20.0          | 1.3418367                     |               | 0.96       |                       | Yes (ru > 0.90)         |
| UT-14    | 150.00               | 13           | 0.500                                                | Ring shear            | Undrain         | 0.024                     | 20.0          | 1.3282828                     |               | 0.98       |                       | No (Small deformation)  |
| UT-15    | 150.00               | 26           | 0.500                                                | Ring shear            | Undrain         | 0.024                     | 20.0          | 1.3350254                     |               | 0.97       |                       | No (Small deformation)  |
| UT-16    | 150.00               | 40           | 0.500                                                | Ring shear            | Undrain         | 0.024                     | 20.0          | 1.3350254                     |               | 0.97       |                       | Yes (Large strain)      |
| UT-17    | 150.00               | 55           | 0.500                                                | Ring shear            | Undrain         | 0.024                     | 20.0          | 1.3418367                     |               | 0.96       |                       | Yes (Large strain)      |
| UT-18    | 150.00               | 70           | 0.500                                                | Ring shear            | Undrain         | 0.024                     | 20.0          | 1.3626943                     |               | 0.93       |                       | Yes (Large strain)      |
| UT-1     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         | 0.14                      | 0.0           | 1.3773389                     |               | 0.924      | 9                     | Yes (ru > 0.95)         |
| UT-2     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 3.0           | 1.3773389                     |               | 0.924      | 8                     | Yes                     |
| UT-3     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 5.0           | 1.3780551                     |               | 0.923      | 7                     | Yes                     |
| UT-4     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 7.0           | 1.3780551                     |               | 0.923      | 5                     | Yes                     |
| UT-5     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 9.0           | 1.3794898                     |               | 0.921      | 17                    | Yes                     |
| UT-6     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 11.0          | 1.3802083                     |               | 0.92       |                       | No                      |
| UT-7     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 15.0          | 1.3816475                     |               | 0.918      |                       | No                      |
| UT-8     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 15.0          | 1.3802083                     |               | 0.92       |                       | Yes                     |
| UT-9     | 105.00               |              | 0.428571429                                          | Ring shear            | Undrain         |                           | 15.0          | 1.3809276                     |               | 0.919      |                       | Yes                     |
| UT-8     | 220.00               | 0            | 0.273                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.4745763                     | 0.784313725   | 0.77       | 2                     | Yes ( $r_u > 0.95$ )    |
| UT-9     | 213.00               | 0            | 0.282                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5                           | 0.843137255   | 0.74       | 1                     | Yes ( $r_u > 0.95$ )    |
| UT-10    | 201.00               | 0            | 0.299                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.4914286                     | 0.823529412   | 0.75       | 2                     | Yes ( $r_u > 0.95$ )    |
| UT-11    | 210.00               | 0            | 0.286                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5174419                     | 0.882352941   | 0.72       | 4                     | Yes ( $r_u > 0.95$ )    |
| UT-12    | 206.00               | 0            | 0.291                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5263158                     | 0.901960784   | 0.71       | 3                     | Yes ( $r_u > 0.95$ )    |
| UT-13    | 199.00               | 0            | 0.302                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5628743                     | 0.980392157   | 0.67       | 6                     | Yes ( $r_u > 0.95$ )    |
| UT-14    | 205.00               | 0            | 0.293                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5086705                     | 0.862745098   | 0.73       | 7                     | Yes ( $r_u > 0.95$ )    |
| UT-15    | 204.00               | 0            | 0.294                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5                           | 0.843137255   | 0.74       | 7                     | Yes ( $r_u > 0.95$ )    |
| UT-16    | 192.00               | 0            | 0.313                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5086705                     | 0.862745098   | 0.73       | 7                     | Yes ( $r_u > 0.95$ )    |
| UT-17    | 187.00               | 0            | 0.321                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5                           | 0.843137255   | 0.74       | 4                     | Yes ( $r_u > 0.95$ )    |
| UT-18    | 207.00               | 0            | 0.290                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5352941                     | 0.921568627   | 0.7        | 8                     | Yes ( $r_u > 0.95$ )    |
| UT-19    | 209.00               | 0            | 0.287                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5443787                     | 0.941176471   | 0.69       | 10                    | Yes ( $r_u > 0.95$ )    |
| UT-20    | 233.00               | 0            | 0.258                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5086705                     | 0.862745098   | 0.73       | 18                    | Yes ( $r_u > 0.95$ )    |
| UT-21    | 227.00               | 0            | 0.264                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5263158                     | 0.901960784   | 0.71       | 14                    | Yes ( $r_u > 0.95$ )    |
| UT-22    | 226.00               | 0            | 0.265                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5352941                     | 0.921568627   | 0.7        | 18                    | Yes ( $r_u > 0.95$ )    |
| UT-23    | 212.00               | 0            | 0.283                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5535714                     | 0.960784314   | 0.68       | 23                    | Yes ( $r_u > 0.95$ )    |
| UT-24    | 205.00               | 0            | 0.293                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5443787                     | 0.941176471   | 0.69       | 12                    | Yes ( $r_u > 0.95$ )    |
| UT-25    | 204.00               | 0            | 0.294                                                | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5628743                     | 0.980392157   | 0.67       | 19                    | Yes ( $r_u > 0.95$ )    |
| UT-26    | 200.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5535714                     | 0.960784314   | 0.68       | 6                     | Yes ( $r_u > 0.95$ )    |
| UT-27    | 200.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5535714                     | 0.960784314   | 0.68       | 4                     | Yes ( $r_u > 0.95$ )    |
| UT-28    | 192.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5628743                     | 0.980392157   | 0.67       | 4                     | Yes ( $r_u > 0.95$ )    |
| UT-29    | 195.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5722892                     | 1             | 0.66       | 5                     | Yes ( $r_u > 0.95$ )    |
| UT-30    | 204.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5628743                     | 0.980392157   | 0.67       | 4                     | Yes ( $r_u > 0.95$ )    |
| UT-31    | 202.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5628743                     | 0.980392157   | 0.67       | 4                     | Yes ( $r_u > 0.95$ )    |
| UT-32    | 202.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5628743                     | 0.980392157   | 0.67       | 5                     | Yes ( $r_u > 0.95$ )    |
| UT-33    | 182.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.6518987                     | 1.156862745   | 0.58       | 3                     | Yes ( $r_u > 0.95$ )    |
| UT-34    | 164.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.63125                       | 1.117647059   | 0.6        | 1                     |                         |
| UT-35    | 191.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.6111111                     | 1.078431373   | 0.62       | 643                   |                         |
| UT-36    | 193.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.6415094                     | 1.137254902   | 0.59       | 1                     |                         |
| UT-37    | 194.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.621118                      | 1.098039216   | 0.61       | 153                   |                         |
| UT-38    | 193.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.6111111                     | 1.078431373   | 0.62       | 16                    | Yes ( $r_u > 0.95$ )    |
| UT-39    | 191.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.601227                      | 1.058823529   | 0.63       | 1                     | Yes ( $r_u > 0.95$ )    |
| UT-40    | 192.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5818182                     | 1.019607843   | 0.65       | 6000                  | No ( $N_L > 30$ )       |
| UT-41    | 192.00               | 0            | 0                                                    | Ring shear            | Undrain         | 0.8                       | 0.0           | 1.5818182                     | 1.019607843   | 0.65       | 7257                  | No ( $N_L > 30$ )       |
| UT-8     | 480.00               | 230          | 0.479166667                                          | Ring shear            | Undrain         | 0.8                       | 0.0           |                               |               | 1.11       | 0.60                  | Yes ( $r_u > 0.9$ )     |
| UT-1     | 200.00               | 105          | 0.525                                                | Ring shear            | Undrain         | 0.15                      | 0.0           |                               |               | 0.78       |                       | No                      |
| UT-2     | 200.00               | 105          | 0.525                                                | Ring shear            | Undrain         | 0.15                      | 0.0           |                               |               | 0.78       |                       | No                      |
| UT-3     | 200.00               | 125          | 0.625                                                | Ring shear            | Undrain         | 0.65                      | 0.0           |                               |               | 2.81       |                       | Yes (Large strain)      |
| UT-4     | 200.00               | 125          | 0.625                                                | Ring shear            | Undrain         | 0.65                      | 0.0           |                               |               | 2.76       |                       | Yes (Large strain)      |
| UT-5     | 200.00               | 75           | 0.375                                                | Ring shear            | Undrain         | 0.0185                    | 0.0           |                               |               | 0.79       |                       | No                      |
| UT-6     | 200.00               | 75           | 0.375                                                | Ring shear            | Undrain         | 0.0185                    | 0.0           |                               |               | 0.79       |                       | No                      |
| UT-6     | 202.00               | 115          | 0.569306931                                          | Ring shear            | Undrain         | 0.18                      | 0.0           | 1.86                          |               | 0.45       |                       | Yes (Large strain)      |
| UT-6     | 1970.00              | 0            | 0                                                    | Ring shear            | Undrain         | 0.6                       | 0.0           |                               |               |            |                       | Yes (Large strain)      |
| UT-1     | 450.00               | 250          | 0.555555556                                          | Ring shear            | Undrain         | 0.2                       | 0.0           |                               |               |            |                       | Yes (Large strain)      |
| UT-1     | 99.74                |              | 0.511                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.811         |            | 168.1                 | No ( $N_L > 30$ )       |
| UT-2     | 99.84                |              | 0.598                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.811         |            | 30.1                  | No ( $N_L > 30$ )       |
| UT-3     | 100.20               |              | 0.691                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.811         |            | 12.1                  | Yes ( $r_u = 1$ )       |
| UT-4     | 100.40               |              | 0.439                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.653         |            | 73.1                  | No ( $N_L > 30$ )       |
| UT-5     | 99.11                |              | 0.505                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.642         |            | 58.1                  | No ( $N_L > 30$ )       |
| UT-6     | 99.53                |              | 0.59                                                 | Triaxial              | Undrain         |                           | 0.46          |                               | 0.642         |            | 12.6                  | Yes ( $r_u = 1$ )       |
| UT-7     | 100.00               |              | 0.399                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.574         |            | 351                   | No ( $N_L > 30$ )       |
| UT-8     | 99.11                |              | 0.525                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.584         |            | 15.1                  | Yes ( $r_u = 1$ )       |
| UT-9     | 99.74                |              | 0.597                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.584         |            | 5.1                   | Yes ( $r_u = 1$ )       |
| UT-10    | 98.16                |              | 0.362                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.463         |            | 108.1                 | No ( $N_L > 30$ )       |
| UT-11    | 100.80               |              | 0.389                                                | Triaxial              | Undrain         |                           | 0.46          |                               | 0.468         |            | 50.6                  | No ( $N_L > 30$         |

|        |        |        |          |         |      |        |        |                        |                        |
|--------|--------|--------|----------|---------|------|--------|--------|------------------------|------------------------|
| UT-54  | 97.84  | 0.614  | Triaxial | Undrain | 0.37 | 20     | 0.975  | 56                     | No ( $N_L > 30$ )      |
| UT-55  | 99.42  | 0.701  | Triaxial | Undrain | 0.37 | 20     | 0.968  | 42.7                   | No ( $N_L > 30$ )      |
| UT-56  | 99.42  | 0.261  | Triaxial | Undrain | 0.37 | 20     | 0.608  | 310.2                  | No ( $N_L > 30$ )      |
| UT-57  | 99.32  | 0.317  | Triaxial | Undrain | 0.37 | 20     | 0.611  | 55                     | No ( $N_L > 30$ )      |
| UT-58  | 98.90  | 0.407  | Triaxial | Undrain | 0.37 | 20     | 0.608  | 14.1                   | Yes ( $r_u = 1$ )      |
| UT-59  | 99.32  | 0.452  | Triaxial | Undrain | 0.37 | 20     | 0.604  | 12.1                   | Yes ( $r_u = 1$ )      |
| UT-60  | 97.74  | 0.167  | Triaxial | Undrain | 0.37 | 20     | -0.021 | 55.3                   | No ( $N_L > 30$ )      |
| UT-61  | 98.37  | 0.247  | Triaxial | Undrain | 0.37 | 20     | -0.011 | 8                      | Yes ( $r_u = 1$ )      |
| UT-62  | 99.53  | 0.516  | Triaxial | Undrain | 0.35 | 25     | 0.979  | 52                     | No ( $N_L > 30$ )      |
| UT-63  | 99.21  | 0.709  | Triaxial | Undrain | 0.35 | 25     | 0.979  | 25.9                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-64  | 99.11  | 0.903  | Triaxial | Undrain | 0.35 | 25     | 0.983  | 11.8                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-65  | 99.95  | 0.305  | Triaxial | Undrain | 0.35 | 25     | 0.759  | 124.1                  | No ( $N_L > 30$ )      |
| UT-66  | 99.21  | 0.407  | Triaxial | Undrain | 0.35 | 25     | 0.762  | 21                     | Yes ( $r_u = 1$ )      |
| UT-67  | 99.63  | 0.47   | Triaxial | Undrain | 0.35 | 25     | 0.755  | 14.1                   | Yes ( $r_u = 1$ )      |
| UT-68  | 98.60  | 0.251  | Triaxial | Undrain | 0.35 | 25     | 0.607  | 60                     | No ( $N_L > 30$ )      |
| UT-69  | 99.21  | 0.311  | Triaxial | Undrain | 0.35 | 25     | 0.6    | 29.1                   | Yes ( $r_u = 1$ )      |
| UT-70  | 99.42  | 0.45   | Undrain  | 0.35    | 25   | 0.614  | 6.1    | Yes ( $r_u = 1$ )      |                        |
| UT-71  | 99.11  | 0.114  | Triaxial | Undrain | 0.35 | 25     | -0.021 | 155.3                  | No ( $N_L > 30$ )      |
| UT-72  | 95.95  | 0.149  | Triaxial | Undrain | 0.35 | 25     | -0.003 | 55                     | No ( $N_L > 30$ )      |
| UT-73  | 97.42  | 0.226  | Triaxial | Undrain | 0.35 | 25     | -0.017 | 8                      | Yes ( $e_{DA} = 5\%$ ) |
| UT-74  | 100.20 | 0.081  | Triaxial | Undrain | 0.31 | 35     | 0.558  | 42.4                   | No ( $N_L > 30$ )      |
| UT-75  | 99.42  | 0.11   | Triaxial | Undrain | 0.31 | 35     | 0.692  | 11.5                   | Yes ( $r_u = 1$ )      |
| UT-76  | 98.79  | 0.119  | Triaxial | Undrain | 0.31 | 35     | 0.625  | 11.3                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-77  | 99.42  | 0.11   | Triaxial | Undrain | 0.31 | 35     | 0.676  | 20                     | Yes ( $r_u = 1$ )      |
| UT-78  | 98.79  | 0.119  | Triaxial | Undrain | 0.31 | 35     | 0.728  | 11.3                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-79  | 97.00  | 0.112  | Triaxial | Undrain | 0.25 | 50     | 0.739  | 466                    | No ( $N_L > 30$ )      |
| UT-80  | 98.90  | 0.125  | Triaxial | Undrain | 0.25 | 50     | 0.769  | 9.4                    | Yes ( $r_u = 1$ )      |
| UT-81  | 98.37  | 0.16   | Triaxial | Undrain | 0.25 | 50     | 0.773  | 20                     | Yes ( $r_u = 1$ )      |
| UT-82  | 98.68  | 0.148  | Triaxial | Undrain | 0.25 | 50     | 0.796  | 20                     | Yes ( $r_u = 1$ )      |
| UT-83  | 98.58  | 0.136  | Triaxial | Undrain | 0.14 | 75     | 0.92   | 13.7                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-84  | 100.50 | 0.159  | Triaxial | Undrain | 0.14 | 75     | 0.905  | 6.4                    | Yes ( $e_{DA} = 5\%$ ) |
| UT-85  | 99.10  | 0.286  | Triaxial | Undrain | 0.17 | 0      | 0.68   | 23.1                   | Yes ( $r_u = 1$ )      |
| UT-86  | 99.63  | 0.323  | Triaxial | Undrain | 0.17 | 0      | 0.7    | 11.1                   | Yes ( $r_u = 1$ )      |
| UT-87  | 98.58  | 0.342  | Triaxial | Undrain | 0.17 | 0      | 0.683  | 11.1                   | Yes ( $r_u = 1$ )      |
| UT-88  | 99.42  | 0.137  | Triaxial | Undrain | 0.17 | 0      | 0.273  | 36.1                   | No ( $N_L > 30$ )      |
| UT-89  | 101.30 | 0.168  | Triaxial | Undrain | 0.17 | 0      | 0.248  | 14                     | Yes ( $r_u = 1$ )      |
| UT-90  | 98.05  | 0.224  | Triaxial | Undrain | 0.17 | 0      | 0.256  | 5                      | Yes ( $r_u = 1$ )      |
| UT-91  | 99.42  | 0.09   | Undrain  | 0.17    | 0    | -0.104 | 14.5   | Yes ( $r_u = 1$ )      |                        |
| UT-92  | 100.60 | 0.066  | Triaxial | Undrain | 0.17 | 0      | -0.327 | 43.3                   | No ( $N_L > 30$ )      |
| UT-93  | 99.74  | 0.063  | Triaxial | Undrain | 0.17 | 0      | -0.445 | 78.5                   | No ( $N_L > 30$ )      |
| UT-94  | 98.47  | 0.0668 | Triaxial | Undrain | 0.17 | 0      | -0.372 | 60.4                   | No ( $N_L > 30$ )      |
| UT-95  | 99.84  | 0.087  | Undrain  | 0.17    | 0    | -0.323 | 11.3   | Yes ( $r_u = 1$ )      |                        |
| UT-96  | 98.26  | 0.11   | Triaxial | Undrain | 0.17 | 0      | -0.32  | 2.3                    | Yes ( $r_u = 1$ )      |
| UT-97  | 99.53  | 0.136  | Triaxial | Undrain | 0.16 | 4      | 0.275  | 8.6                    | Yes ( $r_u = 1$ )      |
| UT-98  | 98.16  | 0.148  | Triaxial | Undrain | 0.16 | 4      | 0.229  | 6.3                    | Yes ( $r_u = 1$ )      |
| UT-99  | 98.16  | 0.163  | Triaxial | Undrain | 0.16 | 4      | 0.282  | 3.2                    | Yes ( $r_u = 1$ )      |
| UT-100 | 100.30 | 0.211  | Triaxial | Undrain | 0.16 | 4      | 0.196  | 15                     | Yes ( $r_u = 1$ )      |
| UT-101 | 99.84  | 0.249  | Undrain  | 0.16    | 4    | 0.521  | 33.1   | No ( $N_L > 30$ )      |                        |
| UT-102 | 100.80 | 0.283  | Triaxial | Undrain | 0.16 | 4      | 0.524  | 11.1                   | Yes ( $r_u = 1$ )      |
| UT-103 | 99.21  | 0.335  | Triaxial | Undrain | 0.16 | 4      | 0.521  | 7.1                    | Yes ( $r_u = 1$ )      |
| UT-104 | 100.80 | 0.188  | Triaxial | Undrain | 0.16 | 4      | 0.295  | 54                     | No ( $N_L > 30$ )      |
| UT-105 | 99.31  | 0.229  | Undrain  | 0.16    | 4    | 0.308  | 19.1   | Yes ( $r_u = 1$ )      |                        |
| UT-106 | 100.60 | 0.243  | Triaxial | Undrain | 0.16 | 4      | 0.295  | 11.1                   | Yes ( $r_u = 1$ )      |
| UT-107 | 96.89  | 0.094  | Undrain  | 0.16    | 4    | -0.109 | 28.3   | Yes ( $r_u = 1$ )      |                        |
| UT-108 | 99.53  | 0.113  | Triaxial | Undrain | 0.16 | 4      | -0.09  | 12                     | Yes ( $r_u = 1$ )      |
| UT-109 | 96.79  | 0.127  | Triaxial | Undrain | 0.16 | 4      | -0.096 | 7.2                    | Yes ( $r_u = 1$ )      |
| UT-110 | 97.74  | 0.077  | Triaxial | Undrain | 0.16 | 4      | -0.365 | 30.3                   | No ( $N_L > 30$ )      |
| UT-111 | 99.84  | 0.081  | Undrain  | 0.16    | 4    | -0.355 | 20.3   | Yes ( $r_u = 1$ )      |                        |
| UT-112 | 98.89  | 0.111  | Triaxial | Undrain | 0.16 | 4      | -0.302 | 6.3                    | Yes ( $r_u = 1$ )      |
| UT-113 | 97.21  | 0.241  | Undrain  | 0.16    | 7    | 0.34   | 20.1   | Yes ( $r_u = 1$ )      |                        |
| UT-114 | 98.47  | 0.251  | Triaxial | Undrain | 0.16 | 7      | 0.346  | 25.1                   | Yes ( $r_u = 1$ )      |
| UT-115 | 100.60 | 0.283  | Triaxial | Undrain | 0.16 | 7      | 0.337  | 9.1                    | Yes ( $r_u = 1$ )      |
| UT-116 | 98.05  | 0.307  | Triaxial | Undrain | 0.16 | 7      | 0.337  | 6                      | Yes ( $r_u = 1$ )      |
| UT-117 | 100.50 | 0.225  | Triaxial | Undrain | 0.16 | 7      | 0.273  | 58.1                   | No ( $N_L > 30$ )      |
| UT-118 | 98.05  | 0.297  | Triaxial | Undrain | 0.16 | 7      | 0.294  | 15.1                   | Yes ( $r_u = 1$ )      |
| UT-119 | 100.90 | 0.323  | Triaxial | Undrain | 0.16 | 7      | 0.307  | 7.1                    | Yes ( $r_u = 1$ )      |
| UT-120 | 99.84  | 0.0859 | Triaxial | Undrain | 0.16 | 7      | -0.09  | 65                     | No ( $N_L > 30$ )      |
| UT-121 | 99.74  | 0.124  | Triaxial | Undrain | 0.16 | 7      | -0.087 | 16.8                   | Yes ( $r_u = 1$ )      |
| UT-122 | 96.47  | 0.161  | Triaxial | Undrain | 0.16 | 7      | -0.055 | 4.2                    | Yes ( $r_u = 1$ )      |
| UT-123 | 100.90 | 0.084  | Triaxial | Undrain | 0.16 | 7      | -0.204 | 29.4                   | Yes ( $r_u = 1$ )      |
| UT-124 | 102.50 | 0.0884 | Triaxial | Undrain | 0.16 | 7      | -0.317 | 29.6                   | Yes ( $r_u = 1$ )      |
| UT-125 | 97.63  | 0.113  | Triaxial | Undrain | 0.16 | 7      | -0.253 | 8.3                    | Yes ( $r_u = 1$ )      |
| UT-126 | 98.05  | 0.132  | Triaxial | Undrain | 0.16 | 7      | -0.253 | 4.3                    | Yes ( $r_u = 1$ )      |
| UT-127 | 99.10  | 0.339  | Triaxial | Undrain | 0.15 | 12     | 0.452  | 13.1                   | Yes ( $r_u = 1$ )      |
| UT-128 | 100.40 | 0.37   | Triaxial | Undrain | 0.15 | 12     | 0.424  | 15.1                   | Yes ( $r_u = 1$ )      |
| UT-129 | 102.40 | 0.386  | Triaxial | Undrain | 0.15 | 12     | 0.439  | 12.1                   | Yes ( $r_u = 1$ )      |
| UT-130 | 99.63  | 0.255  | Undrain  | 0.15    | 12   | 0.544  | 11.7   | Yes ( $r_u = 1$ )      |                        |
| UT-131 | 98.89  | 0.284  | Triaxial | Undrain | 0.15 | 12     | 0.551  | 11.1                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-132 | 99.00  | 0.312  | Triaxial | Undrain | 0.15 | 12     | 0.569  | 7.1                    | Yes ( $r_u = 1$ )      |
| UT-133 | 100.30 | 0.201  | Triaxial | Undrain | 0.15 | 12     | 0.257  | 47.1                   | No ( $N_L > 30$ )      |
| UT-134 | 99.53  | 0.231  | Triaxial | Undrain | 0.15 | 12     | 0.247  | 12.6                   | Yes ( $r_u = 1$ )      |
| UT-135 | 98.89  | 0.267  | Triaxial | Undrain | 0.15 | 12     | 0.275  | 7                      | Yes ( $r_u = 1$ )      |
| UT-136 | 101.10 | 0.153  | Triaxial | Undrain | 0.15 | 12     | 0.034  | 29                     | Yes ( $r_u = 1$ )      |
| UT-137 | 100.60 | 0.188  | Triaxial | Undrain | 0.15 | 12     | 0.028  | 10.9                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-138 | 101.00 | 0.224  | Triaxial | Undrain | 0.15 | 12     | 0.046  | 4                      | Yes ( $r_u = 1$ )      |
| UT-139 | 98.68  | 0.09   | Triaxial | Undrain | 0.15 | 12     | -0.111 | 28.3                   | Yes ( $r_u = 1$ )      |
| UT-140 | 100.90 | 0.097  | Undrain  | 0.15    | 12   | -0.118 | 31.4   | No ( $N_L > 30$ )      |                        |
| UT-141 | 99.31  | 0.116  | Triaxial | Undrain | 0.15 | 12     | -0.096 | 9.3                    | Yes ( $r_u = 1$ )      |
| UT-142 | 98.89  | 0.144  | Undrain  | 0.15    | 12   | -0.099 | 3.4    | Yes ( $r_u = 1$ )      |                        |
| UT-143 | 98.89  | 0.349  | Triaxial | Undrain | 0.15 | 17     | 0.761  | 15.7                   | Yes ( $e_{DA} = 5\%$ ) |
| UT-144 | 100.60 | 0.376  | Undrain  | 0.15    | 17   | 0.778  | 16.7   | Yes ( $e_{DA} = 5\%$ ) |                        |
| UT-145 | 100.30 | 0.406  | Triaxial | Undrain | 0.15 | 17     | 0.763  | 15.1                   | Yes ( $r_u = 1$ )      |
| UT-146 | 99.00  | 0.102  | Triaxial | Undrain | 0.15 | 17     | 0.377  | 118.8                  | No ( $N_L > 30$ )      |
| UT-147 | 98.37  | 0.156  | Triaxial | Undrain | 0.15 | 17     | 0.41   | 16.7                   | Yes ( $r_u = 1$ )      |
| UT-148 | 102.80 | 0.245  | Undrain  | 0.15    | 17   | 0.383  | 2.5    | Yes ( $r_u = 1$ )      |                        |
| UT-149 | 98.68  | 0.201  | Triaxial | Undrain | 0.15 | 17     | 0.253  | 46.6                   | No ( $N_L > 30$ )      |
| UT-150 | 100.30 | 0.212  | Triaxial | Undrain | 0.15 | 17     | 0.26   | 25                     | Yes ( $r_u = 1$ )      |
| UT-151 | 100.20 | 0.248  | Triaxial | Undrain | 0.15 | 17     | 0.277  | 7                      | Yes ( $r_u = 1$ )      |
| UT-152 | 98.26  | 0.198  | Undrain  | 0.15    | 17   | 0.18   | 38     | No ( $N_L > 30$ )      |                        |
| UT-153 | 100.10 | 0.222  | Triaxial | Undrain | 0.15 | 17     | 0.18   | 14                     | Yes ( $r_u = 1$ )      |
| UT-154 | 99.31  | 0.263  | Triaxial | Undrain | 0.15 | 17     | 0.17   | 6                      | Yes ( $r_u = 1$ )      |
| UT-155 | 97.21  | 0.091  | Triaxial | Undrain | 0.15 | 17     | -0.107 | 62.4                   | No ( $N_L > 30$ )      |
| UT-156 | 97.32  | 0.128  | Undrain  | 0.15    | 17   | -0.077 | 20.9   | Yes ( $r_u = 1$ )      |                        |
| UT-157 | 97.74  | 0.159  | Triaxial | Undrain | 0.15 | 17     | -0.067 | 5.2                    | Yes ( $e_{DA} = 5\%$ ) |
| UT-158 | 99.95  | 0.283  | Triaxial | Undrain | 0.13 | 26     | 0.403  | 11.1                   | Yes ( $r_u = 1$ )      |
| UT-159 | 99.74  | 0.301  | Triaxial | Undrain | 0.13 | 26     | 0.428  | 14.1                   | Yes ( $r_u = 1$ )      |
| UT-160 | 99.42  | 0.33   | Triaxial | Undrain | 0.13 | 26     | 0.432  | 14.1                   | Yes ( $r_u = 1$ )      |
| UT-161 | 100.20 | 0.19   | Triaxial | Undrain | 0.13 | 26     | 0.269  | 69                     | No ( $N_L > 30$ )      |
| UT-162 | 98.89  | 0.249  | Triaxial | Undrain | 0.13 | 26     | 0.281  | 13                     | Yes ( $r_u = 1$ )      |
| UT-163 | 100.90 | 0.273  | Triaxial | Undrain | 0.13 | 26     | 0.285  | 5.1                    | Yes ( $r_u = 1$ )      |
| UT-164 | 100.50 | 0.161  | Triaxial | Undrain | 0.13 | 26     | 0.249  | 21                     | Yes ( $r_u = 1$ )      |
| UT-165 | 99.00  | 0.192  | Triaxial | Undrain | 0.13 | 26     | 0.31   | 14.1                   | Yes ( $r_u = 1$ )      |
| UT-166 | 97.95  | 0.219  | Triaxial | Undrain | 0.13 | 26     | 0.277  | 9                      |                        |
| UT-167 | 99.21  | 0.126  | Triaxial | Undrain | 0.13 | 26     | -0.102 | 30.1                   | Yes ( $r_u = 1$ )      |
| UT-168 | 100.90 | 0.151  | Triaxial | Undrain | 0.13 | 26     | -0.09  | 9.4                    | No ( $N_L > 30$ )      |
| UT-169 | 99.74  | 0.169  | Triaxial | Undrain | 0.13 | 26     | -0.09  | 7.1                    | Yes ( $r_u = 1$ )      |
| UT-170 | 102.60 | 0.224  | Triaxial | Undrain | 0.12 | 37     | 0.251  | 12.1                   | Yes ( $r_u = 1$ )      |
| UT-171 | 99.63  | 0.234  | Triaxial | Undrain | 0.12 | 37     | 0.258  | 10                     | Yes ( $r_u = 1$ )      |
| UT-172 | 100.60 | 0.285  | Triaxial | Undrain | 0.12 | 37     | 0.244  | 4.1                    | Yes ( $r_u = 1$ )      |
| UT-173 | 99.84  | 0.112  | Triaxial | Undrain | 0.12 | 37     | 0.045  | 35.7                   | No ( $N_L > 30$ )      |
| UT-174 | 99.42  | 0.119  | Triaxial | Undrain | 0.12 | 37     | 0.084  | 17.9                   | Yes ( $r_u = 1$ )      |
| UT-175 | 99.95  | 0.141  | Triaxial | Undrain | 0.12 | 37     | 0.077  | 9.1                    | Yes ( $r_u = 1$ )      |
| UT-176 | 98.79  | 0.116  | Triaxial | Undrain | 0.12 | 37     | 0.01   | 29                     | Yes ( $r_u = 1$ )      |
| UT-177 | 98.47  | 0.178  | Triaxial | Undrain | 0.12 | 37     | 0      | 7                      | Yes ( $r_u = 1$ )      |

Yes ( $r_u = 1$ )  
No (<

|        |        |        |          |         |       |       |             |       |                                            |
|--------|--------|--------|----------|---------|-------|-------|-------------|-------|--------------------------------------------|
| UT-178 | 99.63  | 0.194  | Triaxial | Undrain | 0.12  | 37    | 0.038       | 3.4   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-179 | 95.32  | 0.0779 | Triaxial | Undrain | 0.12  | 37    | -0.247      | 46.3  | No ( $N_L > 30$ )                          |
| UT-180 | 98.47  | 0.0918 | Undrain  | Undrain | 0.12  | 37    | -0.111      | 19.3  | Yes ( $r_u = 1$ )                          |
| UT-181 | 96.68  | 0.118  | Triaxial | Undrain | 0.12  | 37    | -0.164      | 7.7   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-182 | 100.40 | 0.151  | Undrain  | Undrain | 0.10  | 50    | 0.811       | 18.1  | Yes ( $r_u = 1$ )                          |
| UT-183 | 100.10 | 0.168  | Triaxial | Undrain | 0.10  | 50    | 0.8         | 9.7   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-184 | 100.20 | 0.205  | Triaxial | Undrain | 0.10  | 50    | 0.912       | 3.8   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-185 | 99.31  | 0.111  | Triaxial | Undrain | 0.10  | 50    | 0.722       | 12.5  | Yes ( $r_u = 1$ )                          |
| UT-186 | 99.10  | 0.132  | Triaxial | Undrain | 0.10  | 50    | 0.698       | 7.5   | Yes ( $r_u = 1$ )                          |
| UT-187 | 98.79  | 0.154  | Triaxial | Undrain | 0.10  | 50    | 0.716       | 4.2   | Yes ( $r_u = 1$ )                          |
| UT-188 | 99.84  | 0.068  | Triaxial | Undrain | 0.10  | 50    | 0.634       | 48.2  | No ( $N_L > 30$ )                          |
| UT-189 | 98.68  | 0.107  | Triaxial | Undrain | 0.10  | 50    | 0.622       | 11.2  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-190 | 96.37  | 0.125  | Triaxial | Undrain | 0.10  | 50    | 0.586       | 5.7   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-191 | 99.95  | 0.076  | Triaxial | Undrain | 0.10  | 50    | 0.62        | 46    | No ( $N_L > 30$ )                          |
| UT-192 | 99.53  | 0.095  | Triaxial | Undrain | 0.10  | 50    | 0.544       | 15.2  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-193 | 100.50 | 0.114  | Triaxial | Undrain | 0.10  | 50    | 0.693       | 6.3   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-194 | 102.50 | 0.105  | Triaxial | Undrain | 0.07  | 75    | 0.855       | 26.2  | Yes ( $r_u = 1$ )                          |
| UT-195 | 97.95  | 0.121  | Triaxial | Undrain | 0.07  | 75    | 0.866       | 11.3  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-196 | 103.10 | 0.121  | Triaxial | Undrain | 0.07  | 75    | 0.858       | 13.4  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-197 | 96.47  | 0.12   | Triaxial | Undrain | 0.07  | 75    | 0.797       | 14.3  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-198 | 97.53  | 0.132  | Triaxial | Undrain | 0.07  | 75    | 0.78        | 9.5   | Yes ( $r_u = 1$ )                          |
| UT-199 | 96.89  | 0.152  | Triaxial | Undrain | 0.07  | 75    | 0.782       | 5.4   | Yes ( $r_u = 1$ )                          |
| UT-200 | 99.53  | 0.078  | Triaxial | Undrain | 0.07  | 75    | 0.751       | 36.2  | No ( $N_L > 30$ )                          |
| UT-201 | 99.84  | 0.106  | Triaxial | Undrain | 0.07  | 75    | 0.769       | 9.3   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-202 | 99.42  | 0.121  | Triaxial | Undrain | 0.07  | 75    | 0.742       | 5.3   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-203 | 99.95  | 0.103  | Triaxial | Undrain | 0.03  | 100   | 1.051       | 602.5 | No ( $N_L > 30$ )                          |
| UT-204 | 101.10 | 0.364  | Triaxial | Undrain | 0.03  | 100   | 1.043       | 15.2  | Yes ( $r_u = 1$ )                          |
| UT-205 | 100.60 | 0.423  | Triaxial | Undrain | 0.03  | 100   | 1.033       | 21.3  | Yes ( $r_u = 1$ )                          |
| UT-206 | 98.79  | 0.231  | Triaxial | Undrain | 0.03  | 100   | 0.975       | 180.2 | No ( $N_L > 30$ )                          |
| UT-207 | 99.53  | 0.34   | Triaxial | Undrain | 0.03  | 100   | 0.959       | 17.2  | Yes ( $r_u = 1$ )                          |
| UT-208 | 99.31  | 0.365  | Triaxial | Undrain | 0.03  | 100   | 0.985       | 3.2   | Yes ( $r_u = 1$ )                          |
| UT-209 | 98.47  | 0.151  | Triaxial | Undrain | 0.03  | 100   | 0.856       | 18.2  | Yes ( $r_u = 1$ )                          |
| UT-210 | 100.90 | 0.171  | Triaxial | Undrain | 0.03  | 100   | 0.862       | 9.8   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-211 | 98.47  | 0.194  | Triaxial | Undrain | 0.03  | 100   | 0.872       | 3.7   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-212 | 100.30 | 0.079  | Triaxial | Undrain | 0.03  | 100   | 0.876       | 52.2  | No ( $N_L > 30$ )                          |
| UT-213 | 99.95  | 0.098  | Triaxial | Undrain | 0.03  | 100   | 0.884       | 20.8  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-214 | 100.10 | 0.119  | Triaxial | Undrain | 0.03  | 100   | 0.872       | 8.8   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-215 | 99.63  | 0.078  | Triaxial | Undrain | 0.03  | 100   | 0.843       | 46.1  | No ( $N_L > 30$ )                          |
| UT-216 | 99.31  | 0.104  | Triaxial | Undrain | 0.03  | 100   | 0.846       | 11.2  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-217 | 100.70 | 0.114  | Triaxial | Undrain | 0.03  | 100   | 0.847       | 7.8   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-1   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.64        | 53.4  | No ( $N_L > 30$ )                          |
| UT-2   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.64        | 20.8  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-3   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.69        | 25.5  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-4   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.68        | 18.9  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-5   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.70        | 6.1   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-6   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.73        | 3.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-7   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.72        | 8.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-8   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.75        | 7.2   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-9   | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.75        | 1.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-10  | 100.00 | 0.200  | Triaxial | Undrain | 0.25  | 0     | 0.78        | 1.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-11  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.57        |       | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-12  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.56        | 6.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-13  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.58        | 7.1   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-14  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.56        | 16.1  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-15  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.57        | 13.2  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-16  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.62        | 3.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-17  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.64        | 2.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-18  | 100.00 | 0.200  | Triaxial | Undrain | 0.235 | 15.0  | 0.66        | 2.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-19  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.40        | 13.2  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-20  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.45        |       | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-21  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.45        |       | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-22  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.45        | 12.4  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-23  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.45        | 5.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-24  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.45        | 2.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-25  | 100.00 | 0.200  | Triaxial | Undrain | 0.23  | 25.0  | 0.49        | 2.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-26  | 100.00 | 0.200  | Triaxial | Undrain | 0.029 | 60.0  | 0.49        |       | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-27  | 100.00 | 0.200  | Triaxial | Undrain | 0.029 | 60.0  | 0.55        |       | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-28  | 100.00 | 0.200  | Triaxial | Undrain | 0.029 | 60.0  | 0.50        | 31.7  | No ( $N_L > 30$ )                          |
| UT-29  | 100.00 | 0.200  | Triaxial | Undrain | 0.029 | 60.0  | 0.53        | 5.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-30  | 100.00 | 0.200  | Triaxial | Undrain | 0.029 | 60.0  | 0.54        | 4.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-31  | 100.00 | 0.200  | Triaxial | Undrain | 0.029 | 60.0  | 0.53        |       | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-32  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.81        | 22.4  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-33  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.84        | 9.1   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-34  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.81        | 5.9   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-35  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.85        | 5.1   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-36  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.87        | 3.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-37  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.86        | 4.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-38  | 100.00 | 0.200  | Triaxial | Undrain | 0.01  | 100.0 | 0.87        | 5.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-39  | 100.00 | 0.200  | Triaxial | Undrain | 0.179 | 0.0   | 0.71        | 69.9  | No ( $N_L > 30$ )                          |
| UT-40  | 100.00 | 0.200  | Triaxial | Undrain | 0.179 | 0.0   | 0.75        | 13.1  | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-41  | 100.00 | 0.200  | Triaxial | Undrain | 0.179 | 0.0   | 0.79        | 4.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-42  | 100.00 | 0.200  | Triaxial | Undrain | 0.135 | 25.0  | 0.55        | 32.1  | No ( $N_L > 30$ )                          |
| UT-43  | 100.00 | 0.200  | Triaxial | Undrain | 0.135 | 25.0  | 0.62        | 9.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-44  | 100.00 | 0.200  | Triaxial | Undrain | 0.135 | 25.0  | 0.65        | 3.0   | Yes ( $\epsilon_{DA} = 5\%$ )              |
| UT-1   | 100.00 | 0.075  | Triaxial | Undrain | 0.17  | 0.0   |             | 170.8 | No ( $N_L > 30$ )                          |
| UT-2   | 100.00 | 0.100  | Triaxial | Undrain | 0.17  | 0.0   |             | 40.7  | No ( $N_L > 30$ )                          |
| UT-3   | 100.00 | 0.125  | Triaxial | Undrain | 0.17  | 0.0   |             | 16.3  | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-4   | 100.00 | 0.150  | Triaxial | Undrain | 0.17  | 0.0   |             | 7.1   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-5   | 93.00  | 0.125  | Undrain  | Undrain | 0.17  | 0.0   |             | 21.9  | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-6   | 93.00  | 0.150  | Triaxial | Undrain | 0.17  | 0.0   |             | 9.2   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-7   | 93.00  | 0.200  | Undrain  | Undrain | 0.17  | 0.0   |             | 7.1   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-8   | 83.00  | 0.075  | Triaxial | Undrain | 0.17  | 0.0   |             | 9.1   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-9   | 83.00  | 0.100  | Undrain  | Undrain | 0.17  | 0.0   |             | 5.0   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-10  | 83.00  | 0.125  | Triaxial | Undrain | 0.17  | 0.0   |             | 3.1   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-11  | 74.00  | 0.085  | Triaxial | Undrain | 0.17  | 0.0   |             | 3.0   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-12  | 74.00  | 0.175  | Triaxial | Undrain | 0.17  | 0.0   |             | 1.0   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-13  | 100.00 | 0.150  | Undrain  | Undrain | 0.17  | 0.0   |             |       | Yes ( $r_u = 1$ or $\epsilon_{DA} = 5\%$ ) |
| UT-14  | 100.00 | 0.175  | Triaxial | Undrain | 0.17  | 0.0   |             | 697.7 | No ( $N_L > 30$ )                          |
| UT-15  | 100.00 | 0.200  | Undrain  | Undrain | 0.17  | 0.0   |             | 463.6 | No ( $N_L > 30$ )                          |
| UT-16  | 100.00 | 0.225  | Triaxial | Undrain | 0.17  | 0.0   |             | 363.4 | No ( $N_L > 30$ )                          |
| UT-17  | 93.00  | 0.200  | Undrain  | Undrain | 0.17  | 0.0   |             | 641.2 | No ( $N_L > 30$ )                          |
| UT-18  | 93.00  | 0.250  | Triaxial | Undrain | 0.17  | 0.0   |             | 498.4 | No ( $N_L > 30$ )                          |
| UT-19  | 93.00  | 0.300  | Undrain  | Undrain | 0.17  | 0.0   |             | 236.0 | No ( $N_L > 30$ )                          |
| UT-20  | 83.00  | 0.250  | Triaxial | Undrain | 0.17  | 0.0   |             | 705.4 | No ( $N_L > 30$ )                          |
| UT-21  | 83.00  | 0.300  | Undrain  | Undrain | 0.17  | 0.0   |             | 603.9 | No ( $N_L > 30$ )                          |
| UT-22  | 83.00  | 0.350  | Triaxial | Undrain | 0.17  | 0.0   |             | 376.1 | No ( $N_L > 30$ )                          |
| UT-23  | 74.00  | 0.400  | Undrain  | Undrain | 0.17  | 0.0   |             | 556.4 | No ( $N_L > 30$ )                          |
| UT-24  | 74.00  | 0.425  | Triaxial | Undrain | 0.17  | 0.0   |             |       | No ( $N_L > 30$ )                          |
| UT-25  | 74.00  | 0.450  | Triaxial | Undrain | 0.17  | 0.0   |             | 363.4 | No ( $N_L > 30$ )                          |
| UT-1   | 100.00 | 0.115  | Triaxial | Undrain | 0.28  | 0.0   | 0.439393939 | 0.665 | 81                                         |
| UT-2   | 100.00 | 0.115  | Triaxial | Undrain | 0.28  | 0.0   | 0.442424242 | 0.664 | 88                                         |
| UT-3   | 100.00 | 0.150  | Undrain  | Undrain | 0.28  | 0.0   | 0.424242424 | 0.67  | 66                                         |
| UT-4   | 100.00 | 0.150  | Triaxial | Undrain | 0.28  | 0.0   | 0.421212121 | 0.671 | 11                                         |
| UT-5   | 100.00 | 0.150  | Triaxial | Undrain | 0.28  | 0.0   | 0.424242424 | 0.67  | 3                                          |
| UT-6   | 100.00 | 0.200  | Triaxial | Undrain | 0.28  | 0.0   | 0.424242424 | 0.67  | 13                                         |
| UT-1   | 100.00 | 0.205  | Triaxial | Undrain | 0.71  | 0.0   |             | 33.2  | No ( $N_L > 30$ )                          |
| UT-2   | 100.00 | 0.205  | Triaxial | Undrain | 0.71  | 0.0   |             | 11.1  | Yes ( $r_u = 1$ )                          |
| UT-3   | 100.00 | 0.225  | Triaxial | Undrain | 0.71  | 0.0   |             | 9.7   | Yes ( $r_u = 1$ )                          |
| UT-4   | 100.00 | 0.196  | Triaxial | Undrain | 0.71  | 0.0   |             | 14.2  | Yes ( $r_u = 1$ )                          |
| UT-5   | 100.00 | 0.250  | Triaxial | Undrain | 0.71  | 0.0   |             | 36    | No ( $N_L > 30$ )                          |
| UT-6   | 100.0  |        |          |         |       |       |             |       |                                            |

|         |        |       |              |         |      |      |           |          |                   |                                                                                  |
|---------|--------|-------|--------------|---------|------|------|-----------|----------|-------------------|----------------------------------------------------------------------------------|
| UT-10   | 100.00 | 0.255 | Triaxial     | Undrain | 0.71 | 0.0  |           | 14.8     | Yes ( $r_u = 1$ ) | Yes ( $r_u = 1$ )<br>No ( $N_L > 30$ )<br>Yes ( $r_u = 1$ )<br>No ( $N_L > 30$ ) |
| UT-11   | 100.00 | 0.260 | Triaxial     | Undrain | 0.71 | 0.0  |           | 9        | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-12   | 100.00 | 0.273 | Triaxial     | Undrain | 0.71 | 0.0  |           | 3        | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-13   | 100.00 | 0.203 | Triaxial     | Undrain | 0.71 | 0.0  |           | 14       | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-14   | 100.00 | 0.188 | Triaxial     | Undrain | 0.71 | 0.0  |           | 25.7     |                   |                                                                                  |
| UT-15   | 100.00 | 0.200 | Triaxial     | Undrain | 0.71 | 0.0  |           | 32.9     |                   |                                                                                  |
| UT-16   | 100.00 | 0.190 | Triaxial     | Undrain | 0.71 | 0.0  |           | 19       |                   |                                                                                  |
| UT-17   | 100.00 | 0.169 | Triaxial     | Undrain | 0.71 | 0.0  |           | 42.1     |                   |                                                                                  |
| UT-18   | 100.00 | 0.174 | Triaxial     | Undrain | 0.71 | 0.0  |           | 28.9     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-19   | 100.00 | 0.177 | Triaxial     | Undrain | 0.71 | 0.0  |           | 19.6     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-20   | 100.00 | 0.182 | Triaxial     | Undrain | 0.71 | 0.0  |           | 21.7     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-21   | 100.00 | 0.201 | Triaxial     | Undrain | 0.71 | 0.0  |           | 16       | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-22   | 100.00 | 0.222 | Triaxial     | Undrain | 0.71 | 0.0  |           | 18.8     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-23   | 100.00 | 0.225 | Triaxial     | Undrain | 0.71 | 0.0  |           | 23.9     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-24   | 100.00 | 0.184 | Triaxial     | Undrain | 0.71 | 0.0  |           | 8.8      | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-25   | 100.00 | 0.187 | Triaxial     | Undrain | 0.71 | 0.0  |           | 25.9     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-26   | 100.00 | 0.174 | Triaxial     | Undrain | 0.71 | 0.0  |           | 28.9     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-27   | 100.00 | 0.166 | Triaxial     | Undrain | 0.71 | 0.0  |           | 14.1     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-28   | 100.00 | 0.169 | Triaxial     | Undrain | 0.71 | 0.0  |           | 20.8     | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-1    | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-2    | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-3    | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-4    | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-5    | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-6    | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-7    | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | 2 Yes ( $r_u = 1$ )                                                              |
| UT-8    | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-9    | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-10   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-11   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-12   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5233387 | 0.4      | 0.7396            | Yes ( $r_u = 1$ )                                                                |
| UT-13   | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | 4 Yes ( $r_u = 1$ )                                                              |
| UT-14   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | 5 Yes ( $r_u = 1$ )                                                              |
| UT-15   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | 5 Yes ( $r_u = 1$ )                                                              |
| UT-16   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | 6 Yes ( $r_u = 1$ )                                                              |
| UT-17   | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-18   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-19   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | 3 Yes ( $r_u = 1$ )                                                              |
| UT-20   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-21   | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-22   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-23   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-24   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.5611653 | 0.55     | 0.69745           | Yes ( $r_u = 1$ )                                                                |
| UT-25   | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-26   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-27   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-28   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-29   | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-30   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-31   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | 4 Yes ( $r_u = 1$ )                                                              |
| UT-32   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-33   | 25.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-34   | 50.00  |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-35   | 100.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-36   | 150.00 |       | Simple shear | Undrain | 0.26 | 0.0  | 1.6009183 | 0.7      | 0.6553            | Yes ( $r_u = 1$ )                                                                |
| UT-1    | 50.00  | 1.008 | triaxial     | Undrain | 0.19 | 0.0  | 1.5675057 | 0.4      | 0.748             | 2.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-2    | 100.00 | 0.497 | triaxial     | Undrain | 0.19 | 0.0  | 1.5675057 | 0.4      | 0.748             | 4 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-3    | 200.00 | 0.247 | triaxial     | Undrain | 0.19 | 0.0  | 1.5675057 | 0.4      | 0.748             | 25 Yes ( $\epsilon_{DA} = 5\%$ )                                                 |
| UT-4    | 50.00  | 0.973 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 3.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-5    | 100.00 | 0.490 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 6.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-6    | 200.00 | 0.245 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 30 Yes ( $\epsilon_{DA} = 5\%$ )                                                 |
| UT-7    | 50.00  | 0.994 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 6 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-8    | 100.00 | 0.501 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 10 Yes ( $\epsilon_{DA} = 5\%$ )                                                 |
| UT-9    | 200.00 | 0.247 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 58 No ( $N_L > 30$ )                                                             |
| UT-10   | 50.00  | 0.976 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 4 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-11   | 100.00 | 0.491 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 7.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-12   | 200.00 | 0.242 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 34.5 No ( $N_L > 30$ )                                                           |
| UT-13   | 50.00  | 0.995 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 7 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-14   | 100.00 | 0.500 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 12.5 Yes ( $\epsilon_{DA} = 5\%$ )                                               |
| UT-15   | 200.00 | 0.245 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 67 No ( $N_L > 30$ )                                                             |
| UT-16   | 50.00  | 0.965 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 4.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-17   | 100.00 | 0.482 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 8.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-18   | 200.00 | 0.243 | triaxial     | Undrain |      | 0.3  | 1.5675057 | 0.4      | 0.748             | 40 Yes ( $\epsilon_{DA} = 5\%$ )                                                 |
| UT-19   | 50.00  | 0.995 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 9.5 Yes ( $\epsilon_{DA} = 5\%$ )                                                |
| UT-20   | 100.00 | 0.500 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 14.5 Yes ( $\epsilon_{DA} = 5\%$ )                                               |
| UT-21   | 200.00 | 0.250 | triaxial     | Undrain |      | 0.5  | 1.5675057 | 0.4      | 0.748             | 80 No ( $N_L > 30$ )                                                             |
| UT-22   | 50.00  |       | triaxial     | Undrain | 0.19 | 0.0  | 1.518847  | 0.2      | 0.804             | 1 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-23   | 100.00 |       | triaxial     | Undrain | 0.19 | 0.0  | 1.518847  | 0.2      | 0.804             | 2 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-24   | 200.00 |       | triaxial     | Undrain | 0.19 | 0.0  | 1.518847  | 0.2      | 0.804             | 14.5 Yes ( $\epsilon_{DA} = 5\%$ )                                               |
| UT-25   | 50.00  |       | triaxial     | Undrain |      | 0.3  | 1.518847  | 0.2      | 0.804             | 2 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-26   | 100.00 |       | triaxial     | Undrain |      | 0.3  | 1.518847  | 0.2      | 0.804             | 3 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-27   | 200.00 |       | triaxial     | Undrain |      | 0.3  | 1.518847  | 0.2      | 0.804             | 28 Yes ( $\epsilon_{DA} = 5\%$ )                                                 |
| UT-28   | 50.00  |       | triaxial     | Undrain |      | 0.5  | 1.518847  | 0.2      | 0.804             | 3 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-29   | 100.00 |       | triaxial     | Undrain |      | 0.5  | 1.518847  | 0.2      | 0.804             | 5 Yes ( $\epsilon_{DA} = 5\%$ )                                                  |
| UT-30   | 200.00 |       | triaxial     | Undrain |      | 0.5  | 1.518847  | 0.2      | 0.804             | 41 No ( $N_L > 30$ )                                                             |
| UT-1    | 100.00 | 0.225 | triaxial     | Undrain | 0.34 | 0.0  |           | 0.4      | 0.787             | 86.0 No ( $N_L > 30$ )                                                           |
| UT-2    | 100.00 | 0.230 | triaxial     | Undrain | 0.34 | 0.0  | 0.387     | 0.790965 | 50.0              | No ( $N_L > 30$ )                                                                |
| UT-3    | 100.00 | 0.250 | triaxial     | Undrain | 0.34 | 0.0  | 0.396     | 0.78822  | 18.0              | Yes ( $r_u = 1$ )                                                                |
| UT-4    | 100.00 | 0.290 | triaxial     | Undrain | 0.34 | 0.0  | 0.407     | 0.784865 | 6.0               | Yes ( $r_u = 1$ )                                                                |
| UT-5    | 100.00 | 0.260 | triaxial     | Undrain | 0.34 | 0.0  | 0.383     | 0.792185 | 286.0             | No ( $N_L > 30$ )                                                                |
| UT-6    | 100.00 | 0.300 | triaxial     | Undrain | 0.34 | 0.0  | 0.403     | 0.786085 | 30.0              | Yes ( $r_u = 1$ )                                                                |
| UT-7    | 100.00 | 0.400 | triaxial     | Undrain | 0.34 | 0.0  | 0.396     | 0.78822  | 10.0              | Yes ( $r_u = 1$ )                                                                |
| UT-8    | 100.00 | 0.350 | triaxial     | Undrain | 0.34 | 0.0  | 0.391     | 0.789745 | 517.0             | No ( $N_L > 30$ )                                                                |
| UT-9    | 100.00 | 0.400 | triaxial     | Undrain | 0.34 | 0.0  | 0.386     | 0.79127  | 118.0             | No ( $N_L > 30$ )                                                                |
| UT-10   | 100.00 | 0.450 | triaxial     | Undrain | 0.34 | 0.0  | 0.405     | 0.785475 | 106.0             | No ( $N_L > 30$ )                                                                |
| UT-11   | 100.00 | 0.225 | triaxial     | Undrain | 0.32 | 10.0 | 0.393     | 0.691263 | 87.0              | No ( $N_L > 30$ )                                                                |
| UT-12   | 100.00 | 0.175 | triaxial     | Undrain | 0.32 | 10.0 | 0.38      | 0.69658  | 386.0             | No ( $N_L > 30$ )                                                                |
| UT-13   | 100.00 | 0.200 | triaxial     | Undrain | 0.32 | 10.0 | 0.389     | 0.692899 | 102.0             | No ( $N_L > 30$ )                                                                |
| UT-14   | 100.00 | 0.250 | triaxial     | Undrain | 0.32 | 10.0 | 0.406     | 0.685946 | 28.0              | Yes ( $r_u = 1$ )                                                                |
| UT-15   | 100.00 | 0.250 | triaxial     | Undrain | 0.32 | 10.0 | 0.398     | 0.689218 | 76.0              | No ( $N_L > 30$ )                                                                |
| UT-16   | 100.00 | 0.300 | triaxial     | Undrain | 0.32 | 10.0 | 0.38      | 0.69658  | 38.0              | No ( $N_L > 30$ )                                                                |
| UT-17   | 100.00 | 0.350 | triaxial     | Undrain | 0.32 | 10.0 | 0.398     | 0.689218 | 16.0              | Yes ( $r_u = 1$ )                                                                |
| UT-18   | 100.00 | 0.365 | triaxial     | Undrain | 0.32 | 10.0 | 0.395     | 0.690445 | 11.0              | Yes ( $r_u = 1$ )                                                                |
| UT-19   | 100.00 | 0.300 | triaxial     | Undrain | 0.32 | 10.0 | 0.401     | 0.687991 | 47.0              | No ( $N_L > 30$ )                                                                |
| UT-20   | 100.00 | 0.340 | triaxial     | Undrain | 0.32 | 10.0 | 0.406     | 0.685946 | 30.0              | Yes ( $r_u = 1$ )                                                                |
| UT-21   | 100.00 | 0.400 | triaxial     | Undrain | 0.32 | 10.0 | 0.397     | 0.689627 | 22.0              | Yes ( $r_u = 1$ )                                                                |
| UT-22   | 100.00 | 0.400 | triaxial     | Undrain | 0.32 | 10.0 | 0.406     | 0.685946 | 20.0              | No ( $N_L > 30$ )                                                                |
| UT-23   | 100.00 | 0.500 | triaxial     | Undrain | 0.32 | 10.0 | 0.38      | 0.69658  | 26.0              | Yes ( $r_u = 1$ )                                                                |
| UT-24   | 100.00 | 0.225 | triaxial     | Undrain | 0.3  | 20.0 | 0.401     | 0.650134 | 83.0              | No ( $N_L > 30$ )                                                                |
| UT-25   | 100.00 | 0.235 | triaxial     | Undrain | 0.3  | 20.0 | 0.4       | 0.6506   | 24.0              | Yes ( $r_u = 1$ )                                                                |
| UT-26   | 100.00 | 0.250 | triaxial     | Undrain | 0.3  | 20.0 | 0.401     | 0.650134 | 18.0              | Yes ( $r_u = 1$ )                                                                |
| UT-27</ |        |       |              |         |      |      |           |          |                   |                                                                                  |

|       |        |         |                  |         |            |       |             |            |         |                                              |                                              |
|-------|--------|---------|------------------|---------|------------|-------|-------------|------------|---------|----------------------------------------------|----------------------------------------------|
| UT-7  | 120.00 | 0.4     | Torsional torque | Undrain | 0.361      | 0.0   | 0.696551724 | 0.668      | 2.75    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-8  | 120.00 | 0.5     | Torsional torque | Undrain | 0.361      | 0.0   | 0.703448276 | 0.666      | 1.6     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-9  | 240.00 | 0.2     | Torsional torque | Undrain | 0.361      | 0.0   | 0.696551724 | 0.668      | 898     | No ( $N_L > 30$ )                            |                                              |
| UT-10 | 240.00 | 0.246   | Torsional torque | Undrain | 0.361      | 0.0   | 0.703448276 | 0.666      | 323.5   | No ( $N_L > 30$ )                            |                                              |
| UT-11 | 240.00 | 0.3     | Torsional torque | Undrain | 0.361      | 0.0   | 0.710344828 | 0.664      | 43.6    | No ( $N_L > 30$ )                            |                                              |
| UT-12 | 240.00 | 0.331   | Torsional torque | Undrain | 0.361      | 0.0   | 0.717241379 | 0.662      | 1.25    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-13 | 60.00  | 0.2     | Torsional torque | Undrain | 0.351      | 15.0  | 0.635714286 | 0.563      | 127.6   | No ( $N_L > 30$ )                            |                                              |
| UT-14 | 60.00  | 0.226   | Torsional torque | Undrain | 0.351      | 15.0  | 0.642857143 | 0.56       | 66.25   | No ( $N_L > 30$ )                            |                                              |
| UT-15 | 60.00  | 0.3     | Torsional torque | Undrain | 0.351      | 15.0  | 0.647619048 | 0.558      | 23.3    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-16 | 60.00  | 0.4001  | Torsional torque | Undrain | 0.351      | 15.0  | 0.652380952 | 0.556      | 3.2     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-17 | 120.00 | 0.25    | Torsional torque | Undrain | 0.351      | 15.0  | 0.638095238 | 0.562      | 226.1   | No ( $N_L > 30$ )                            |                                              |
| UT-18 | 120.00 | 0.273   | Torsional torque | Undrain | 0.351      | 15.0  | 0.645238095 | 0.559      | 124.5   | No ( $N_L > 30$ )                            |                                              |
| UT-19 | 120.00 | 0.3     | Torsional torque | Undrain | 0.351      | 15.0  | 0.661904762 | 0.552      | 43.2    | No ( $N_L > 30$ )                            |                                              |
| UT-20 | 120.00 | 0.35    | Torsional torque | Undrain | 0.351      | 15.0  | 0.664285714 | 0.551      | 3.19    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-21 | 240.00 | 0.15    | Torsional torque | Undrain | 0.351      | 15.0  | 0.664285714 | 0.551      | 665     | No ( $N_L > 30$ )                            |                                              |
| UT-22 | 240.00 | 0.173   | Torsional torque | Undrain | 0.351      | 15.0  | 0.669047619 | 0.549      | 236     | No ( $N_L > 30$ )                            |                                              |
| UT-23 | 240.00 | 0.2     | Torsional torque | Undrain | 0.351      | 15.0  | 0.671428571 | 0.548      | 21.8    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-24 | 240.00 | 0.3     | Torsional torque | Undrain | 0.351      | 15.0  | 0.685714286 | 0.542      | 0.171   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-25 | 60.00  | 0.255   | Torsional torque | Undrain | 0.308      | 30.0  | 0.628037383 | 0.518      | 259     | No ( $N_L > 30$ )                            |                                              |
| UT-26 | 60.00  | 0.3     | Torsional torque | Undrain | 0.308      | 30.0  | 0.637363178 | 0.513      | 132.5   | No ( $N_L > 30$ )                            |                                              |
| UT-27 | 60.00  | 0.35    | Torsional torque | Undrain | 0.308      | 30.0  | 0.639252336 | 0.512      | 31.2    | No ( $N_L > 30$ )                            |                                              |
| UT-28 | 60.00  | 0.4     | Torsional torque | Undrain | 0.64289854 | 0.51  | 2.7         | 0.64289854 | 0.51    | 2.7                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-29 | 120.00 | 0.109   | Torsional torque | Undrain | 0.308      | 30.0  | 0.626168224 | 0.519      | 373.35  | No ( $N_L > 30$ )                            |                                              |
| UT-30 | 120.00 | 0.15    | Torsional torque | Undrain | 0.308      | 30.0  | 0.631775701 | 0.516      | 167.4   | No ( $N_L > 30$ )                            |                                              |
| UT-31 | 120.00 | 0.2001  | Torsional torque | Undrain | 0.308      | 30.0  | 0.637363178 | 0.513      | 10.27   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-32 | 120.00 | 0.218   | Torsional torque | Undrain | 0.308      | 30.0  | 0.639252336 | 0.512      | 0.75    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-33 | 240.00 | 0.125   | Torsional torque | Undrain | 0.308      | 30.0  | 0.646728972 | 0.508      | 114.3   | No ( $N_L > 30$ )                            |                                              |
| UT-34 | 240.00 | 0.15    | Torsional torque | Undrain | 0.308      | 30.0  | 0.648598131 | 0.507      | 35      | No ( $N_L > 30$ )                            |                                              |
| UT-35 | 240.00 | 0.2     | Torsional torque | Undrain | 0.308      | 30.0  | 0.656074766 | 0.503      | 2.8     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-36 | 240.00 | 0.291   | Torsional torque | Undrain | 0.308      | 30.0  | 0.66728972  | 0.497      | 0.25    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-37 | 60.00  | 0.2001  | Torsional torque | Undrain | 0.05       | 60.0  | 0.618464961 | 0.703      | 175     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-38 | 60.00  | 0.30002 | Torsional torque | Undrain | 0.05       | 60.0  | 0.621802002 | 0.7        | 36      | No ( $N_L > 30$ )                            |                                              |
| UT-39 | 60.00  | 0.3637  | Torsional torque | Undrain | 0.05       | 60.0  | 0.624026696 | 0.698      | 10.22   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-40 | 60.00  | 0.4438  | Torsional torque | Undrain | 0.05       | 60.0  | 0.62625139  | 0.696      | 1.25    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-41 | 120.00 | 0.113   | Torsional torque | Undrain | 0.05       | 60.0  | 0.63403782  | 0.689      | 118.6   | No ( $N_L > 30$ )                            |                                              |
| UT-42 | 120.00 | 0.15    | Torsional torque | Undrain | 0.05       | 60.0  | 0.636262514 | 0.687      | 50      | No ( $N_L > 30$ )                            |                                              |
| UT-43 | 120.00 | 0.225   | Torsional torque | Undrain | 0.05       | 60.0  | 0.640711902 | 0.683      | 15      | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-44 | 120.00 | 0.3001  | Torsional torque | Undrain | 0.05       | 60.0  | 0.649610679 | 0.675      | 2.2     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-45 | 240.00 | 0.15    | Torsional torque | Undrain | 0.05       | 60.0  | 0.631813126 | 0.691      | 242.7   | No ( $N_L > 30$ )                            |                                              |
| UT-46 | 240.00 | 0.2     | Torsional torque | Undrain | 0.05       | 60.0  | 0.642936596 | 0.681      | 132     | No ( $N_L > 30$ )                            |                                              |
| UT-47 | 240.00 | 0.273   | Torsional torque | Undrain | 0.05       | 60.0  | 0.65294772  | 0.672      | 7.2     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-48 | 240.00 | 0.3     | Torsional torque | Undrain | 0.05       | 60.0  | 0.655172414 | 0.67       | 0.3     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-49 | 60.00  | 0.2     | Torsional torque | Undrain | 0.021      | 100.0 | 0.61971831  | 1          | 42.6    | No ( $N_L > 30$ )                            |                                              |
| UT-50 | 60.00  | 0.218   | Torsional torque | Undrain | 0.021      | 100.0 | 0.621126761 | 0.998      | 25      | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-51 | 60.00  | 0.2401  | Torsional torque | Undrain | 0.021      | 100.0 | 0.628873239 | 0.987      | 10.31   | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-52 | 60.00  | 0.3     | Torsional torque | Undrain | 0.021      | 100.0 | 0.630985915 | 0.984      | 0.88    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-53 | 120.00 | 0.1     | Torsional torque | Undrain | 0.021      | 100.0 | 0.633802817 | 0.98       | 39.9    | No ( $N_L > 30$ )                            |                                              |
| UT-54 | 120.00 | 0.12    | Torsional torque | Undrain | 0.021      | 100.0 | 0.640140845 | 0.971      | 23.8    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-55 | 120.00 | 0.15    | Torsional torque | Undrain | 0.021      | 100.0 | 0.644366197 | 0.965      | 7.8     | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-56 | 120.00 | 0.2     | Torsional torque | Undrain | 0.021      | 100.0 | 0.647183099 | 0.961      | 2.33    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-57 | 240.00 | 0.06    | Torsional torque | Undrain | 0.021      | 100.0 | 0.643661972 | 0.966      | 138.4   | No ( $N_L > 30$ )                            |                                              |
| UT-58 | 240.00 | 0.075   | Torsional torque | Undrain | 0.021      | 100.0 | 0.647887324 | 0.96       | 68.5    | No ( $N_L > 30$ )                            |                                              |
| UT-59 | 240.00 | 0.1     | Torsional torque | Undrain | 0.021      | 100.0 | 0.655633803 | 0.949      | 33.29   | No ( $N_L > 30$ )                            |                                              |
| UT-60 | 240.00 | 0.15    | Torsional torque | Undrain | 0.021      | 100.0 | 0.666901408 | 0.933      | 3.69    | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |                                              |
| UT-1  | 98.00  | 0.353   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.411474    | 0.51       | 0.87747 | 4.2                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-2  | 98.00  | 0.236   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.411474    | 0.51       | 0.87747 | 11.7                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-3  | 98.00  | 0.236   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3935267   | 0.45       | 0.90165 | 12.7                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-4  | 98.00  | 0.205   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.4084507   | 0.5        | 0.8815  | 34.1                                         | No ( $N_L > 30$ )                            |
| UT-5  | 98.00  | 0.188   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.4145102   | 0.52       | 0.87344 | 55.2                                         | No ( $N_L > 30$ )                            |
| UT-6  | 98.00  | 0.201   | Torsional shear  | Undrain | 0.1448     | 10.0  | 1.4752136   | 0.55       | 0.79635 | 5.1                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-7  | 98.00  | 0.184   | Torsional shear  | Undrain | 0.1448     | 10.0  | 1.4347435   | 0.46       | 0.84702 | 15.2                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-8  | 98.00  | 0.182   | Torsional shear  | Undrain | 0.1448     | 10.0  | 1.4752136   | 0.55       | 0.79635 | 15.6                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-9  | 98.00  | 0.170   | Torsional shear  | Undrain | 0.1667     | 20.0  | 1.4284174   | 0.44       | 0.8552  | 5.1                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-10 | 98.00  | 0.151   | Torsional shear  | Undrain | 0.1667     | 20.0  | 1.4228952   | 0.43       | 0.8624  | 9.6                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-11 | 98.00  | 0.119   | Torsional shear  | Undrain | 0.1667     | 20.0  | 1.4801162   | 0.53       | 0.7904  | 47.6                                         | No ( $N_L > 30$ )                            |
| UT-12 | 98.00  | 0.126   | Torsional shear  | Undrain | 0.184      | 30.0  | 1.3750162   | 0.45       | 0.92725 | 25.7                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-13 | 98.00  | 0.111   | Torsional shear  | Undrain | 0.184      | 30.0  | 1.4144272   | 0.51       | 0.87355 | 46.7                                         | No ( $N_L > 30$ )                            |
| UT-14 | 49.00  | 0.213   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.4084507   | 0.5        | 0.8815  | 13.7                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-15 | 49.00  | 0.215   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.4024429   | 0.48       | 0.88956 | 17.1                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-16 | 49.00  | 0.165   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.4084507   | 0.5        | 0.8815  | 194.1                                        | No ( $N_L > 30$ )                            |
| UT-17 | 196.00 | 0.245   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3964861   | 0.46       | 0.89762 | 9.6                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-18 | 196.00 | 0.211   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.4024429   | 0.48       | 0.88956 | 24.7                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-19 | 196.00 | 0.183   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3994582   | 0.47       | 0.89359 | 54.1                                         | No ( $N_L > 30$ )                            |
| UT-20 | 98.00  | 0.232   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3395881   | 0.26       | 0.97822 | 6.1                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-21 | 98.00  | 0.190   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3450684   | 0.28       | 0.97016 | 6.2                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-22 | 98.00  | 0.197   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3478254   | 0.29       | 0.96613 | 11                                           | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-23 | 98.00  | 0.172   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3646077   | 0.35       | 0.94195 | 26.1                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-24 | 98.00  | 0.168   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3450684   | 0.28       | 0.97016 | 27.7                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-25 | 98.00  | 0.151   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3533735   | 0.31       | 0.95807 | 85.6                                         | No ( $N_L > 30$ )                            |
| UT-26 | 49.00  | 0.227   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3533735   | 0.31       | 0.95807 | 4.6                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-27 | 49.00  | 0.180   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3505938   | 0.3        | 0.9621  | 15.8                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-28 | 49.00  | 0.183   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3478254   | 0.29       | 0.96613 | 20.1                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-29 | 196.00 | 0.210   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3533735   | 0.31       | 0.95807 | 5.6                                          | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-30 | 196.00 | 0.185   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3478254   | 0.29       | 0.96613 | 23.1                                         | Yes ( $r_u = 1$ or $\epsilon_{DA} = 7.5\%$ ) |
| UT-31 | 196.00 | 0.153   | Torsional shear  | Undrain | 0.0154     | 0.0   | 1.3646077   | 0.35       | 0.94195 | 30.6                                         | No ( $N_L > 30$ )                            |
| UT-1  | 98.00  | 0.118   | Triaxial         | Undrain | 0.19       | 0.0   | 0.27        |            | 32.0    | No ( $N_L > 30$ )                            |                                              |
| UT-2  | 98.00  | 0.144   | Triaxial         | Undrain | 0.19       | 0.0   | 0.34        |            | 1.7     | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-3  | 98.00  | 0.124   | Triaxial         | Undrain | 0.19       | 0.0   | 0.36        |            | 16.0    | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-4  | 98.00  | 0.194   | Triaxial         | Undrain | 0.19       | 0.0   | 0.49        |            | 4.0     | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-5  | 98.00  | 0.146   | Triaxial         | Undrain | 0.19       | 0.0   | 0.51        |            | 34.0    | No ( $N_L > 30$ )                            |                                              |
| UT-6  | 98.00  | 0.157   | Triaxial         | Undrain | 0.19       | 0.0   | 0.52        |            | 17.0    | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-7  | 98.00  | 0.150   | Triaxial         | Undrain | 0.19       | 0.0   | 0.53        |            | 12.0    | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-8  | 98.00  | 0.259   | Triaxial         | Undrain | 0.19       | 0.0   | 0.69        |            | 3.6     | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-9  | 98.00  | 0.299   | Triaxial         | Undrain | 0.19       | 0.0   | 0.70        |            | 3.5     | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-10 | 98.00  | 0.198   | Triaxial         | Undrain | 0.19       | 0.0   | 0.70        |            | 16.0    | Yes ( $\epsilon_{DA} = 5\%$ )                |                                              |
| UT-11 | 98.00  |         |                  |         |            |       |             |            |         |                                              |                                              |

|       |        |        |               |         |       |     |           |       |          |      |                                               |
|-------|--------|--------|---------------|---------|-------|-----|-----------|-------|----------|------|-----------------------------------------------|
| UT-17 | 60.00  | 0.162  | Direct Simple | Undrain | 0.55  | 0.0 | 1.62      | 0.685 | 0.645475 | 3    | Yes ( $r_u = 0.85$ )                          |
| UT-18 | 60.00  | 0.086  | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.784 | 0.61924  | 69   | No ( $N_L > 30$ )                             |
| UT-19 | 60.00  | 0.101  | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.777 | 0.621095 | 36.5 | No ( $N_L > 30$ )                             |
| UT-20 | 60.00  | 0.1092 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.804 | 0.61394  | 17   | Yes ( $r_u = 0.85$ )                          |
| UT-21 | 60.00  | 0.1104 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.757 | 0.626395 | 12   | Yes ( $r_u = 0.85$ )                          |
| UT-22 | 60.00  | 0.1334 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.773 | 0.622155 | 9    | Yes ( $r_u = 0.85$ )                          |
| UT-23 | 60.00  | 0.1335 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.769 | 0.623215 | 5.5  | Yes ( $r_u = 0.85$ )                          |
| UT-24 | 60.00  | 0.1574 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.781 | 0.620035 | 4.5  | Yes ( $r_u = 0.85$ )                          |
| UT-25 | 60.00  | 0.1655 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.769 | 0.623215 | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-26 | 60.00  | 0.21   | Direct Simple | Undrain | 0.55  | 0.0 | 1.63      | 0.744 | 0.62984  | 3    | Yes ( $r_u = 0.85$ )                          |
| UT-27 | 100.00 | 0.0645 | Direct Simple | Undrain | 0.55  | 0.0 | 1.50      | 0.208 | 0.77188  | 49   | No ( $N_L > 30$ )                             |
| UT-28 | 100.00 | 0.0651 | Direct Simple | Undrain | 0.55  | 0.0 | 1.53      | 0.313 | 0.744055 | 42   | No ( $N_L > 30$ )                             |
| UT-29 | 100.00 | 0.079  | Direct Simple | Undrain | 0.55  | 0.0 | 1.53      | 0.327 | 0.740345 | 10   | Yes ( $r_u = 0.85$ )                          |
| UT-30 | 100.00 | 0.0795 | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.226 | 0.76711  | 13   | Yes ( $r_u = 0.85$ )                          |
| UT-31 | 100.00 | 0.0799 | Direct Simple | Undrain | 0.55  | 0.0 | 1.52      | 0.304 | 0.74844  | 10   | Yes ( $r_u = 0.85$ )                          |
| UT-32 | 100.00 | 0.0985 | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.259 | 0.758365 | 3.5  | Yes ( $r_u = 0.85$ )                          |
| UT-33 | 100.00 | 0.0995 | Direct Simple | Undrain | 0.55  | 0.0 | 1.50      | 0.205 | 0.772675 | 5.5  | Yes ( $r_u = 0.85$ )                          |
| UT-34 | 100.00 | 0.0804 | Direct Simple | Undrain | 0.55  | 0.0 | 1.53      | 0.354 | 0.73319  | 12   | Yes ( $r_u = 0.85$ )                          |
| UT-35 | 100.00 | 0.1008 | Direct Simple | Undrain | 0.55  | 0.0 | 1.55      | 0.424 | 0.71464  | 4.5  | Yes ( $r_u = 0.85$ )                          |
| UT-36 | 100.00 | 0.1233 | Direct Simple | Undrain | 0.55  | 0.0 | 1.56      | 0.455 | 0.706425 | 2    | Yes ( $r_u = 0.85$ )                          |
| UT-37 | 100.00 | 0.1285 | Direct Simple | Undrain | 0.55  | 0.0 | 1.55      | 0.419 | 0.715965 | 1.5  | Yes ( $r_u = 0.85$ )                          |
| UT-38 | 100.00 | 0.0801 | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.607 | 0.666145 | 30.5 | No ( $N_L > 30$ )                             |
| UT-39 | 100.00 | 0.092  | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.62  | 0.6627   | 19.5 | Yes ( $r_u = 0.85$ )                          |
| UT-40 | 100.00 | 0.0988 | Direct Simple | Undrain | 0.55  | 0.0 | 1.59      | 0.591 | 0.670385 | 8    | Yes ( $r_u = 0.85$ )                          |
| UT-41 | 100.00 | 0.1098 | Direct Simple | Undrain | 0.55  | 0.0 | 1.59      | 0.599 | 0.668265 | 4.5  | Yes ( $r_u = 0.85$ )                          |
| UT-42 | 100.00 | 0.1148 | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.62  | 0.6627   | 13.5 | Yes ( $r_u = 0.85$ )                          |
| UT-43 | 100.00 | 0.1369 | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.636 | 0.65846  | 9.5  | Yes ( $r_u = 0.85$ )                          |
| UT-44 | 100.00 | 0.1657 | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.624 | 0.66164  | 3    | Yes ( $r_u = 0.85$ )                          |
| UT-45 | 100.00 | 0.2068 | Direct Simple | Undrain | 0.55  | 0.0 | 1.59      | 0.595 | 0.669325 | 1    | Yes ( $r_u = 0.85$ )                          |
| UT-46 | 100.00 | 0.0929 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.792 | 0.61712  | 80   | No ( $N_L > 30$ )                             |
| UT-47 | 100.00 | 0.0964 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.781 | 0.620035 | 33.5 | No ( $N_L > 30$ )                             |
| UT-48 | 100.00 | 0.114  | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.788 | 0.61818  | 10.5 | Yes ( $r_u = 0.85$ )                          |
| UT-49 | 100.00 | 0.1147 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.792 | 0.61712  | 13.5 | Yes ( $r_u = 0.85$ )                          |
| UT-50 | 100.00 | 0.1266 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.827 | 0.607845 | 6    | Yes ( $r_u = 0.85$ )                          |
| UT-51 | 100.00 | 0.1365 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.812 | 0.61182  | 9.5  | Yes ( $r_u = 0.85$ )                          |
| UT-52 | 100.00 | 0.1899 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.816 | 0.61076  | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-53 | 100.00 | 0.2051 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.792 | 0.61712  | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-54 | 100.00 | 0.2097 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.796 | 0.61606  | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-55 | 100.00 | 0.2111 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.808 | 0.61288  | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-56 | 250.00 | 0.0648 | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.268 | 0.75598  | 38.5 | No ( $N_L > 30$ )                             |
| UT-57 | 250.00 | 0.0895 | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.259 | 0.758365 | 5.5  | Yes ( $r_u = 0.85$ )                          |
| UT-58 | 250.00 | 0.0817 | Direct Simple | Undrain | 0.55  | 0.0 | 1.57      | 0.511 | 0.691585 | 35.5 | No ( $N_L > 30$ )                             |
| UT-59 | 250.00 | 0.1261 | Direct Simple | Undrain | 0.55  | 0.0 | 1.57      | 0.507 | 0.692645 | 5.5  | Yes ( $r_u = 0.85$ )                          |
| UT-60 | 250.00 | 0.0921 | Direct Simple | Undrain | 0.55  | 0.0 | 1.61      | 0.661 | 0.651835 | 62   | No ( $N_L > 30$ )                             |
| UT-61 | 250.00 | 0.1119 | Direct Simple | Undrain | 0.55  | 0.0 | 1.61      | 0.644 | 0.65634  | 14.5 | Yes ( $r_u = 0.85$ )                          |
| UT-62 | 250.00 | 0.1803 | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.607 | 0.666145 | 2    | Yes ( $r_u = 0.85$ )                          |
| UT-63 | 250.00 | 0.0915 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.781 | 0.620035 | 42   | No ( $N_L > 30$ )                             |
| UT-64 | 250.00 | 0.0969 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.827 | 0.607845 | 28   | Yes ( $r_u = 0.85$ )                          |
| UT-65 | 250.00 | 0.1117 | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.823 | 0.608905 | 22   | Yes ( $r_u = 0.85$ )                          |
| UT-66 | 250.00 | 0.1623 | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.777 | 0.621095 | 3    | Yes ( $r_u = 0.85$ )                          |
| UT-67 | 60.00  | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.52      | 0.272 | 0.75492  | 18.5 | Yes ( $r_u = 0.85$ )                          |
| UT-68 | 60.00  | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.259 | 0.758365 | 4.5  | Yes ( $r_u = 0.85$ )                          |
| UT-69 | 60.00  | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.612 | 0.66482  | 6    | Yes ( $r_u = 0.85$ )                          |
| UT-70 | 60.00  | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.59      | 0.578 | 0.67383  | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-71 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.228 | 0.76658  | 15.5 | Yes ( $r_u = 0.85$ )                          |
| UT-72 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.54      | 0.363 | 0.730805 | 5.5  | Yes ( $r_u = 0.85$ )                          |
| UT-73 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.50      | 0.221 | 0.768435 | 4    | Yes ( $r_u = 0.85$ )                          |
| UT-74 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.50      | 0.217 | 0.769495 | 2.5  | Yes ( $r_u = 0.85$ )                          |
| UT-75 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.57      | 0.498 | 0.69503  | 8.5  | Yes ( $r_u = 0.85$ )                          |
| UT-76 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.57      | 0.507 | 0.692645 | 3.5  | Yes ( $r_u = 0.85$ )                          |
| UT-77 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.58      | 0.54  | 0.6839   | 9    | Yes ( $r_u = 0.85$ )                          |
| UT-78 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.58      | 0.56  | 0.6786   | 3    | Yes ( $r_u = 0.85$ )                          |
| UT-79 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.58      | 0.557 | 0.679395 | 2    | Yes ( $r_u = 0.85$ )                          |
| UT-80 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.8   | 0.615    | 5.5  | Yes ( $r_u = 0.85$ )                          |
| UT-81 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.63      | 0.733 | 0.632755 | 4    | Yes ( $r_u = 0.85$ )                          |
| UT-82 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.65      | 0.808 | 0.61288  | 3    | Yes ( $r_u = 0.85$ )                          |
| UT-83 | 100.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.64      | 0.781 | 0.620035 | 2    | Yes ( $r_u = 0.85$ )                          |
| UT-84 | 250.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.51      | 0.254 | 0.75969  | 55.5 | No ( $N_L > 30$ )                             |
| UT-85 | 250.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.53      | 0.349 | 0.734515 | 10.5 | Yes ( $r_u = 0.85$ )                          |
| UT-86 | 250.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.632 | 0.65952  | 7.5  | Yes ( $r_u = 0.85$ )                          |
| UT-87 | 250.00 | 0      | Direct Simple | Undrain | 0.55  | 0.0 | 1.60      | 0.632 | 0.65952  | 4    | Yes ( $r_u = 0.85$ )                          |
| UT-1  | 50.00  | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3874346 | 0.3   | 0.91     | 130  | No ( $N_L > 30$ )                             |
| UT-2  | 50.00  | 0.150  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3859833 | 0.3   | 0.912    | 20   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-3  | 100.00 | 0.075  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3874346 | 0.3   | 0.91     | 100  | No ( $N_L > 30$ )                             |
| UT-4  | 100.00 | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3874346 | 0.3   | 0.91     | 30   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-5  | 100.00 | 0.125  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3903463 | 0.3   | 0.906    | 8    | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-6  | 200.00 | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3947368 | 0.3   | 0.9      | 14   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-7  | 200.00 | 0.125  | Triaxial      | Undrain | 0.34  | 0.0 | 1.3918067 | 0.3   | 0.904    | 4    | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-8  | 50.00  | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4363144 | 0.5   | 0.845    | 110  | No ( $N_L > 30$ )                             |
| UT-9  | 50.00  | 0.125  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4363144 | 0.5   | 0.845    | 50   | No ( $N_L > 30$ )                             |
| UT-10 | 100.00 | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4402174 | 0.5   | 0.84     | 65   | No ( $N_L > 30$ )                             |
| UT-11 | 100.00 | 0.125  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4480874 | 0.5   | 0.83     | 30   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-12 | 100.00 | 0.175  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4402174 | 0.5   | 0.84     | 8    | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-13 | 200.00 | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4324324 | 0.5   | 0.85     | 70   | No ( $N_L > 30$ )                             |
| UT-14 | 200.00 | 0.125  | Triaxial      | Undrain | 0.34  | 0.0 | 1.4324324 | 0.5   | 0.85     | 30   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-15 | 50.00  | 0.200  | Triaxial      | Undrain | 0.34  | 0.0 | 1.5186246 | 0.8   | 0.745    | 60   | No ( $N_L > 30$ )                             |
| UT-16 | 50.00  | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.5186246 | 0.8   | 0.745    | 2000 | No ( $N_L > 30$ )                             |
| UT-17 | 100.00 | 0.100  | Triaxial      | Undrain | 0.34  | 0.0 | 1.5264977 | 0.8   | 0.736    | 1050 | No ( $N_L > 30$ )                             |
| UT-18 | 100.00 | 0.200  | Triaxial      | Undrain | 0.34  | 0.0 | 1.5229885 | 0.8   | 0.74     | 30   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-19 | 100.00 | 0.225  | Triaxial      | Undrain | 0.34  | 0.0 | 1.5317919 | 0.8   | 0.73     | 14   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-20 | 200.00 | 0.2    | Triaxial      | Undrain | 0.34  | 0.0 | 1.5142857 | 0.8   | 0.75     | 10   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-21 | 200.00 | 0.1    | Triaxial      | Undrain | 0.34  | 0.0 | 1.5142857 | 0.8   | 0.75     | 2000 | No ( $N_L > 30$ )                             |
| UT-22 | 50.00  | 0.2    | Triaxial      | Undrain | 0.34  | 0.0 | 1.5142857 | 0.8   | 0.75     |      | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-23 | 100.00 | 0.2    | Triaxial      | Undrain | 0.34  | 0.0 | 1.5142857 | 0.8   | 0.75     |      | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-24 | 100.00 | 0.05   | Triaxial      | Undrain | 0.338 | 5.0 | 1.3947368 | 0.3   | 0.9      | 2000 | No ( $N_L > 30$ )                             |
| UT-25 | 100.00 | 0.1    | Triaxial      | Undrain | 0.338 | 5.0 | 1.4021164 | 0.3   | 0.89     | 70   | No ( $N_L > 30$ )                             |
| UT-26 | 100.00 | 0.15   | Triaxial      | Undrain | 0.338 | 5.0 | 1.4058355 | 0.3   | 0.885    | 15   | Yes ( $r_u = 1$ or $\varepsilon_{sk} = 3\%$ ) |
| UT-27 | 100.00 | 0.125  | Triaxial      | Undrain | 0.338 | 5.0 | 1.4640884 | 0.5   | 0.81     | 120  | No ( $N_L > 30$ )                             |
| UT-28 | 100.00 | 0.15   | Triaxial      | Undrain | 0.338 | 5.0 | 1.4722222 | 0.5   | 0.8      | 60   | No ( $N_L > 30$ )                             |

|       |        |       |              |         |       |      |             |      |     |                               |
|-------|--------|-------|--------------|---------|-------|------|-------------|------|-----|-------------------------------|
| UT-4  | 100.00 | 0.230 | Simple shear | Undrain | 0.56  | 0.0  | 0.71        | 0.68 | 3   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-5  | 100.00 | 0.200 | Simple shear | Undrain | 0.56  | 0.0  | 0.71        | 0.68 | 9   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-6  | 100.00 | 0.160 | Simple shear | Undrain | 0.56  | 0.0  | 0.71        | 0.68 | 19  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-7  | 100.00 | 0.140 | Simple shear | Undrain | 0.56  | 0.0  | 0.71        | 0.68 | 76  | No ( $N_L > 30$ )             |
| UT-8  | 100.00 | 0.100 | Simple shear | Undrain | 0.56  | 0.0  | 0.71        | 0.68 | 229 | No ( $N_L > 30$ )             |
| UT-9  | 100.00 | 0.180 | Simple shear | Undrain | 0.56  | 0.0  | 0.54        | 0.74 | 7   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-10 | 100.00 | 0.160 | Simple shear | Undrain | 0.56  | 0.0  | 0.54        | 0.74 | 12  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-11 | 100.00 | 0.140 | Simple shear | Undrain | 0.56  | 0.0  | 0.54        | 0.74 | 24  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-12 | 100.00 | 0.120 | Simple shear | Undrain | 0.56  | 0.0  | 0.54        | 0.74 | 126 | No ( $N_L > 30$ )             |
| UT-13 | 100.00 | 0.200 | Simple shear | Undrain | 0.56  | 0.0  | 0.43        | 0.78 | 2   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-14 | 100.00 | 0.180 | Simple shear | Undrain | 0.56  | 0.0  | 0.43        | 0.78 | 4   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-15 | 100.00 | 0.160 | Simple shear | Undrain | 0.56  | 0.0  | 0.43        | 0.78 | 9   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-16 | 100.00 | 0.140 | Simple shear | Undrain | 0.56  | 0.0  | 0.43        | 0.78 | 28  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-17 | 100.00 | 0.120 | Simple shear | Undrain | 0.56  | 0.0  | 0.43        | 0.78 | 47  | No ( $N_L > 30$ )             |
| UT-18 | 50.00  | 0.150 | Simple shear | Undrain | 0.56  | 0.0  | 0.31        | 0.82 | 15  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-19 | 100.00 | 0.160 | Simple shear | Undrain | 0.56  | 5.0  | 0.37        | 0.73 | 4   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-20 | 100.00 | 0.12  | Simple shear | Undrain | 0.56  | 5.0  | 0.37        | 0.73 | 15  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-21 | 100.00 | 0.1   | Simple shear | Undrain | 0.56  | 5.0  | 0.37        | 0.73 | 235 | No ( $N_L > 30$ )             |
| UT-22 | 100.00 | 0.22  | Simple shear | Undrain | 0.56  | 5.0  | 0.52        | 0.68 | 2   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-23 | 100.00 | 0.16  | Simple shear | Undrain | 0.56  | 5.0  | 0.52        | 0.68 | 13  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-24 | 100.00 | 0.14  | Simple shear | Undrain | 0.56  | 5.0  | 0.52        | 0.68 | 22  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-25 | 100.00 | 0.22  | Simple shear | Undrain | 0.56  | 5.0  | 0.74        | 0.61 | 6   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-26 | 100.00 | 0.2   | Simple shear | Undrain | 0.56  | 5.0  | 0.74        | 0.61 | 8   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-27 | 100.00 | 0.16  | Simple shear | Undrain | 0.56  | 5.0  | 0.74        | 0.61 | 18  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-28 | 100.00 | 0.14  | Simple shear | Undrain | 0.56  | 5.0  | 0.74        | 0.61 | 34  | No ( $N_L > 30$ )             |
| UT-29 | 100.00 | 0.16  | Simple shear | Undrain | 0.55  | 10.0 | 0.38        | 0.68 | 5   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-30 | 100.00 | 0.14  | Simple shear | Undrain | 0.55  | 10.0 | 0.38        | 0.68 | 10  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-31 | 100.00 | 0.12  | Simple shear | Undrain | 0.55  | 10.0 | 0.38        | 0.68 | 25  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-32 | 100.00 | 0.1   | Simple shear | Undrain | 0.55  | 10.0 | 0.38        | 0.68 | 52  | No ( $N_L > 30$ )             |
| UT-33 | 100.00 | 0.2   | Simple shear | Undrain | 0.55  | 10.0 | 0.62        | 0.60 | 4   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-34 | 100.00 | 0.16  | Simple shear | Undrain | 0.55  | 10.0 | 0.62        | 0.60 | 12  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-35 | 100.00 | 0.14  | Simple shear | Undrain | 0.55  | 10.0 | 0.62        | 0.60 | 42  | No ( $N_L > 30$ )             |
| UT-36 | 100.00 | 0.2   | Simple shear | Undrain | 0.55  | 10.0 | 0.82        | 0.53 | 9   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-37 | 100.00 | 0.18  | Simple shear | Undrain | 0.55  | 10.0 | 0.82        | 0.53 | 16  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-38 | 100.00 | 0.14  | Simple shear | Undrain | 0.55  | 10.0 | 0.82        | 0.53 | 92  | No ( $N_L > 30$ )             |
| UT-39 | 50.00  | 0.19  | Simple shear | Undrain | 0.55  | 10.0 | 0.77        | 0.55 | 10  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-40 | 50.00  | 0.18  | Simple shear | Undrain | 0.55  | 10.0 | 0.77        | 0.55 | 14  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-41 | 50.00  | 0.18  | Simple shear | Undrain | 0.55  | 10.0 | 0.62        | 0.60 | 13  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-42 | 50.00  | 0.16  | Simple shear | Undrain | 0.55  | 10.0 | 0.62        | 0.60 | 32  | No ( $N_L > 30$ )             |
| UT-43 | 50.00  | 0.15  | Simple shear | Undrain | 0.55  | 10.0 | 0.38        | 0.68 | 10  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-44 | 50.00  | 0.14  | Simple shear | Undrain | 0.55  | 10.0 | 0.38        | 0.68 | 16  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-45 | 100.00 | 0.12  | Simple shear | Undrain | 0.52  | 20.0 | 0.26        | 0.68 | 8   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-46 | 100.00 | 0.1   | Simple shear | Undrain | 0.52  | 20.0 | 0.26        | 0.68 | 21  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-47 | 100.00 | 0.08  | Simple shear | Undrain | 0.52  | 20.0 | 0.26        | 0.68 | 59  | No ( $N_L > 30$ )             |
| UT-48 | 100.00 | 0.16  | Simple shear | Undrain | 0.52  | 20.0 | 0.50        | 0.58 | 5   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-49 | 100.00 | 0.14  | Simple shear | Undrain | 0.52  | 20.0 | 0.50        | 0.58 | 12  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-50 | 100.00 | 0.12  | Simple shear | Undrain | 0.52  | 20.0 | 0.50        | 0.58 | 16  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-51 | 100.00 | 0.19  | Simple shear | Undrain | 0.52  | 20.0 | 0.666666667 | 0.51 | 7   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-52 | 100.00 | 0.18  | Simple shear | Undrain | 0.52  | 20.0 | 0.666666667 | 0.51 | 14  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-53 | 100.00 | 0.16  | Simple shear | Undrain | 0.52  | 20.0 | 0.666666667 | 0.51 | 19  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-54 | 100.00 | 0.14  | Simple shear | Undrain | 0.52  | 20.0 | 0.666666667 | 0.51 | 34  | No ( $N_L > 30$ )             |
| UT-55 | 50.00  | 0.15  | Simple shear | Undrain | 0.52  | 20.0 | 0.5         | 0.58 | 11  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-56 | 50.00  | 0.14  | Simple shear | Undrain | 0.52  | 20.0 | 0.5         | 0.58 | 27  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-57 | 100.00 | 0.14  | Simple shear | Undrain | 0.49  | 30.0 | 0.279069767 | 0.68 | 4   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-58 | 100.00 | 0.12  | Simple shear | Undrain | 0.49  | 30.0 | 0.279069767 | 0.68 | 7   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-59 | 100.00 | 0.1   | Simple shear | Undrain | 0.49  | 30.0 | 0.279069767 | 0.68 | 15  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-60 | 100.00 | 0.08  | Simple shear | Undrain | 0.49  | 30.0 | 0.279069767 | 0.68 | 46  | No ( $N_L > 30$ )             |
| UT-61 | 100.00 | 0.18  | Simple shear | Undrain | 0.49  | 30.0 | 0.511627907 | 0.58 | 3   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-62 | 100.00 | 0.14  | Simple shear | Undrain | 0.49  | 30.0 | 0.511627907 | 0.58 | 10  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-63 | 50.00  | 0.14  | Simple shear | Undrain | 0.49  | 30.0 | 0.279069767 | 0.68 | 12  | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-64 | 50.00  | 0.12  | Simple shear | Undrain | 0.49  | 30.0 | 0.279069767 | 0.68 | 58  | No ( $N_L > 30$ )             |
| UT-65 | 100.00 | 0.1   | Simple shear | Undrain | 0.45  | 35.0 | 0.574468085 | 0.68 | 54  | No ( $N_L > 30$ )             |
| UT-66 | 100.00 | 0.16  | Simple shear | Undrain | 0.45  | 40.0 | 0.574468085 | 0.68 | 5   | Yes ( $\epsilon_{SA} = 3\%$ ) |
| UT-1  | 100.00 | 0.333 | Triaxial     | Undrain | 0.361 | 0.0  | 0.5         | 0.7  | 6   | Yes ( $r_u = 1$ )             |
| UT-2  | 100.00 | 0.305 | Triaxial     | Undrain | 0.361 | 0.0  | 0.5         | 0.7  | 11  | Yes ( $r_u = 1$ )             |
| UT-3  | 100.00 | 0.285 | Triaxial     | Undrain | 0.361 | 0.0  | 0.5         | 0.7  | 27  | Yes ( $r_u = 1$ )             |
| UT-4  | 100.00 | 0.301 | Triaxial     | Undrain | 0.315 | 10.0 | 0.5         | 0.62 | 10  | Yes ( $r_u = 1$ )             |
| UT-5  | 100.00 | 0.265 | Triaxial     | Undrain | 0.315 | 10.0 | 0.5         | 0.62 | 30  | Yes ( $r_u = 1$ )             |
| UT-6  | 100.00 | 0.250 | Triaxial     | Undrain | 0.315 | 10.0 | 0.5         | 0.62 | 78  | No ( $N_L > 30$ )             |
| UT-7  | 100.00 | 0.314 | Triaxial     | Undrain | 0.294 | 15.0 | 0.5         | 0.58 | 5   | Yes ( $r_u = 1$ )             |
| UT-8  | 100.00 | 0.282 | Triaxial     | Undrain | 0.294 | 15.0 | 0.5         | 0.58 | 12  | Yes ( $r_u = 1$ )             |
| UT-9  | 100.00 | 0.245 | Triaxial     | Undrain | 0.294 | 15.0 | 0.5         | 0.58 | 45  | No ( $N_L > 30$ )             |
| UT-10 | 100.00 | 0.285 | Triaxial     | Undrain | 0.273 | 20.0 | 0.5         | 0.56 | 5   | Yes ( $r_u = 1$ )             |
| UT-11 | 100.00 | 0.235 | Triaxial     | Undrain | 0.273 | 20.0 | 0.5         | 0.56 | 18  | Yes ( $r_u = 1$ )             |
| UT-12 | 100.00 | 0.215 | Triaxial     | Undrain | 0.273 | 20.0 | 0.5         | 0.56 | 45  | No ( $N_L > 30$ )             |
| UT-13 | 100.00 | 0.260 | Triaxial     | Undrain | 0.246 | 25.0 | 0.5         | 0.56 | 5   | Yes ( $r_u = 1$ )             |
| UT-14 | 100.00 | 0.223 | Triaxial     | Undrain | 0.246 | 25.0 | 0.5         | 0.56 | 13  | Yes ( $r_u = 1$ )             |
| UT-15 | 100.00 | 0.199 | Triaxial     | Undrain | 0.246 | 25.0 | 0.5         | 0.56 | 35  | No ( $N_L > 30$ )             |
| UT-16 | 100.00 | 0.230 | Triaxial     | Undrain | 0.224 | 30.0 | 0.5         | 0.56 | 9   | Yes ( $r_u = 1$ )             |
| UT-17 | 100.00 | 0.185 | Triaxial     | Undrain | 0.224 | 30.0 | 0.5         | 0.56 | 35  | No ( $N_L > 30$ )             |
| UT-18 | 100.00 | 0.170 | Triaxial     | Undrain | 0.224 | 30.0 | 0.5         | 0.56 | 76  | No ( $N_L > 30$ )             |
| UT-19 | 100.00 | 0.420 | Triaxial     | Undrain | 0.361 | 0.0  | 0.6         | 0.67 | 5   | Yes ( $r_u = 1$ )             |
| UT-20 | 100.00 | 0.361 | Triaxial     | Undrain | 0.361 | 0.0  | 0.6         | 0.67 | 13  | Yes ( $r_u = 1$ )             |
| UT-21 | 100.00 | 0.319 | Triaxial     | Undrain | 0.361 | 0.0  | 0.6         | 0.67 | 66  | No ( $N_L > 30$ )             |
| UT-22 | 100.00 | 0.339 | Triaxial     | Undrain | 0.315 | 10.0 | 0.382       | 0.67 | 4   | Yes ( $r_u = 1$ )             |
| UT-23 | 100.00 | 0.289 | Triaxial     | Undrain | 0.315 | 10.0 | 0.382       | 0.67 | 15  | Yes ( $r_u = 1$ )             |
| UT-24 | 100.00 | 0.259 | Triaxial     | Undrain | 0.315 | 10.0 | 0.382       | 0.67 | 60  | No ( $N_L > 30$ )             |
| UT-25 | 100.00 | 0.280 | Triaxial     | Undrain | 0.294 | 15.0 | 0.318       | 0.67 | 5   | Yes ( $r_u = 1$ )             |
| UT-26 | 100.00 | 0.249 | Triaxial     | Undrain | 0.294 | 15.0 | 0.318       | 0.67 | 11  | Yes ( $r_u = 1$ )             |
| UT-27 | 100.00 | 0.225 | Triaxial     | Undrain | 0.294 | 15.0 | 0.318       | 0.67 | 41  | No ( $N_L > 30$ )             |
| UT-28 | 100.00 | 0.202 | Triaxial     | Undrain | 0.273 | 20.0 | 0.295       | 0.67 | 9   | Yes ( $r_u = 1$ )             |
| UT-29 | 100.00 | 0.161 | Triaxial     | Undrain | 0.273 | 20.0 | 0.295       | 0.67 | 38  | No ( $N_L > 30$ )             |
| UT-30 | 100.00 | 0.149 | Triaxial     | Undrain | 0.273 | 20.0 | 0.295       | 0.67 | 89  | No ( $N_L > 30$ )             |
| UT-31 | 100.00 | 0.194 | Triaxial     | Undrain | 0.246 | 25.0 | 0.303       | 0.67 | 5   | Yes ( $r_u = 1$ )             |
| UT-32 | 100.00 | 0.164 | Triaxial     | Undrain | 0.246 | 25.0 | 0.303       | 0.67 | 12  | Yes ( $r_u = 1$ )             |
| UT-33 | 100.00 | 0.144 | Triaxial     | Undrain | 0.246 | 25.0 | 0.303       | 0.67 | 35  | No ( $N_L > 30$ )             |
| UT-34 | 100.00 | 0.157 | Triaxial     | Undrain | 0.224 | 30.0 | 0.323       | 0.67 | 8   | Yes ( $r_u = 1$ )             |
| UT-35 | 100.00 | 0.127 | Triaxial     | Undrain | 0.224 | 30.0 | 0.323       | 0.67 | 20  | Yes ( $r_u = 1$ )             |
| UT-36 | 100.00 | 0.117 | Triaxial     | Undrain | 0.224 | 30.0 | 0.323       | 0.67 | 42  | No ( $N_L > 30$ )             |
| UT-37 | 100.00 |       | Triaxial     | Undrain | 0.361 | 0.0  |             |      |     | Yes ( $r_u = 1$ )             |
| UT-38 | 100.00 | 0.220 | Triaxial     | Undrain | 0.315 | 10.0 | 0.19        | 0.76 | 12  | Yes ( $r_u = 1$ )             |
| UT-39 | 100.00 | 0.200 | Triaxial     | Undrain | 0.315 | 10.0 | 0.19        | 0.76 | 20  | Yes ( $r_u = 1$ )             |
| UT-40 | 100.00 | 0.179 | Triaxial     | Undrain | 0.315 | 10.0 | 0.19        | 0.76 | 45  | No ( $N_L > 30$ )             |
| UT-41 | 100.00 | 0.244 | Triaxial     | Undrain | 0.294 | 15.0 | 0.343       | 0.66 | 8   | Yes ( $r_u = 1$ )             |
| UT-42 | 100.00 | 0.223 | Triaxial     | Undrain | 0.294 | 15.0 | 0.343       | 0.66 | 19  | Yes ( $r_u = 1$ )             |
| UT-43 | 100.00 | 0.199 | Triaxial     | Undrain | 0.294 | 15.0 | 0.343       | 0.66 | 66  | No ( $N_L > 30$ )             |
| UT-44 | 100.00 | 0.256 | Triaxial     | Undrain | 0.273 | 20.0 | 0.505       | 0.56 | 10  | Yes ( $r_u = 1$ )             |
| UT-45 | 100.00 | 0.226 | Triaxial     | Undrain | 0.273 | 20.0 | 0.505       | 0.56 | 25  | Yes ( $r_u = 1$ )             |
| UT-46 | 100.00 | 0.205 | Triaxial     | Undrain | 0.273 | 20.0 | 0.505       | 0.56 | 75  | No ( $N_L > 30$ )             |
| UT-47 | 100.00 | 0.408 | Triaxial     | Undrain | 0.246 | 25.0 | 0.662       | 0.46 | 7   | Yes ( $r_u = 1$ )             |
| UT-48 | 100.00 | 0.357 | Triaxial     | Undrain | 0.246 | 25.0 | 0.662       | 0.46 | 21  | Yes ( $r_u = 1$ )             |
| UT-49 | 100.00 | 0.323 | Triaxial     | Undrain | 0.246 | 25.0 | 0.662       | 0.46 |     |                               |

|        |        |       |          |         |        |      |       |      |     |                   |
|--------|--------|-------|----------|---------|--------|------|-------|------|-----|-------------------|
| UT-62  | 100.00 | 0.178 | Triaxial | Undrain | 0.252  | 30.0 | 0.5   | 0.57 | 5   | Yes ( $r_u = 1$ ) |
| UT-63  | 100.00 | 0.131 | Triaxial | Undrain | 0.252  | 30.0 | 0.5   | 0.57 | 21  | Yes ( $r_u = 1$ ) |
| UT-64  | 100.00 | 0.100 | Triaxial | Undrain | 0.252  | 30.0 | 0.5   | 0.57 | 91  | No ( $N_L > 30$ ) |
| UT-65  | 100.00 | 0.386 | Triaxial | Undrain | 0.33   | 0.0  | 0.7   | 0.65 | 13  | Yes ( $r_u = 1$ ) |
| UT-66  | 100.00 | 0.345 | Triaxial | Undrain | 0.33   | 0.0  | 0.7   | 0.65 | 31  | No ( $N_L > 30$ ) |
| UT-67  | 100.00 | 0.310 | Triaxial | Undrain | 0.33   | 0.0  | 0.7   | 0.65 | 106 | No ( $N_L > 30$ ) |
| UT-68  | 100.00 | 0.399 | Triaxial | Undrain | 0.307  | 10.0 | 0.7   | 0.56 | 7   | Yes ( $r_u = 1$ ) |
| UT-69  | 100.00 | 0.365 | Triaxial | Undrain | 0.307  | 10.0 | 0.7   | 0.56 | 14  | Yes ( $r_u = 1$ ) |
| UT-70  | 100.00 | 0.322 | Triaxial | Undrain | 0.307  | 10.0 | 0.7   | 0.56 | 45  | No ( $N_L > 30$ ) |
| UT-71  | 100.00 | 0.310 | Triaxial | Undrain | 0.279  | 20.0 | 0.7   | 0.52 | 3   | Yes ( $r_u = 1$ ) |
| UT-72  | 100.00 | 0.256 | Triaxial | Undrain | 0.279  | 20.0 | 0.7   | 0.52 | 13  | Yes ( $r_u = 1$ ) |
| UT-73  | 100.00 | 0.219 | Triaxial | Undrain | 0.279  | 20.0 | 0.7   | 0.52 | 54  | No ( $N_L > 30$ ) |
| UT-74  | 100.00 | 0.244 | Triaxial | Undrain | 0.252  | 30.0 | 0.7   | 0.5  | 10  | Yes ( $r_u = 1$ ) |
| UT-75  | 100.00 | 0.196 | Triaxial | Undrain | 0.252  | 30.0 | 0.7   | 0.5  | 34  | No ( $N_L > 30$ ) |
| UT-76  | 100.00 | 0.166 | Triaxial | Undrain | 0.252  | 30.0 | 0.7   | 0.5  | 116 | No ( $N_L > 30$ ) |
| UT-77  | 100.00 | 0.300 | Triaxial | Undrain | 0.35   | 0.0  | 0.5   | 0.5  | 6   | Yes ( $r_u = 1$ ) |
| UT-78  | 100.00 | 0.230 | Triaxial | Undrain | 0.35   | 0.0  | 0.5   | 0.5  | 26  | Yes ( $r_u = 1$ ) |
| UT-79  | 100.00 | 0.209 | Triaxial | Undrain | 0.35   | 0.0  | 0.5   | 0.5  | 54  | No ( $N_L > 30$ ) |
| UT-80  | 100.00 | 0.270 | Triaxial | Undrain | 0.209  | 10.0 | 0.5   | 0.48 | 4   | Yes ( $r_u = 1$ ) |
| UT-81  | 100.00 | 0.199 | Triaxial | Undrain | 0.209  | 10.0 | 0.5   | 0.48 | 22  | Yes ( $r_u = 1$ ) |
| UT-82  | 100.00 | 0.160 | Triaxial | Undrain | 0.209  | 10.0 | 0.5   | 0.48 | 79  | No ( $N_L > 30$ ) |
| UT-83  | 100.00 | 0.148 | Triaxial | Undrain | 0.182  | 20.0 | 0.5   | 0.48 | 12  | Yes ( $r_u = 1$ ) |
| UT-84  | 100.00 | 0.120 | Triaxial | Undrain | 0.182  | 20.0 | 0.5   | 0.48 | 26  | Yes ( $r_u = 1$ ) |
| UT-85  | 100.00 | 0.099 | Triaxial | Undrain | 0.182  | 20.0 | 0.5   | 0.48 | 61  | No ( $N_L > 30$ ) |
| UT-86  | 100.00 | 0.170 | Triaxial | Undrain | 0.141  | 30.0 | 0.5   | 0.49 | 3   | Yes ( $r_u = 1$ ) |
| UT-87  | 100.00 | 0.115 | Triaxial | Undrain | 0.141  | 30.0 | 0.5   | 0.49 | 13  | Yes ( $r_u = 1$ ) |
| UT-88  | 100.00 | 0.074 | Triaxial | Undrain | 0.141  | 30.0 | 0.5   | 0.49 | 54  | No ( $N_L > 30$ ) |
| UT-89  | 100.00 | 0.311 | Triaxial | Undrain | 0.35   | 0.0  | 0.7   | 0.46 | 10  | Yes ( $r_u = 1$ ) |
| UT-90  | 100.00 | 0.266 | Triaxial | Undrain | 0.35   | 0.0  | 0.7   | 0.46 | 21  | Yes ( $r_u = 1$ ) |
| UT-91  | 100.00 | 0.225 | Triaxial | Undrain | 0.35   | 0.0  | 0.7   | 0.46 | 71  | No ( $N_L > 30$ ) |
| UT-92  | 100.00 | 0.276 | Triaxial | Undrain | 0.209  | 10.0 | 0.7   | 0.43 | 9   | Yes ( $r_u = 1$ ) |
| UT-93  | 100.00 | 0.242 | Triaxial | Undrain | 0.209  | 10.0 | 0.7   | 0.43 | 19  | Yes ( $r_u = 1$ ) |
| UT-94  | 100.00 | 0.186 | Triaxial | Undrain | 0.209  | 10.0 | 0.7   | 0.43 | 95  | No ( $N_L > 30$ ) |
| UT-95  | 100.00 | 0.227 | Triaxial | Undrain | 0.182  | 20.0 | 0.7   | 0.43 | 4   | Yes ( $r_u = 1$ ) |
| UT-96  | 100.00 | 0.177 | Triaxial | Undrain | 0.182  | 20.0 | 0.7   | 0.43 | 11  | Yes ( $r_u = 1$ ) |
| UT-97  | 100.00 | 0.138 | Triaxial | Undrain | 0.182  | 20.0 | 0.7   | 0.43 | 32  | No ( $N_L > 30$ ) |
| UT-98  | 100.00 | 0.180 | Triaxial | Undrain | 0.141  | 30.0 | 0.7   | 0.42 | 10  | Yes ( $r_u = 1$ ) |
| UT-99  | 100.00 | 0.149 | Triaxial | Undrain | 0.141  | 30.0 | 0.7   | 0.42 | 20  | Yes ( $r_u = 1$ ) |
| UT-100 | 100.00 | 0.110 | Triaxial | Undrain | 0.141  | 30.0 | 0.7   | 0.42 | 90  | No ( $N_L > 30$ ) |
| UT-101 | 100.00 | 0.305 | Triaxial | Undrain | 0.169  | 0.0  | 0.5   | 0.88 | 9   | Yes ( $r_u = 1$ ) |
| UT-102 | 100.00 | 0.263 | Triaxial | Undrain | 0.169  | 0.0  | 0.5   | 0.88 | 19  | Yes ( $r_u = 1$ ) |
| UT-103 | 100.00 | 0.239 | Triaxial | Undrain | 0.169  | 0.0  | 0.5   | 0.88 | 44  | No ( $N_L > 30$ ) |
| UT-104 | 100.00 | 0.266 | Triaxial | Undrain | 0.152  | 10.0 | 0.5   | 0.85 | 4   | Yes ( $r_u = 1$ ) |
| UT-105 | 100.00 | 0.193 | Triaxial | Undrain | 0.152  | 10.0 | 0.5   | 0.85 | 22  | Yes ( $r_u = 1$ ) |
| UT-106 | 100.00 | 0.156 | Triaxial | Undrain | 0.152  | 10.0 | 0.5   | 0.85 | 79  | No ( $N_L > 30$ ) |
| UT-107 | 100.00 | 0.208 | Triaxial | Undrain | 0.144  | 15.0 | 0.5   | 0.85 | 7   | Yes ( $r_u = 1$ ) |
| UT-108 | 100.00 | 0.175 | Triaxial | Undrain | 0.144  | 15.0 | 0.5   | 0.85 | 15  | Yes ( $r_u = 1$ ) |
| UT-109 | 100.00 | 0.149 | Triaxial | Undrain | 0.144  | 15.0 | 0.5   | 0.85 | 40  | No ( $N_L > 30$ ) |
| UT-110 | 100.00 | 0.208 | Triaxial | Undrain | 0.138  | 20.0 | 0.5   | 0.85 | 5   | Yes ( $r_u = 1$ ) |
| UT-111 | 100.00 | 0.175 | Triaxial | Undrain | 0.138  | 20.0 | 0.5   | 0.85 | 11  | Yes ( $r_u = 1$ ) |
| UT-112 | 100.00 | 0.151 | Triaxial | Undrain | 0.138  | 20.0 | 0.5   | 0.85 | 23  | Yes ( $r_u = 1$ ) |
| UT-113 | 100.00 | 0.190 | Triaxial | Undrain | 0.134  | 25.0 | 0.5   | 0.85 | 6   | Yes ( $r_u = 1$ ) |
| UT-114 | 100.00 | 0.160 | Triaxial | Undrain | 0.134  | 25.0 | 0.5   | 0.85 | 13  | Yes ( $r_u = 1$ ) |
| UT-115 | 100.00 | 0.135 | Triaxial | Undrain | 0.134  | 25.0 | 0.5   | 0.85 | 35  | No ( $N_L > 30$ ) |
| UT-116 | 100.00 | 0.160 | Triaxial | Undrain | 0.128  | 30.0 | 0.5   | 0.86 | 11  | Yes ( $r_u = 1$ ) |
| UT-117 | 100.00 | 0.131 | Triaxial | Undrain | 0.128  | 30.0 | 0.5   | 0.86 | 25  | Yes ( $r_u = 1$ ) |
| UT-118 | 100.00 | 0.114 | Triaxial | Undrain | 0.128  | 30.0 | 0.5   | 0.86 | 52  | No ( $N_L > 30$ ) |
| UT-119 | 100.00 | 0.235 | Triaxial | Undrain | 0.169  | 0.0  | 0.27  | 1    | 4   | Yes ( $r_u = 1$ ) |
| UT-120 | 100.00 | 0.190 | Triaxial | Undrain | 0.169  | 0.0  | 0.27  | 1    | 10  | Yes ( $r_u = 1$ ) |
| UT-121 | 100.00 | 0.160 | Triaxial | Undrain | 0.169  | 0.0  | 0.27  | 1    | 31  | Yes ( $r_u = 1$ ) |
| UT-122 | 100.00 | 0.141 | Triaxial | Undrain | 0.152  | 10.0 | 0.247 | 1    | 12  | Yes ( $r_u = 1$ ) |
| UT-123 | 100.00 | 0.116 | Triaxial | Undrain | 0.152  | 10.0 | 0.247 | 1    | 28  | Yes ( $r_u = 1$ ) |
| UT-124 | 100.00 | 0.100 | Triaxial | Undrain | 0.152  | 10.0 | 0.247 | 1    | 77  | No ( $N_L > 30$ ) |
| UT-125 | 100.00 | 0.142 | Triaxial | Undrain | 0.144  | 15.0 | 0.281 | 1    | 10  | Yes ( $r_u = 1$ ) |
| UT-126 | 100.00 | 0.123 | Triaxial | Undrain | 0.144  | 15.0 | 0.281 | 1    | 18  | Yes ( $r_u = 1$ ) |
| UT-127 | 100.00 | 0.102 | Triaxial | Undrain | 0.144  | 15.0 | 0.281 | 1    | 46  | No ( $N_L > 30$ ) |
| UT-128 | 100.00 | 0.117 | Triaxial | Undrain | 0.138  | 20.0 | 0.302 | 1    | 8   | Yes ( $r_u = 1$ ) |
| UT-129 | 100.00 | 0.089 | Triaxial | Undrain | 0.138  | 20.0 | 0.302 | 1    | 25  | Yes ( $r_u = 1$ ) |
| UT-130 | 100.00 | 0.075 | Triaxial | Undrain | 0.138  | 20.0 | 0.302 | 1    | 71  | No ( $N_L > 30$ ) |
| UT-131 | 100.00 | 0.121 | Triaxial | Undrain | 0.134  | 25.0 | 0.317 | 1    | 5   | Yes ( $r_u = 1$ ) |
| UT-132 | 100.00 | 0.101 | Triaxial | Undrain | 0.134  | 25.0 | 0.317 | 1    | 12  | Yes ( $r_u = 1$ ) |
| UT-133 | 100.00 | 0.081 | Triaxial | Undrain | 0.134  | 25.0 | 0.317 | 1    | 35  | No ( $N_L > 30$ ) |
| UT-134 | 100.00 | 0.098 | Triaxial | Undrain | 0.128  | 30.0 | 0.336 | 1    | 10  | Yes ( $r_u = 1$ ) |
| UT-135 | 100.00 | 0.073 | Triaxial | Undrain | 0.128  | 30.0 | 0.336 | 1    | 31  | No ( $N_L > 30$ ) |
| UT-136 | 100.00 | 0.063 | Triaxial | Undrain | 0.128  | 30.0 | 0.336 | 1    | 77  | No ( $N_L > 30$ ) |
| UT-137 | 100.00 |       | Triaxial | Undrain | 0.169  | 0.0  |       |      |     | Yes ( $r_u = 1$ ) |
| UT-138 | 100.00 | 0.161 | Triaxial | Undrain | 0.152  | 10.0 | 0.203 | 1.03 | 3   | Yes ( $r_u = 1$ ) |
| UT-139 | 100.00 | 0.123 | Triaxial | Undrain | 0.152  | 10.0 | 0.203 | 1.03 | 12  | Yes ( $r_u = 1$ ) |
| UT-140 | 100.00 | 0.100 | Triaxial | Undrain | 0.152  | 10.0 | 0.203 | 1.03 | 35  | No ( $N_L > 30$ ) |
| UT-141 | 100.00 | 0.158 | Triaxial | Undrain | 0.144  | 15.0 | 0.411 | 0.91 | 9   | Yes ( $r_u = 1$ ) |
| UT-142 | 100.00 | 0.123 | Triaxial | Undrain | 0.144  | 15.0 | 0.411 | 0.91 | 23  | Yes ( $r_u = 1$ ) |
| UT-143 | 100.00 | 0.101 | Triaxial | Undrain | 0.144  | 15.0 | 0.411 | 0.91 | 88  | No ( $N_L > 30$ ) |
| UT-144 | 100.00 | 0.208 | Triaxial | Undrain | 0.138  | 20.0 | 0.568 | 0.8  | 13  | Yes ( $r_u = 1$ ) |
| UT-145 | 100.00 | 0.179 | Triaxial | Undrain | 0.138  | 20.0 | 0.568 | 0.8  | 31  | No ( $N_L > 30$ ) |
| UT-146 | 100.00 | 0.147 | Triaxial | Undrain | 0.138  | 20.0 | 0.568 | 0.8  | 100 | No ( $N_L > 30$ ) |
| UT-147 | 100.00 | 0.279 | Triaxial | Undrain | 0.134  | 25.0 | 0.7   | 0.69 | 6   | Yes ( $r_u = 1$ ) |
| UT-148 | 100.00 | 0.232 | Triaxial | Undrain | 0.134  | 25.0 | 0.7   | 0.69 | 17  | Yes ( $r_u = 1$ ) |
| UT-149 | 100.00 | 0.200 | Triaxial | Undrain | 0.134  | 25.0 | 0.7   | 0.69 | 68  | No ( $N_L > 30$ ) |
| UT-150 | 100.00 | 0.297 | Triaxial | Undrain | 0.128  | 30.0 | 0.839 | 0.58 | 12  | Yes ( $r_u = 1$ ) |
| UT-151 | 100.00 | 0.267 | Triaxial | Undrain | 0.128  | 30.0 | 0.839 | 0.58 | 21  | Yes ( $r_u = 1$ ) |
| UT-152 | 100.00 | 0.241 | Triaxial | Undrain | 0.128  | 30.0 | 0.839 | 0.58 | 56  | No ( $N_L > 30$ ) |
| UT-153 | 100.00 | 0.280 | Triaxial | Undrain | 0.113  | 0.0  | 0.5   | 1.01 | 6   | Yes ( $r_u = 1$ ) |
| UT-154 | 100.00 | 0.257 | Triaxial | Undrain | 0.113  | 0.0  | 0.5   | 1.01 | 13  | Yes ( $r_u = 1$ ) |
| UT-155 | 100.00 | 0.227 | Triaxial | Undrain | 0.113  | 0.0  | 0.5   | 1.01 | 45  | No ( $N_L > 30$ ) |
| UT-156 | 100.00 | 0.237 | Triaxial | Undrain | 0.104  | 10.0 | 0.5   | 0.91 | 10  | Yes ( $r_u = 1$ ) |
| UT-157 | 100.00 | 0.211 | Triaxial | Undrain | 0.104  | 10.0 | 0.5   | 0.91 | 31  | No ( $N_L > 30$ ) |
| UT-158 | 100.00 | 0.196 | Triaxial | Undrain | 0.104  | 10.0 | 0.5   | 0.91 | 104 | No ( $N_L > 30$ ) |
| UT-159 | 100.00 | 0.257 | Triaxial | Undrain | 0.0994 | 15.0 | 0.5   | 0.87 | 4   | Yes ( $r_u = 1$ ) |
| UT-160 | 100.00 | 0.224 | Triaxial | Undrain | 0.0994 | 15.0 | 0.5   | 0.87 | 11  | Yes ( $r_u = 1$ ) |
| UT-161 | 100.00 | 0.201 | Triaxial | Undrain | 0.0994 | 15.0 | 0.5   | 0.87 | 34  | No ( $N_L > 30$ ) |
| UT-162 | 100.00 | 0.213 | Triaxial | Undrain | 0.0961 | 20.0 | 0.5   | 0.83 | 15  | Yes ( $r_u = 1$ ) |
| UT-163 | 100.00 | 0.194 | Triaxial | Undrain | 0.0961 | 20.0 | 0.5   | 0.83 | 35  | No ( $N_L > 30$ ) |
| UT-164 | 100.00 | 0.175 | Triaxial | Undrain | 0.0961 | 20.0 | 0.5   | 0.83 | 123 | No ( $N_L > 30$ ) |
| UT-165 | 100.00 | 0.261 | Triaxial | Undrain | 0.093  | 25.0 | 0.5   | 0.8  | 3   | Yes ( $r_u = 1$ ) |
| UT-166 | 100.00 | 0.222 | Triaxial | Undrain | 0.093  | 25.0 | 0.5   | 0.8  | 8   | Yes ( $r_u = 1$ ) |
| UT-167 | 100.00 | 0.198 | Triaxial | Undrain | 0.093  | 25.0 | 0.5   | 0.8  | 23  | Yes ( $r_u = 1$ ) |
| UT-168 | 100.00 | 0.234 | Triaxial | Undrain | 0.0909 | 30.0 | 0.5   | 0.79 | 5   | Yes ( $r_u = 1$ ) |
| UT-169 | 100.00 | 0.205 | Triaxial | Undrain | 0.0909 | 30.0 | 0.5   | 0.79 | 14  | Yes ( $r_u = 1$ ) |
| UT-170 | 100.00 | 0.181 | Triaxial | Undrain | 0.0909 | 30.0 | 0.5   | 0.79 | 41  | No ( $N_L > 30$ ) |
| UT-171 | 100.00 | 0.380 | Triaxial | Undrain | 0.113  | 0.0  | 0.769 | 0.86 | 3   | Yes ( $r_u = 1$ ) |
| UT-172 | 100.00 | 0.321 | Triaxial | Undrain | 0.113  | 0.0  | 0.769 | 0.86 | 14  | Yes ( $r_u = 1$ ) |
| UT-173 | 100.00 | 0.291 | Triaxial | Undrain | 0.113  | 0.0  | 0.769 | 0.86 | 55  | No ( $N_L > 30$ ) |
| UT-174 | 100.00 | 0.285 | Triaxial | Undrain | 0.104  |      |       |      |     |                   |

|        |        |       |            |         |        |       |             |          |            |                   |                                                                                  |
|--------|--------|-------|------------|---------|--------|-------|-------------|----------|------------|-------------------|----------------------------------------------------------------------------------|
| UT-186 | 100.00 | 0.205 | Triaxial   | Undrain | 0.0909 | 30.0  | 0.415       | 0.86     | 5          | Yes ( $r_u = 1$ ) | No ( $N_L > 30$ )<br>Yes ( $r_u = 1$ )<br>Yes ( $r_u = 1$ )<br>No ( $N_L > 30$ ) |
| UT-187 | 100.00 | 0.168 | Triaxial   | Undrain | 0.0909 | 30.0  | 0.415       | 0.86     | 19         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-188 | 100.00 | 0.143 | Triaxial   | Undrain | 0.0909 | 30.0  | 0.415       | 0.86     | 96         |                   |                                                                                  |
| UT-189 | 100.00 | 0.375 | Triaxial   | Undrain | 0.113  | 0.0   | 0.25        | 1.15     | 4          |                   |                                                                                  |
| UT-190 | 100.00 | 0.325 | Triaxial   | Undrain | 0.113  | 0.0   | 0.25        | 1.15     | 15         |                   |                                                                                  |
| UT-191 | 100.00 | 0.300 | Triaxial   | Undrain | 0.113  | 0.0   | 0.25        | 1.15     | 43         |                   |                                                                                  |
| UT-192 | 100.00 | 0.254 | Triaxial   | Undrain | 0.104  | 10.0  | 0.46        | 0.94     | 7          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-193 | 100.00 | 0.224 | Triaxial   | Undrain | 0.104  | 10.0  | 0.46        | 0.94     | 20         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-194 | 100.00 | 0.204 | Triaxial   | Undrain | 0.104  | 10.0  | 0.46        | 0.94     | 68         | No ( $N_L > 30$ ) |                                                                                  |
| UT-195 | 100.00 | 0.296 | Triaxial   | Undrain | 0.0994 | 15.0  | 0.559       | 0.83     | 4          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-196 | 100.00 | 0.253 | Triaxial   | Undrain | 0.0994 | 15.0  | 0.559       | 0.83     | 15         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-197 | 100.00 | 0.225 | Triaxial   | Undrain | 0.0994 | 15.0  | 0.559       | 0.83     | 65         | No ( $N_L > 30$ ) |                                                                                  |
| UT-198 | 100.00 | 0.302 | Triaxial   | Undrain | 0.0961 | 20.0  | 0.634       | 0.72     | 10         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-199 | 100.00 | 0.271 | Triaxial   | Undrain | 0.0961 | 20.0  | 0.634       | 0.72     | 26         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-200 | 100.00 | 0.251 | Triaxial   | Undrain | 0.0961 | 20.0  | 0.634       | 0.72     | 82         | No ( $N_L > 30$ ) |                                                                                  |
| UT-201 | 100.00 | 0.400 | Triaxial   | Undrain | 0.093  | 25.0  | 0.724       | 0.61     | 4          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-202 | 100.00 | 0.367 | Triaxial   | Undrain | 0.093  | 25.0  | 0.724       | 0.61     | 9          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-203 | 100.00 | 0.339 | Triaxial   | Undrain | 0.093  | 25.0  | 0.724       | 0.61     | 29         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-204 | 100.00 | 0.444 | Triaxial   | Undrain | 0.0909 | 30.0  | 0.834       | 0.51     | 7          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-205 | 100.00 | 0.400 | Triaxial   | Undrain | 0.0909 | 30.0  | 0.834       | 0.51     | 21         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-206 | 100.00 | 0.375 | Triaxial   | Undrain | 0.0909 | 30.0  | 0.834       | 0.51     | 51         | No ( $N_L > 30$ ) |                                                                                  |
| UT-207 | 100.00 | 0.230 | Triaxial   | Undrain | 1.265  | 0.0   | 0.5         | 0.69     | 6          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-208 | 100.00 | 0.202 | Triaxial   | Undrain | 1.265  | 0.0   | 0.5         | 0.69     | 26         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-209 | 100.00 | 0.189 | Triaxial   | Undrain | 1.265  | 0.0   | 0.5         | 0.69     | 76         | No ( $N_L > 30$ ) |                                                                                  |
| UT-210 | 100.00 | 0.228 | Triaxial   | Undrain | 1.173  | 10.0  | 0.5         | 0.59     | 5          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-211 | 100.00 | 0.206 | Triaxial   | Undrain | 1.173  | 10.0  | 0.5         | 0.59     | 15         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-212 | 100.00 | 0.189 | Triaxial   | Undrain | 1.173  | 10.0  | 0.5         | 0.59     | 45         | No ( $N_L > 30$ ) |                                                                                  |
| UT-213 | 100.00 | 0.235 | Triaxial   | Undrain | 1.078  | 20.0  | 0.5         | 0.53     | 3          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-214 | 100.00 | 0.206 | Triaxial   | Undrain | 1.078  | 20.0  | 0.5         | 0.53     | 9          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-215 | 100.00 | 0.173 | Triaxial   | Undrain | 1.078  | 20.0  | 0.5         | 0.53     | 67         | No ( $N_L > 30$ ) |                                                                                  |
| UT-216 | 100.00 | 0.200 | Triaxial   | Undrain | 0.967  | 30.0  | 0.5         | 0.52     | 12         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-217 | 100.00 | 0.185 | Triaxial   | Undrain | 0.967  | 30.0  | 0.5         | 0.52     | 27         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-218 | 100.00 | 0.164 | Triaxial   | Undrain | 0.967  | 30.0  | 0.5         | 0.52     | 101        | No ( $N_L > 30$ ) |                                                                                  |
| UT-219 | 100.00 | 0.251 | Triaxial   | Undrain | 1.265  | 0.0   | 0.7         | 0.63     | 5          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-220 | 100.00 | 0.226 | Triaxial   | Undrain | 1.265  | 0.0   | 0.7         | 0.63     | 15         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-221 | 100.00 | 0.196 | Triaxial   | Undrain | 1.265  | 0.0   | 0.7         | 0.63     | 126        | No ( $N_L > 30$ ) |                                                                                  |
| UT-222 | 100.00 | 0.260 | Triaxial   | Undrain | 1.173  | 10.0  | 0.7         | 0.52     | 3          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-223 | 100.00 | 0.232 | Triaxial   | Undrain | 1.173  | 10.0  | 0.7         | 0.52     | 9          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-224 | 100.00 | 0.220 | Triaxial   | Undrain | 1.173  | 10.0  | 0.7         | 0.52     | 19         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-225 | 100.00 | 0.223 | Triaxial   | Undrain | 1.078  | 20.0  | 0.7         | 0.47     | 10         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-226 | 100.00 | 0.211 | Triaxial   | Undrain | 1.078  | 20.0  | 0.7         | 0.47     | 20         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-227 | 100.00 | 0.195 | Triaxial   | Undrain | 1.078  | 20.0  | 0.7         | 0.47     | 80         | No ( $N_L > 30$ ) |                                                                                  |
| UT-228 | 100.00 | 0.222 | Triaxial   | Undrain | 0.967  | 30.0  | 0.7         | 0.45     | 7          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-229 | 100.00 | 0.198 | Triaxial   | Undrain | 0.967  | 30.0  | 0.7         | 0.45     | 25         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-230 | 100.00 | 0.177 | Triaxial   | Undrain | 0.967  | 30.0  | 0.7         | 0.45     | 95         | No ( $N_L > 30$ ) |                                                                                  |
| UT-1   | 100.00 | 0.351 | Simulation | Undrain | 0.11   | 0.0   | 0.68        | 0.68     | 6          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-2   | 100.00 | 0.250 | Simulation | Undrain | 0.11   | 0.0   | 0.68        | 0.68     | 8          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-3   | 100.00 | 0.199 | Simulation | Undrain | 0.11   | 0.0   | 0.68        | 0.68     | 12         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-4   | 100.00 | 0.350 | Simulation | Undrain | 0.11   | 15.0  | 0.68        | 0.68     | 5          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-5   | 100.00 | 0.250 | Simulation | Undrain | 0.11   | 15.0  | 0.68        | 0.68     | 7          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-6   | 100.00 | 0.200 | Simulation | Undrain | 0.11   | 15.0  | 0.68        | 0.68     | 9          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-7   | 100.00 | 0.350 | Simulation | Undrain | 0.095  | 25.0  | 0.68        | 0.68     | 4          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-8   | 100.00 | 0.250 | Simulation | Undrain | 0.095  | 25.0  | 0.68        | 0.68     | 6          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-9   | 100.00 | 0.200 | Simulation | Undrain | 0.095  | 25.0  | 0.68        | 0.68     | 8          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-10  | 100.00 | 0.350 | Simulation | Undrain | 0.09   | 30.0  | 0.68        | 0.68     | 4          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-11  | 100.00 | 0.249 | Simulation | Undrain | 0.09   | 30.0  | 0.68        | 0.68     | 5          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-12  | 100.00 | 0.199 | Simulation | Undrain | 0.09   | 30.0  | 0.68        | 0.68     | 6          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-13  | 100.00 | 0.350 | Simulation | Undrain | 0.082  | 40.0  | 0.68        | 0.68     | 5          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-14  | 100.00 | 0.250 | Simulation | Undrain | 0.082  | 40.0  | 0.68        | 0.68     | 6          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-15  | 100.00 | 0.199 | Simulation | Undrain | 0.082  | 40.0  | 0.68        | 0.68     | 8          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-16  | 100.00 | 0.350 | Simulation | Undrain | 0.06   | 60.0  | 0.68        | 0.68     | 6          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-17  | 100.00 | 0.249 | Simulation | Undrain | 0.06   | 60.0  | 0.68        | 0.68     | 8          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-18  | 100.00 | 0.200 | Simulation | Undrain | 0.06   | 60.0  | 0.68        | 0.68     | 10         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-19  | 100.00 | 0.349 | Simulation | Undrain | 0.048  | 80.0  | 0.68        | 0.68     | 8          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-20  | 100.00 | 0.250 | Simulation | Undrain | 0.048  | 80.0  | 0.68        | 0.68     | 9          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-21  | 100.00 | 0.200 | Simulation | Undrain | 0.048  | 80.0  | 0.68        | 0.68     | 11         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-22  | 100.00 | 0.350 | Simulation | Undrain | 0.04   | 100.0 | 0.68        | 0.68     | 9          | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-23  | 100.00 | 0.250 | Simulation | Undrain | 0.04   | 100.0 | 0.68        | 0.68     | 10         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-24  | 100.00 | 0.199 | Simulation | Undrain | 0.04   | 100.0 | 0.68        | 0.68     | 12         | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-1   | 100.00 | 0.154 | Triaxial   | Undrain | 0.375  | 0.0   | 0.923076923 | 0.44     | 544.60724  | No ( $N_L > 30$ ) |                                                                                  |
| UT-2   | 100.00 | 0.154 | Triaxial   | Undrain |        | 5.0   | 0.633027523 | 0.44     | 173.08419  | No ( $N_L > 30$ ) |                                                                                  |
| UT-3   | 100.00 | 0.154 | Triaxial   | Undrain |        | 10.0  | 0.547550432 | 0.44     | 19.25302   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-4   | 100.00 | 0.154 | Triaxial   | Undrain |        | 15.0  | 0.493150685 | 0.44     | 10.02391   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-5   | 100.00 | 0.154 | Triaxial   | Undrain |        | 20.0  | 0.427792916 | 0.44     | 11.10839   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-6   | 100.00 | 0.154 | Triaxial   | Undrain |        | 25.0  | 0.603211009 | 0.44     | 20.04053   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-7   | 100.00 | 0.154 | Triaxial   | Undrain |        | 30.0  | 0.628888889 | 0.44     | 21.17622   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-8   | 100.00 | 0.154 | Triaxial   | Undrain |        | 35.0  | 0.702479339 | 0.44     | 48.8365    | No ( $N_L > 30$ ) |                                                                                  |
| UT-9   | 100.00 | 0.154 | Triaxial   | Undrain |        | 40.0  | 0.790352505 | 0.44     | 56.82995   | No ( $N_L > 30$ ) |                                                                                  |
| UT-10  | 100.00 | 0.154 | Triaxial   | Undrain |        | 50.0  | 0.888888889 | 0.44     | 99.98936   | No ( $N_L > 30$ ) |                                                                                  |
| UT-11  | 100.00 | 0.154 | Triaxial   | Undrain |        | 60.0  | 0.90784044  | 0.44     | 143.07324  | No ( $N_L > 30$ ) |                                                                                  |
| UT-12  | 100.00 | 0.128 | Triaxial   | Undrain | 0.375  | 0.0   | 0.53        | 0.5422   | 99.01092   | No ( $N_L > 30$ ) |                                                                                  |
| UT-13  | 100.00 | 0.128 | Triaxial   | Undrain |        | 5.0   | 0.53        | 0.47369  | 248.27172  | No ( $N_L > 30$ ) |                                                                                  |
| UT-14  | 100.00 | 0.128 | Triaxial   | Undrain |        | 10.0  | 0.53        | 0.44609  | 41.09204   | No ( $N_L > 30$ ) |                                                                                  |
| UT-15  | 100.00 | 0.128 | Triaxial   | Undrain |        | 15.0  | 0.53        | 0.42655  | 65.48086   | No ( $N_L > 30$ ) |                                                                                  |
| UT-16  | 100.00 | 0.128 | Triaxial   | Undrain |        | 20.0  | 0.53        | 0.40249  | 22.54572   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-17  | 100.00 | 0.128 | Triaxial   | Undrain |        | 25.0  | 0.53        | 0.47192  | 13.56679   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-18  | 100.00 | 0.128 | Triaxial   | Undrain |        | 30.0  | 0.53        | 0.4845   | 5.85964    | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-19  | 100.00 | 0.128 | Triaxial   | Undrain |        | 35.0  | 0.53        | 0.52348  | 7.74644    | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-20  | 100.00 | 0.128 | Triaxial   | Undrain |        | 40.0  | 0.53        | 0.58033  | 10.81517   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-21  | 100.00 | 0.128 | Triaxial   | Undrain |        | 45.0  | 0.53        | 0.6308   | 7.74644    | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-22  | 100.00 | 0.128 | Triaxial   | Undrain |        | 50.0  | 0.53        | 0.6661   | 11.71308   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-23  | 100.00 | 0.128 | Triaxial   | Undrain |        | 55.0  | 0.53        | 0.71469  | 18.7042    | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-24  | 100.00 | 0.128 | Triaxial   | Undrain |        | 60.0  | 0.53        | 0.915302 | 12.71218   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-25  | 100.00 | 0.13  | Triaxial   | Undrain |        | 100.0 | 0.53        | 1.04264  | 12.52678   | Yes ( $r_u = 1$ ) |                                                                                  |
| UT-26  | 100.00 | 0.128 | Triaxial   | Undrain | 0.375  | 0.0   | 0.2712344   | 0.609479 | 20.84841</ |                   |                                                                                  |

|       |        |       |              |         |        |       |             |         |      |                                          |
|-------|--------|-------|--------------|---------|--------|-------|-------------|---------|------|------------------------------------------|
| UT-21 | 98.00  | 0.144 | Triaxial     | Undrain | 0.197  | 0.0   | 0.34        | 0.94598 | 2    | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-22 | 98.00  | 0.124 | Triaxial     | Undrain | 0.197  | 0.0   | 0.36        | 0.93792 | 16   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-23 | 98.00  | 0.120 | Triaxial     | Undrain | 0.19   | 5.0   | 0.28        | 0.97532 | 7    | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-24 | 98.00  | 0.096 | Triaxial     | Undrain | 0.19   | 5.0   | 0.26        | 0.98594 | 19   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-25 | 98.00  | 0.14  | Undrain      | Undrain | 0.19   | 5.0   | 0.3         | 0.9647  | 3.70 | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-26 | 98.00  | 0.088 | Triaxial     | Undrain | 0.163  | 20.0  | 0.36        | 1.03348 | 19   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-27 | 98.00  | 0.118 | Triaxial     | Undrain | 0.163  | 20.0  | 0.37        | 1.02541 | 3    | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-28 | 98.00  | 0.07  | Triaxial     | Undrain | 0.163  | 20.0  | 0.41        | 0.99313 | 120  | No ( $N_v > 30$ )                        |
| UT-29 | 98.00  | 0.313 | Triaxial     | Undrain | 0.197  | 0.0   | 0.71        | 0.79687 | 4    | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-30 | 98.00  | 0.299 | Triaxial     | Undrain | 0.197  | 0.0   | 0.7         | 0.8009  | 4    | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-31 | 98.00  | 0.259 | Triaxial     | Undrain | 0.197  | 0.0   | 0.69        | 0.80493 | 4    | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-32 | 98.00  | 0.198 | Triaxial     | Undrain | 0.197  | 0.0   | 0.71        | 0.79687 | 16   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-33 | 98.00  | 0.197 | Triaxial     | Undrain | 0.19   | 5.0   | 0.67        | 0.76823 | 2.6  | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-34 | 98.00  | 0.16  | Triaxial     | Undrain | 0.19   | 5.0   | 0.69        | 0.75761 | 14   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-35 | 98.00  |       | Triaxial     | Undrain | 0.19   | 5.0   |             |         |      |                                          |
| UT-36 | 98.00  | 0.218 | Triaxial     | Undrain | 0.19   | 5.0   | 0.72        | 0.74168 | 5.6  | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-37 | 98.00  | 0.168 | Triaxial     | Undrain | 0.183  | 10.0  | 0.62        | 0.7795  | 0.7  | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-38 | 98.00  | 0.12  | Triaxial     | Undrain | 0.183  | 10.0  | 0.67        | 0.74825 | 4.8  | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-39 | 98.00  | 0.109 | Triaxial     | Undrain | 0.183  | 10.0  | 0.65        | 0.76075 | 13   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-40 | 98.00  | 0.167 | Triaxial     | Undrain | 0.163  | 20.0  | 0.76        | 0.71068 | 0.8  | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-41 | 98.00  | 0.111 | Triaxial     | Undrain | 0.163  | 20.0  | 0.7         | 0.7591  | 5.7  | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-42 | 98.00  | 0.094 | Triaxial     | Undrain | 0.163  | 20.0  | 0.76        | 0.71068 | 29   | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-1  | 105.00 | 0.119 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 86   | No ( $N_v > 30$ )                        |
| UT-2  | 105.00 | 0.119 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 88   | No ( $N_v > 30$ )                        |
| UT-3  | 105.00 | 0.119 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 83   | No ( $N_v > 30$ )                        |
| UT-4  | 105.00 | 0.143 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 39   | No ( $N_v > 30$ )                        |
| UT-5  | 105.00 | 0.143 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 45   | No ( $N_v > 30$ )                        |
| UT-6  | 105.00 | 0.143 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 44   | No ( $N_v > 30$ )                        |
| UT-7  | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 12   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-8  | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 10   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-9  | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.35        | 1.6     | 11   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-10 | 105.00 | 0.143 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 58   | No ( $N_v > 30$ )                        |
| UT-11 | 105.00 | 0.143 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 62   | No ( $N_v > 30$ )                        |
| UT-12 | 105.00 | 0.143 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 54   | No ( $N_v > 30$ )                        |
| UT-13 | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 29   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-14 | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 32   | No ( $N_v > 30$ )                        |
| UT-15 | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 33   | No ( $N_v > 30$ )                        |
| UT-16 | 105.00 | 0.190 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 12   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-17 | 105.00 | 0.190 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 11   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-18 | 105.00 | 0.190 | Ring shear   | Undrain | 0.012  | 100.0 | 0.45        | 1.45    | 9    | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-19 | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 58   | No ( $N_v > 30$ )                        |
| UT-20 | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 66   | No ( $N_v > 30$ )                        |
| UT-21 | 105.00 | 0.171 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 62   | No ( $N_v > 30$ )                        |
| UT-22 | 105.00 | 0.190 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 24   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-23 | 105.00 | 0.190 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 21   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-24 | 105.00 | 0.190 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 20   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-25 | 105.00 | 0.21  | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 12   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-26 | 105.00 | 0.214 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 15   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-27 | 105.00 | 0.214 | Ring shear   | Undrain | 0.012  | 100.0 | 0.55        | 1.31    | 14   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-28 | 105.00 | 0.095 | Ring shear   | Undrain | 0.029  | 75.0  | 0.14        | 1.36    | 68   | No ( $N_v > 30$ )                        |
| UT-29 | 105.00 | 0.119 | Ring shear   | Undrain | 0.029  | 75.0  | 0.14        | 1.36    | 23   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-30 | 105.00 | 0.143 | Ring shear   | Undrain | 0.029  | 75.0  | 0.14        | 1.36    | 16   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-31 | 105.00 | 0.171 | Ring shear   | Undrain | 0.029  | 75.0  | 0.14        | 1.36    | 6    | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-32 | 105.00 | 0.095 | Ring shear   | Undrain | 0.029  | 75.0  | 0.31        | 1.2     | 75   | No ( $N_v > 30$ )                        |
| UT-33 | 105.00 | 0.119 | Ring shear   | Undrain | 0.029  | 75.0  | 0.31        | 1.2     | 45   | No ( $N_v > 30$ )                        |
| UT-34 | 105.00 | 0.143 | Ring shear   | Undrain | 0.029  | 75.0  | 0.31        | 1.2     | 27   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-35 | 105.00 | 0.171 | Ring shear   | Undrain | 0.029  | 75.0  | 0.31        | 1.2     | 8    | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-36 | 105.00 | 0.119 | Ring shear   | Undrain | 0.029  | 75.0  | 0.37        | 1.15    | 97   | No ( $N_v > 30$ )                        |
| UT-37 | 105.00 | 0.143 | Ring shear   | Undrain | 0.029  | 75.0  | 0.37        | 1.15    | 84   | No ( $N_v > 30$ )                        |
| UT-38 | 105.00 | 0.171 | Ring shear   | Undrain | 0.029  | 75.0  | 0.37        | 1.15    | 31   | No ( $N_v > 30$ )                        |
| UT-39 | 105.00 | 0.19  | Ring shear   | Undrain | 0.0029 | 75.0  | 0.37        | 1.15    | 9    | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-40 | 105.00 | 0.095 | Ring shear   | Undrain | 0.07   | 50.0  | 0.13        | 1.06    | 102  | No ( $N_v > 30$ )                        |
| UT-41 | 105.00 | 0.119 | Ring shear   | Undrain | 0.07   | 50.0  | 0.13        | 1.06    | 80   | No ( $N_v > 30$ )                        |
| UT-42 | 105.00 | 0.143 | Ring shear   | Undrain | 0.07   | 50.0  | 0.13        | 1.06    | 29   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-43 | 105.00 | 0.171 | Ring shear   | Undrain | 0.07   | 50.0  | 0.13        | 1.06    | 12   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-44 | 105.00 | 0.119 | Ring shear   | Undrain | 0.07   | 50.0  | 0.25        | 0.98    | 85   | No ( $N_v > 30$ )                        |
| UT-45 | 105.00 | 0.143 | Ring shear   | Undrain | 0.07   | 50.0  | 0.25        | 0.98    | 36   | No ( $N_v > 30$ )                        |
| UT-46 | 105.00 | 0.171 | Ring shear   | Undrain | 0.07   | 50.0  | 0.25        | 0.98    | 17   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-47 | 105.00 | 0.19  | Ring shear   | Undrain | 0.07   | 50.0  | 0.25        | 0.98    | 10   | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-48 | 105.00 | 0.143 | Ring shear   | Undrain | 0.07   | 50.0  | 0.38        | 0.89    | 73   | No ( $N_v > 30$ )                        |
| UT-49 | 105.00 | 0.171 | Ring shear   | Undrain | 0.07   | 50.0  | 0.38        | 0.89    | 63   | No ( $N_v > 30$ )                        |
| UT-50 | 105.00 | 0.19  | Ring shear   | Undrain | 0.07   | 50.0  | 0.38        | 0.89    | 33   | No ( $N_v > 30$ )                        |
| UT-51 | 105.00 | 0.214 | Ring shear   | Undrain | 0.07   | 50.0  | 0.38        | 0.89    | 6    | Yes ( $r_v > 0.6, \epsilon_{DA} = 5\%$ ) |
| UT-1  | 200.00 | 0.250 | Triaxial     | Undrain | 1.8    | 18.0  | 0.23        | 842     |      | No ( $N_v > 30$ )                        |
| UT-2  | 200.00 | 0.150 | Triaxial     | Undrain | 1.8    | 18.0  | 0.25        | 596     |      | No ( $N_v > 30$ )                        |
| UT-3  | 200.00 | 0.100 | Triaxial     | Undrain | 1.8    | 18.0  | 0.25        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-4  | 200.00 | 0.250 | Triaxial     | Undrain | 1.8    | 18.0  | 0.27        | 42      |      | No ( $N_v > 30$ )                        |
| UT-5  | 200.00 | 0.075 | Triaxial     | Undrain | 1.8    | 18.0  | 0.28        | 2194    |      | No ( $N_v > 30$ )                        |
| UT-6  | 200.00 | 0.050 | Triaxial     | Undrain | 1.8    | 18.0  | 0.28        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-7  | 200.00 | 0.250 | Triaxial     | Undrain | 0.548  | 28.0  | 0.32        | 95      |      | No ( $N_v > 30$ )                        |
| UT-8  | 200.00 | 0.100 | Triaxial     | Undrain | 0.548  | 28.0  | 0.29        | 132     |      | No ( $N_v > 30$ )                        |
| UT-9  | 200.00 | 0.075 | Triaxial     | Undrain | 0.548  | 28.0  | 0.29        | 350     |      | No ( $N_v > 30$ )                        |
| UT-10 | 200.00 | 0.050 | Triaxial     | Undrain | 0.548  | 28.0  | 0.29        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-11 | 200.00 | 0.250 | Triaxial     | Undrain | 0.548  | 28.0  | 0.32        | 3       |      | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-12 | 200.00 | 0.150 | Triaxial     | Undrain | 0.548  | 28.0  | 0.32        | 120     |      | No ( $N_v > 30$ )                        |
| UT-13 | 200.00 | 0.100 | Triaxial     | Undrain | 0.548  | 28.0  | 0.34        | 86      |      | No ( $N_v > 30$ )                        |
| UT-14 | 200.00 | 0.050 | Triaxial     | Undrain | 0.548  | 28.0  | 0.34        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-15 | 200.00 | 0.250 | Triaxial     | Undrain | 0.232  | 40.0  | 0.36        | 132     |      | No ( $N_v > 30$ )                        |
| UT-16 | 200.00 | 0.075 | Triaxial     | Undrain | 0.232  | 40.0  | 0.31        | 374     |      | No ( $N_v > 30$ )                        |
| UT-17 | 200.00 | 0.050 | Triaxial     | Undrain | 0.232  | 40.0  | 0.33        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-18 | 200.00 | 0.250 | Triaxial     | Undrain | 0.232  | 40.0  | 0.41        | 3       |      | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-19 | 200.00 | 0.150 | Triaxial     | Undrain | 0.232  | 40.0  | 0.33        | 195     |      | No ( $N_v > 30$ )                        |
| UT-20 | 200.00 | 0.150 | Triaxial     | Undrain | 0.232  | 40.0  | 0.36        | 58      |      | No ( $N_v > 30$ )                        |
| UT-21 | 200.00 | 0.075 | Triaxial     | Undrain | 0.232  | 40.0  | 0.36        | 1100    |      | No ( $N_v > 30$ )                        |
| UT-22 | 200.00 | 0.050 | Triaxial     | Undrain | 0.232  | 40.0  | 0.39        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-23 | 200.00 | 0.250 | Triaxial     | Undrain | 0.033  | 60.0  | 0.42        | 19      |      | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-24 | 200.00 | 0.150 | Triaxial     | Undrain | 0.033  | 60.0  | 0.37        | 224     |      | No ( $N_v > 30$ )                        |
| UT-25 | 200.00 | 0.08  | Triaxial     | Undrain | 0.033  | 60.0  | 0.41        | 2566    |      | No ( $N_v > 30$ )                        |
| UT-26 | 200.00 | 0.05  | Triaxial     | Undrain | 0.033  | 60.0  | 0.41        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-27 | 200.00 | 0.25  | Triaxial     | Undrain | 0.033  | 60.0  | 0.41        | 32      |      | No ( $N_v > 30$ )                        |
| UT-28 | 200.00 | 0.25  | Triaxial     | Undrain | 0.033  | 60.0  | 0.46        | 12      |      | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-29 | 200.00 | 0.15  | Triaxial     | Undrain | 0.033  | 60.0  | 0.44        | 24      |      | Yes ( $\epsilon_{DA} = 5\%$ )            |
| UT-30 | 200.00 | 0.15  | Triaxial     | Undrain | 0.033  | 60.0  | 0.41        | 212     |      | No ( $N_v > 30$ )                        |
| UT-31 | 200.00 | 0.075 | Triaxial     | Undrain | 0.033  | 60.0  | 0.41        | 598     |      | No ( $N_v > 30$ )                        |
| UT-32 | 200.00 | 0.05  | Triaxial     | Undrain | 0.033  | 60.0  | 0.41        | 3000    |      | No ( $N_v > 30$ )                        |
| UT-1  | 100.00 | 0.230 | Simple shear | Undrain | 0.56   | 0.0   | 0.714285714 | 0.68    | 3    | Yes ( $\nu_{DA} = 3.75\%$ )              |
| UT-2  | 100.00 | 0.200 | Simple shear | Undrain | 0.56   | 0.0   | 0.714285714 | 0.68    | 9    | Yes ( $\nu_{DA} = 3.75\%$ )              |
| UT-3  | 100.00 | 0.160 | Simple shear | Undrain | 0.56   | 0.0   | 0.714285714 | 0.68    | 19   | Yes ( $\nu_{DA} = 3.75\%$ )              |
| UT-4  | 100.00 | 0.140 | Simple shear | Undrain | 0.56   | 0.0   | 0.714285714 | 0.68    | 76   | No ( $N_v > 30$ )                        |
| UT-5  | 100.00 | 0.100 |              |         |        |       |             |         |      |                                          |

|       |        |       |              |         |         |       |             |      |     |                             |
|-------|--------|-------|--------------|---------|---------|-------|-------------|------|-----|-----------------------------|
| UT-20 | 100.00 | 0.160 | Simple shear | Undrain | 0.56    | 5.0   | 0.35483871  | 0.73 | 4   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-21 | 100.00 | 0.140 | Simple shear | Undrain | 0.56    | 5.0   | 0.516129032 | 0.68 | 22  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-22 | 100.00 | 0.160 | Simple shear | Undrain | 0.56    | 5.0   | 0.516129032 | 0.68 | 13  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-23 | 100.00 | 0.220 | Simple shear | Undrain | 0.56    | 5.0   | 0.516129032 | 0.68 | 2   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-24 | 100.00 | 0.140 | Simple shear | Undrain | 0.56    | 5.0   | 0.741935484 | 0.61 | 34  | No ( $N_L > 30$ )           |
| UT-25 | 100.00 | 0.16  | Simple shear | Undrain | 0.56    | 5.0   | 0.741935484 | 0.61 | 18  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-26 | 100.00 | 0.2   | Simple shear | Undrain | 0.56    | 5.0   | 0.741935484 | 0.61 | 8   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-27 | 100.00 | 0.22  | Simple shear | Undrain | 0.56    | 5.0   | 0.741935484 | 0.61 | 6   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-28 | 100.00 | 0.16  | Simple shear | Undrain | 0.55    | 10.0  | 0.382352941 | 0.68 | 5   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-29 | 100.00 | 0.14  | Simple shear | Undrain | 0.55    | 10.0  | 0.382352941 | 0.68 | 10  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-30 | 100.00 | 0.1   | Simple shear | Undrain | 0.55    | 10.0  | 0.382352941 | 0.68 | 52  | No ( $N_L > 30$ )           |
| UT-31 | 100.00 | 0.12  | Simple shear | Undrain | 0.55    | 10.0  | 0.382352941 | 0.68 | 25  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-32 | 100.00 | 0.2   | Simple shear | Undrain | 0.55    | 10.0  | 0.617647059 | 0.6  | 4   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-33 | 100.00 | 0.16  | Simple shear | Undrain | 0.55    | 10.0  | 0.617647059 | 0.6  | 12  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-34 | 100.00 | 0.14  | Simple shear | Undrain | 0.55    | 10.0  | 0.617647059 | 0.6  | 42  | No ( $N_L > 30$ )           |
| UT-35 | 100.00 | 0.18  | Simple shear | Undrain | 0.55    | 10.0  | 0.823529412 | 0.53 | 16  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-36 | 100.00 | 0.2   | Simple shear | Undrain | 0.55    | 10.0  | 0.823529412 | 0.53 | 9   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-37 | 100.00 | 0.14  | Simple shear | Undrain | 0.55    | 10.0  | 0.823529412 | 0.53 | 92  | No ( $N_L > 30$ )           |
| UT-38 | 100.00 | 0.08  | Simple shear | Undrain | 0.52    | 20.0  | 0.261904762 | 0.68 | 59  | No ( $N_L > 30$ )           |
| UT-39 | 100.00 | 0.1   | Simple shear | Undrain | 0.52    | 20.0  | 0.261904762 | 0.68 | 21  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-40 | 100.00 | 0.12  | Simple shear | Undrain | 0.52    | 20.0  | 0.261904762 | 0.68 | 8   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-41 | 100.00 | 0.16  | Simple shear | Undrain | 0.52    | 20.0  | 0.5         | 0.58 | 5   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-42 | 100.00 | 0.14  | Simple shear | Undrain | 0.52    | 20.0  | 0.5         | 0.58 | 12  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-43 | 100.00 | 0.12  | Simple shear | Undrain | 0.52    | 20.0  | 0.5         | 0.58 | 16  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-44 | 100.00 | 0.18  | Simple shear | Undrain | 0.52    | 20.0  | 0.666666667 | 0.51 | 14  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-45 | 100.00 | 0.16  | Simple shear | Undrain | 0.52    | 20.0  | 0.666666667 | 0.51 | 19  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-46 | 100.00 | 0.14  | Simple shear | Undrain | 0.52    | 20.0  | 0.666666667 | 0.51 | 34  | No ( $N_L > 30$ )           |
| UT-47 | 100.00 | 0.19  | Simple shear | Undrain | 0.52    | 20.0  | 0.666666667 | 0.51 | 7   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-48 | 100.00 | 0.1   | Simple shear | Undrain | 0.49    | 30.0  | 0.279069767 | 0.68 | 15  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-49 | 100.00 | 0.12  | Simple shear | Undrain | 0.49    | 30.0  | 0.279069767 | 0.68 | 7   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-50 | 100.00 | 0.14  | Simple shear | Undrain | 0.49    | 30.0  | 0.279069767 | 0.68 | 4   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-51 | 100.00 | 0.08  | Simple shear | Undrain | 0.49    | 30.0  | 0.279069767 | 0.68 | 46  | No ( $N_L > 30$ )           |
| UT-52 | 100.00 | 0.18  | Simple shear | Undrain | 0.49    | 30.0  | 0.511627907 | 0.58 | 3   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-53 | 100.00 | 0.14  | Simple shear | Undrain | 0.49    | 30.0  | 0.511627907 | 0.58 | 10  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-54 | 100.00 | 0.2   | Simple shear | Undrain | 0.49    | 30.0  | 0.720930233 | 0.49 | 33  | No ( $N_L > 30$ )           |
| UT-55 | 100.00 | 0.22  | Simple shear | Undrain | 0.49    | 30.0  | 0.720930233 | 0.49 | 12  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-56 | 100.00 | 0.24  | Simple shear | Undrain | 0.49    | 30.0  | 0.720930233 | 0.49 | 3   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-57 | 100.00 | 0.1   | Simple shear | Undrain | 0.45    | 40.0  | 0.574468085 | 0.68 | 54  | No ( $N_L > 30$ )           |
| UT-58 | 100.00 | 0.1   | Simple shear | Undrain | 0.45    | 40.0  | 0.574468085 | 0.68 | 292 | No ( $N_L > 30$ )           |
| UT-59 | 100.00 | 0.16  | Simple shear | Undrain | 0.45    | 40.0  | 0.574468085 | 0.68 | 5   | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-60 | 100.00 | 0.14  | Simple shear | Undrain | 0.45    | 40.0  | 0.574468085 | 0.68 | 10  | Yes ( $\nu_{sk} = 3.75\%$ ) |
| UT-61 | 100.00 | 0.12  | Simple shear | Undrain | 0.45    | 40.0  | 0.574468085 | 0.68 | 50  | No ( $N_L > 30$ )           |
| UT-1  | 100.00 | 0.205 | Triaxial     | Undrain | 0.375   | 0.0   |             | 0.54 | 12  | Yes ( $r_u = 1$ )           |
| UT-2  | 100.00 | 0.192 | Triaxial     | Undrain | 0.375   | 0.0   |             | 0.54 | 15  | Yes ( $r_u = 1$ )           |
| UT-3  | 100.00 | 0.180 | Triaxial     | Undrain | 0.375   | 0.0   |             | 0.54 | 26  | Yes ( $r_u = 1$ )           |
| UT-4  | 100.00 | 0.154 | Triaxial     | Undrain | 0.375   | 0.0   |             | 0.54 | 50  | No ( $N_L > 30$ )           |
| UT-5  | 100.00 | 0.128 | Triaxial     | Undrain | 0.375   | 0.0   |             | 0.54 | 103 | No ( $N_L > 30$ )           |
| UT-6  | 100.00 | 0.179 | Triaxial     | Undrain | 0.368   | 5.0   |             | 0.54 | 7   | Yes ( $r_u = 1$ )           |
| UT-7  | 100.00 | 0.155 | Triaxial     | Undrain | 0.368   | 5.0   |             | 0.54 | 25  | Yes ( $r_u = 1$ )           |
| UT-8  | 100.00 | 0.130 | Triaxial     | Undrain | 0.368   | 5.0   |             | 0.54 | 84  | No ( $N_L > 30$ )           |
| UT-9  | 100.00 | 0.128 | Triaxial     | Undrain | 0.34    | 10.0  |             | 0.54 | 12  | Yes ( $r_u = 1$ )           |
| UT-10 | 100.00 | 0.114 | Triaxial     | Undrain | 0.34    | 10.0  |             | 0.54 | 26  | Yes ( $r_u = 1$ )           |
| UT-11 | 100.00 | 0.100 | Triaxial     | Undrain | 0.34    | 10.0  |             | 0.54 | 153 | No ( $N_L > 30$ )           |
| UT-12 | 100.00 | 0.128 | Triaxial     | Undrain | 0.326   | 15.0  |             | 0.54 | 7   | Yes ( $r_u = 1$ )           |
| UT-13 | 100.00 | 0.103 | Triaxial     | Undrain | 0.326   | 15.0  |             | 0.54 | 27  | Yes ( $r_u = 1$ )           |
| UT-14 | 100.00 | 0.076 | Triaxial     | Undrain | 0.326   | 15.0  |             | 0.54 | 74  | No ( $N_L > 30$ )           |
| UT-15 | 100.00 | 0.129 | Triaxial     | Undrain | 0.293   | 20.0  |             | 0.54 | 6   | Yes ( $r_u = 1$ )           |
| UT-16 | 100.00 | 0.102 | Triaxial     | Undrain | 0.293   | 20.0  |             | 0.54 | 10  | Yes ( $r_u = 1$ )           |
| UT-17 | 100.00 | 0.076 | Triaxial     | Undrain | 0.293   | 20.0  |             | 0.54 | 32  | No ( $N_L > 30$ )           |
| UT-18 | 100.00 | 0.129 | Triaxial     | Undrain | 0.264   | 25.0  |             | 0.54 | 6   | Yes ( $r_u = 1$ )           |
| UT-19 | 100.00 | 0.104 | Triaxial     | Undrain | 0.264   | 25.0  |             | 0.54 | 23  | Yes ( $r_u = 1$ )           |
| UT-20 | 100.00 | 0.077 | Triaxial     | Undrain | 0.264   | 25.0  |             | 0.54 | 47  | No ( $N_L > 30$ )           |
| UT-21 | 100.00 | 0.099 | Triaxial     | Undrain | 0.234   | 30.0  |             | 0.54 | 17  | Yes ( $r_u = 1$ )           |
| UT-22 | 100.00 | 0.090 | Triaxial     | Undrain | 0.234   | 30.0  |             | 0.54 | 22  | Yes ( $r_u = 1$ )           |
| UT-23 | 100.00 | 0.058 | Triaxial     | Undrain | 0.234   | 30.0  |             | 0.54 | 78  | No ( $N_L > 30$ )           |
| UT-1  | 99.80  | 0.011 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | No                          |
| UT-2  | 100.00 | 0.022 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | No                          |
| UT-3  | 99.80  | 0.042 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | No                          |
| UT-4  | 100.00 | 0.069 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | No                          |
| UT-5  | 99.60  | 0.101 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | No                          |
| UT-6  | 99.30  | 0.109 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | Yes                         |
| UT-7  | 99.60  | 0.142 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | Yes                         |
| UT-8  | 99.90  | 0.173 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  |     | Yes                         |
| UT-9  | 99.70  | 0.188 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  | 1.5 | Yes                         |
| UT-10 | 99.30  | 0.196 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  | 1   | Yes                         |
| UT-11 | 99.80  | 0.226 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.8  | 0.5 | Yes                         |
| UT-12 | 100.00 | 0.022 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  |     | No                          |
| UT-13 | 99.60  | 0.047 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  |     | No                          |
| UT-14 | 99.90  | 0.069 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  |     | No                          |
| UT-15 | 98.90  | 0.087 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  |     | No                          |
| UT-16 | 100.00 | 0.134 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  |     | No                          |
| UT-17 | 99.00  | 0.146 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  | 6   | Yes                         |
| UT-18 | 99.20  | 0.173 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  | 3   | Yes                         |
| UT-19 | 99.20  | 0.19  | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  | 1   | Yes                         |
| UT-20 | 100.00 | 0.202 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  | 0.8 | Yes                         |
| UT-21 | 99.50  | 0.207 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.7  | 0.5 | Yes                         |
| UT-22 | 99.00  | 0.022 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  |     | No                          |
| UT-23 | 99.80  | 0.045 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  |     | No                          |
| UT-24 | 99.50  | 0.069 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  |     | No                          |
| UT-25 | 100.00 | 0.088 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  |     | No                          |
| UT-26 | 100.00 | 0.108 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  | 13  | Yes                         |
| UT-27 | 100.00 | 0.128 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  | 3   | Yes                         |
| UT-28 | 99.00  | 0.174 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  | 1   | Yes                         |
| UT-29 | 99.00  | 0.193 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  | 0.7 | Yes                         |
| UT-30 | 98.00  | 0.217 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  | 0.5 | Yes                         |
| UT-31 | 99.90  | 0.19  | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.6  | 0.8 | Yes                         |
| UT-32 | 99.20  | 0.011 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  |     | No                          |
| UT-33 | 99.00  | 0.024 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  |     | No                          |
| UT-34 | 99.60  | 0.048 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  |     | No                          |
| UT-35 | 99.30  | 0.062 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  |     | No                          |
| UT-36 | 99.00  | 0.07  | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  |     | No                          |
| UT-37 | 100.00 | 0.091 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  |     | No                          |
| UT-38 | 100.00 | 0.118 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  | 18  | Yes                         |
| UT-39 | 99.00  | 0.149 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  | 7   | Yes                         |
| UT-40 | 99.00  | 0.163 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  | 5   | Yes                         |
| UT-41 | 99.60  | 0.186 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.5  | 2   | Yes                         |
| UT-42 | 100.00 | 0.011 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-43 | 99.50  | 0.023 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-44 | 99.90  | 0.047 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-45 | 99.50  | 0.059 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-46 | 99.70  | 0.07  | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-47 | 99.90  | 0.093 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-48 | 99.50  | 0.124 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | No                          |
| UT-49 | 99.70  | 0.137 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  | 6   | Yes                         |
| UT-50 | 99.70  | 0.169 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  |     | Yes                         |
| UT-51 | 99.60  | 0.19  | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.4  | 3   | Yes                         |
| UT-52 | 100.00 | 0.01  | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.3  |     | No                          |
| UT-53 | 99.80  | 0.022 | Triaxial     | Undrain | 0.01485 | 100.0 |             | 0.3  |     | No                          |
| UT-54 | 99.80  |       |              |         |         |       |             |      |     |                             |

|       |        |         |                     |         |         |      |          |          |          |                             |
|-------|--------|---------|---------------------|---------|---------|------|----------|----------|----------|-----------------------------|
| UT-8  | 100.00 | 0.152   | Triaxial            | Undrain | 0.07511 | 51.0 | 0.405685 | 13       | Yes      |                             |
| UT-9  | 100.00 | 0.346   | Triaxial            | Undrain | 0.0408  | 71.0 | 0.421776 | 2        | Yes      |                             |
| UT-10 | 100.00 | 0.254   | Triaxial            | Undrain | 0.0408  | 71.0 | 0.447793 | 3        | Yes      |                             |
| UT-11 | 100.00 | 0.199   | Triaxial            | Undrain | 0.0408  | 71.0 | 0.445459 | 8        | Yes      |                             |
| UT-12 | 100.00 | 0.152   | Triaxial            | Undrain | 0.0408  | 71.0 | 0.433138 | 30       | No       |                             |
| UT-13 | 100.00 | 0.369   | Triaxial            | Undrain | 0.05624 | 67.0 | 0.527149 | 1        | Yes      |                             |
| UT-14 | 100.00 | 0.247   | Triaxial            | Undrain | 0.05624 | 67.0 | 0.582649 | 3        | Yes      |                             |
| UT-15 | 100.00 | 0.201   | Triaxial            | Undrain | 0.05624 | 67.0 | 0.415094 | 10       | Yes      |                             |
| UT-16 | 100.00 | 0.151   | Triaxial            | Undrain | 0.05624 | 67.0 | 0.424802 | 32       | No       |                             |
| UT-17 | 100.00 | 0.372   | Triaxial            | Undrain | 0.05624 | 73.0 | 0.45484  | 4        | Yes      |                             |
| UT-18 | 100.00 | 0.252   | Triaxial            | Undrain | 0.05624 | 73.0 | 0.461957 | 8        | Yes      |                             |
| UT-19 | 100.00 | 0.203   | Triaxial            | Undrain | 0.05624 | 73.0 | 0.409653 | 12       | Yes      |                             |
| UT-20 | 100.00 | 0.151   | Triaxial            | Undrain | 0.05624 | 73.0 | 0.42833  | 302      | No       |                             |
| CTX01 | 100.00 | 0.1     | Triaxial            | Undrain | 0.46    | 0.0  | 0.217    | 1.129    | 36       | No ( $N_L > 30$ )           |
| CTX02 | 100.00 | 0.15    | Triaxial            | Undrain | 0.46    | 0.0  | 0.22     | 1.128    | 8        | Yes ( $r_u = 1$ )           |
| CTX03 | 100.00 | 0.2     | Triaxial            | Undrain | 0.46    | 0.0  | 0.236    | 1.126    | 5        | Yes ( $r_u = 1$ )           |
| CTX04 | 100.00 | 0.15    | Triaxial            | Undrain | 0.46    | 0.0  | 0.231    | 1.123    | 29       | Yes ( $r_u = 1$ )           |
| CTX05 | 100.00 | 0.13    | Triaxial            | Undrain | 0.46    | 0.0  | 0.232    | 1.123    | 13       | Yes ( $r_u = 1$ )           |
| CTX06 | 100.00 | 0.25    | Triaxial            | Undrain | 0.46    | 0.0  | 0.384    | 1.059    | 3        | Yes ( $r_u = 1$ )           |
| CTX07 | 100.00 | 0.2     | Triaxial            | Undrain | 0.46    | 0.0  | 0.413    | 1.047    | 11       | Yes ( $r_u = 1$ )           |
| CTX08 | 100.00 | 0.15    | Triaxial            | Undrain | 0.46    | 0.0  | 0.426    | 1.042    | 23       | Yes ( $r_u = 1$ )           |
| CTX09 | 100.00 | 0.3     | Triaxial            | Undrain | 0.46    | 0.0  | 0.554    | 0.988    | 8        | Yes ( $r_u = 1$ )           |
| CTX10 | 100.00 | 0.35    | Triaxial            | Undrain | 0.46    | 0.0  | 0.566    | 0.983    | 7        | Yes ( $r_u = 1$ )           |
| CTX11 | 100.00 | 0.32    | Triaxial            | Undrain | 0.46    | 0.0  | 0.568    | 0.982    | 7        | Yes ( $r_u = 1$ )           |
| CTX12 | 100.00 | 0.3     | Triaxial            | Undrain | 0.46    | 0.0  | 0.578    | 0.978    | 11       | Yes ( $r_u = 1$ )           |
| CTX13 | 100.00 | 0.25    | Triaxial            | Undrain | 0.46    | 0.0  | 0.589    | 0.974    | 38       | No ( $N_L > 30$ )           |
| UT-1  | 100.00 | 0.15    | Triaxial            | Undrain | 0.61    | 0.0  | 0.15     | 0.80615  | 23       | Yes                         |
| UT-2  | 100.00 | 0.25    | Triaxial            | Undrain | 0.61    | 0.0  | 0.15     | 0.80615  | 3        | Yes                         |
| UT-3  | 100.00 | 0.35    | Triaxial            | Undrain | 0.61    | 0.0  | 0.15     | 0.80615  | 2        | Yes                         |
| UT-4  | 100.00 | 0.15    | Triaxial            | Undrain | 0.61    | 0.0  | 0.5      | 0.6945   | 70       | No ( $N_L > 30$ )           |
| UT-5  | 100.00 | 0.25    | Triaxial            | Undrain | 0.61    | 0.0  | 0.5      | 0.6945   | 6        | Yes                         |
| UT-6  | 100.00 | 0.35    | Triaxial            | Undrain | 0.61    | 0.0  | 0.5      | 0.6945   | 4        | Yes                         |
| UT-7  | 100.00 | 0.15    | Triaxial            | Undrain | 0.61    | 0.0  | 0.65     | 0.64665  | 120      | No ( $N_L > 30$ )           |
| UT-8  | 100.00 | 0.25    | Triaxial            | Undrain | 0.61    | 0.0  | 0.65     | 0.64665  | 11       | Yes                         |
| UT-9  | 100.00 | 0.35    | Triaxial            | Undrain | 0.61    | 0.0  | 0.65     | 0.64665  | 5        | Yes                         |
| UT-1  | 50.00  | 0.19944 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.63     | 0.6079   | 6.79961  | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-2  | 50.00  | 0.14935 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.63     | 0.6079   | 17.83604 | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-3  | 50.00  | 0.13957 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.63     | 0.6079   | 33.45681 | No ( $N_L > 30$ )           |
| UT-4  | 100.00 | 0.17982 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.59     | 0.6187   | 2.65643  | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-5  | 100.00 | 0.14935 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.59     | 0.6187   | 6.53847  | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-6  | 100.00 | 0.12036 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.59     | 0.6187   | 20.18268 | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-7  | 100.00 | 0.09961 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.59     | 0.6187   | 42.89208 | No ( $N_L > 30$ )           |
| UT-8  | 400.00 | 0.15083 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.62     | 0.6106   | 3.76969  | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-9  | 400.00 | 0.10115 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.62     | 0.6106   | 21.64083 | Yes ( $\gamma_{SA} = 6\%$ ) |
| UT-10 | 400.00 | 0.08567 | Direct Simple Shear | Undrain | 0.2     | 0.0  | 0.62     | 0.6106   | 80.55541 | No ( $N_L > 30$ )           |
| UT-16 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.27     | 0.79946  | 1.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-17 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.422    | 0.753556 | 14.6     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-18 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.425    | 0.753265 | 2.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-19 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.429    | 0.751442 | 5.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-20 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.453    | 0.744194 | 0.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-21 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.581    | 0.705538 | 3.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-22 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.585    | 0.70433  | 2.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-23 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.597    | 0.700706 | 3.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-24 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.627    | 0.691646 | 4.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-25 | 100.00 | 0.18    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.633    | 0.696834 | 1.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-26 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.647    | 0.685606 | 24.1     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-27 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.66     | 0.68168  | 20.7     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-28 | 100.00 | 0.13    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.664    | 0.680472 | 10.6     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-29 | 100.00 | 0.13    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.714    | 0.665372 | 11.1     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-30 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.77     | 0.64846  | 6.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-31 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.8      | 0.6394   | 14.7     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-32 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.804    | 0.638192 | 38.7     | No ( $N_L > 30$ )           |
| UT-33 | 100.00 | 0.05    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.416    | 0.755368 | 55.2     | No ( $N_L > 30$ )           |
| UT-34 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.426    | 0.752348 | 8.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-35 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.417    | 0.755066 | 1.3      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-36 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.441    | 0.747818 | 7.9      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-37 | 100.00 | 0.04    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.44     | 0.74812  | 498.2    | No ( $N_L > 30$ )           |
| UT-38 | 100.00 | 0.05    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.355    | 0.77379  | 8.3      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-39 | 100.00 | 0.06    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.446    | 0.746308 | 6.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-40 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.428    | 0.751744 | 0.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-41 | 100.00 | 0.015   | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.398    | 0.760804 | 57.3     | No ( $N_L > 30$ )           |
| UT-42 | 100.00 | 0.02    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.443    | 0.747214 | 9.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-43 | 100.00 | 0.024   | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.398    | 0.760804 | 1.3      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-44 | 100.00 | 0.05    | Direct Simple Shear | Undrain | 0.18    | 0.0  | 0.42     | 0.75416  | 0.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-45 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.406    | 0.708734 | 5.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-46 | 100.00 | 0.06    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.447    | 0.695983 | 121.1    | No ( $N_L > 30$ )           |
| UT-47 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.462    | 0.691318 | 55.1     | No ( $N_L > 30$ )           |
| UT-48 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.462    | 0.691318 | 10.1     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-49 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.474    | 0.687586 | 5.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-50 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.476    | 0.686964 | 1.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-51 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.624    | 0.640936 | 2.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-52 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.626    | 0.640314 | 29.6     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-53 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.636    | 0.637204 | 8.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-54 | 100.00 | 0.13    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.643    | 0.635027 | 6.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-55 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.775    | 0.593975 | 8.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-56 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.814    | 0.581846 | 5.3      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-57 | 100.00 | 0.2     | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.819    | 0.580291 | 2.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-58 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.32     | 0.74876  | 2.1      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-59 | 100.00 | 0.06    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.416    | 0.721688 | 21.6     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-60 | 100.00 | 0.07    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.433    | 0.716894 | 10.1     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-61 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.44     | 0.71492  | 3.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-62 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.453    | 0.711254 | 0.8      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-63 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.565    | 0.67967  | 1.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-64 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.648    | 0.656264 | 2.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-65 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.661    | 0.652598 | 12.1     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-66 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.662    | 0.652316 | 4.2      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-67 | 100.00 | 0.06    | Direct Simple Shear | Undrain | 1.31    | 0.0  | 0.663    | 0.652034 | 31.6     |                             |
| UT-68 | 100.00 | 0.13    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.386    | 0.64299  | 0.8      | No ( $N_L > 30$ )           |
| UT-69 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.409    | 0.636435 | 3.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-70 | 100.00 | 0.07    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.432    | 0.62968  | 33.6     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-71 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.484    | 0.61506  | 20.2     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-72 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.493    | 0.612495 | 17.1     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-73 | 100.00 | 0.12    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.515    | 0.606225 | 4.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-74 | 100.00 | 0.13    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.58     | 0.5877   | 5.6      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-75 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.582    | 0.58713  | 12.2     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-76 | 100.00 | 0.08    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.604    | 0.58086  | 38.7     | No ( $N_L > 30$ )           |
| UT-77 | 100.00 | 0.13    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.746    | 0.54039  | 11.7     | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-78 | 100.00 | 0.15    | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.773    | 0.532695 | 8.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-79 | 100.00 | 0.2     | Direct Simple Shear | Undrain | 0.29    | 0.0  | 0.795    | 0.526425 | 3.7      | Yes ( $\gamma_{SA} = 3\%$ ) |
| UT-85 | 100.00 | 0.1     | Direct Simple Shear | Undrain | 0.51    | 0.0  | 0.25     | 0.56575  | 1.7      | Yes ( $\gamma_{SA} = 3\%$ ) |

|        |        |       |                     |         |      |     |       |          |       |                                |
|--------|--------|-------|---------------------|---------|------|-----|-------|----------|-------|--------------------------------|
| UT-103 | 100.00 | 0.02  | Direct Simple Shear | Undrain | 0.51 | 0.0 | 0.427 | 0.525925 | 175.2 | No ( $N_v > 30$ )              |
| UT-104 | 100.00 | 0.025 | Direct Simple Shear | Undrain | 0.51 | 0.0 | 0.4   | 0.532    | 5.3   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-105 | 100.00 | 0.03  | Direct Simple Shear | Undrain | 0.51 | 0.0 | 0.42  | 0.5275   | 6.3   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-106 | 100.00 | 0.035 | Direct Simple Shear | Undrain | 0.51 | 0.0 | 0.412 | 0.5293   | 0.4   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-107 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.337 | 0.779226 | 5.7   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-108 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.426 | 0.752348 | 3.1   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-109 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.429 | 0.751442 | 18.1  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-110 | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.458 | 0.742684 | 52.1  | No ( $N_v > 30$ )              |
| UT-111 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.614 | 0.695572 | 19.2  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-112 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.553 | 0.713994 | 4.2   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-113 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.612 | 0.696176 | 20.1  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-114 | 100.00 | 0.18  | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.681 | 0.675338 | 5.2   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-115 | 100.00 | 0.13  | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.709 | 0.666882 | 16.7  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-116 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 0.18 | 0.0 | 0.646 | 0.685908 | 7.2   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-117 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.487 | 0.679536 | 6.6   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-118 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.339 | 0.719792 | 4.1   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-119 | 100.00 | 0.07  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.469 | 0.684432 | 31.2  | No ( $N_v > 30$ )              |
| UT-120 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.341 | 0.719248 | 1.1   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-121 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.345 | 0.71816  | 0.8   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-122 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.412 | 0.699936 | 1.1   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-123 | 100.00 | 0.07  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.384 | 0.707552 | 27.6  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-124 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.636 | 0.630008 | 1.7   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-125 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.61  | 0.64608  | 6.6   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-126 | 100.00 | 0.08  | Direct Simple Shear | Undrain | 2.58 | 0.0 | 0.604 | 0.647712 | 14.6  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-127 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.564 | 0.408076 | 8.2   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-128 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.572 | 0.406148 | 10.1  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-129 | 100.00 | 0.07  | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.563 | 0.408317 | 26.2  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-130 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.409 | 0.445431 | 5.1   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-131 | 100.00 | 0.07  | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.392 | 0.449528 | 18.1  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-132 | 100.00 | 0.15  | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.407 | 0.445913 | 1.7   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-133 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.295 | 0.472905 | 4.7   | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-134 | 100.00 | 0.07  | Direct Simple Shear | Undrain | 0.8  | 0.0 | 0.177 | 0.501343 | 17.6  | Yes ( $\gamma_{SA} = 3\%$ )    |
| UT-1   | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.266 | 0.788    | 5     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-2   | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.403 | 0.75     | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-3   | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.854 | 0.626    | 56    | No ( $N_v > 30$ )              |
| UT-4   | 50.00  | 0.1   | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.282 | 0.784    | 1     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-5   | 50.00  | 0.1   | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.683 | 0.673    | 12    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-6   | 50.00  | 0.1   | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.789 | 0.644    | 23    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-7   | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.297 | 0.779    | 10    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-8   | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.494 | 0.725    | 18    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-9   | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.717 | 0.664    | 57    | No ( $N_v > 30$ )              |
| UT-10  | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.3   | 0.778    | 9     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-11  | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.486 | 0.727    | 16    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-12  | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.63  | 0.688    | 26    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-13  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.331 | 0.77     | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-14  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.486 | 0.727    | 12    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-15  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.695 | 0.67     | 26    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-16  | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.369 | 0.76     | 5     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-17  | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.528 | 0.716    | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-18  | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.17 | 4.0 | 0.751 | 0.654    | 25    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-19  | 100.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.222 | 0.816    | 2     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-20  | 100.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.457 | 0.751    | 3     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-21  | 100.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.878 | 0.636    | 14    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-22  | 200.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.817 | 0.652    | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-23  | 200.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.487 | 0.743    | 3     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-24  | 200.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.321 | 0.789    | 3     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-25  | 400.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.927 | 0.622    | 13    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-26  | 400.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.575 | 0.719    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-27  | 400.00 | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.347 | 0.782    | 3     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-28  | 400.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.9   | 0.629    | 17    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-29  | 400.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.336 | 0.785    | 6     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-30  | 400.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.484 | 0.744    | 10    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-31  | 200.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.908 | 0.627    | 20    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-32  | 200.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.325 | 0.788    | 6     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-33  | 200.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.571 | 0.72     | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-34  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.885 | 0.634    | 22    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-35  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.181 | 0.827    | 3     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-36  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.241 | 0.811    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-37  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.226 | 0.815    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-38  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.476 | 0.746    | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-39  | 400.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.908 | 0.627    | 36    | No ( $N_v > 30$ )              |
| UT-40  | 400.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.768 | 0.666    | 28    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-41  | 400.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.431 | 0.759    | 14    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-42  | 200.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.548 | 0.726    | 15    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-43  | 200.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.298 | 0.795    | 9     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-44  | 200.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.438 | 0.756    | 12    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-45  | 200.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.719 | 0.679    | 23    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-46  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.215 | 0.818    | 6     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-47  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.241 | 0.811    | 7     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-48  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.711 | 0.681    | 26    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-49  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.438 | 0.756    | 10    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-50  | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.173 | 0.829    | 5     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-51  | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.347 | 0.782    | 11    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-52  | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.734 | 0.675    | 30    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-53  | 50.00  | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.184 | 0.826    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-54  | 50.00  | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.734 | 0.675    | 18    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-55  | 50.00  | 0.105 | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.465 | 0.749    | 10    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-56  | 50.00  | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.378 | 0.773    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-57  | 50.00  | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.503 | 0.739    | 5     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-58  | 50.00  | 0.12  | Direct Simple Shear | Undrain | 0.46 | 0.0 | 0.647 | 0.699    | 8     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-59  | 50.00  | 0.09  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.19  | 0.773    | 15    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-60  | 50.00  | 0.09  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.504 | 0.691    | 33    | No ( $N_v > 30$ )              |
| UT-61  | 50.00  | 0.09  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.663 | 0.649    | 54    | No ( $N_v > 30$ )              |
| UT-62  | 50.00  | 0.105 | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.063 | 0.807    | 6     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-63  | 50.00  | 0.105 | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.457 | 0.703    | 15    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-64  | 50.00  | 0.105 | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.675 | 0.646    | 28    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-65  | 50.00  | 0.12  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.003 | 0.822    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-66  | 50.00  | 0.12  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.27  | 0.752    | 5     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-67  | 50.00  | 0.12  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.715 | 0.636    | 20    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-68  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.115 | 0.793    | 10    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-69  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.62  | 0.661    | 36    | No ( $N_v > 30$ )              |
| UT-70  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.477 | 0.698    | 22    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-71  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.103 | 0.796    | 5     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-72  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.214 | 0.767    | 6     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-73  | 100.00 | 0.105 | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.66  | 0.65     | 22    | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-74  | 100.00 | 0.12  | Direct Simple Shear | Undrain | 2.35 | 0.0 | 0.123 | 0.791    | 4     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-75  | 1      |       |                     |         |      |     |       |          |       |                                |

|        |        |       |                     |         |         |      |       |          |     |                                |
|--------|--------|-------|---------------------|---------|---------|------|-------|----------|-----|--------------------------------|
| UT-93  | 100.00 | 0.09  | Direct Simple Shear | Undrain | 6.75    | 0.0  | 0.172 | 0.782    | 12  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-94  | 100.00 | 0.11  | Direct Simple Shear | Undrain | 6.75    | 0.0  | 0.817 | 0.647    | 16  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-95  | 100.00 | 0.11  | Direct Simple Shear | Undrain | 6.75    | 0.0  | 0.66  | 0.679    | 12  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-96  | 100.00 | 0.11  | Direct Simple Shear | Undrain | 6.75    | 0.0  | 0.447 | 0.724    | 8   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-97  | 50.00  | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.023 | 0.585    | 15  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-98  | 50.00  | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.051 | 0.58     | 19  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-99  | 50.00  | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.378 | 0.517    | 25  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-100 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.596 | 0.475    | 36  | No ( $N_L > 30$ )              |
| UT-101 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.007 | 0.589    | 18  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-102 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.302 | 0.532    | 27  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-103 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.635 | 0.468    | 41  | No ( $N_L > 30$ )              |
| UT-104 | 50.00  | 0.12  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.083 | 0.574    | 9   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-105 | 50.00  | 0.12  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.373 | 0.518    | 13  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-106 | 50.00  | 0.12  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.662 | 0.462    | 17  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-107 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.083 | 0.574    | 13  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-108 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.187 | 0.554    | 15  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-109 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.449 | 0.503    | 21  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-110 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.629 | 0.469    | 23  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-111 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.198 | 0.552    | 21  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-112 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.438 | 0.505    | 26  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-113 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.705 | 0.454    | 38  | No ( $N_L > 30$ )              |
| UT-114 | 100.00 | 0.12  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.1   | 0.571    | 7   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-115 | 100.00 | 0.12  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.591 | 0.476    | 13  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-116 | 100.00 | 0.12  | Direct Simple Shear | Undrain | 5.1     | 0.0  | 0.716 | 0.452    | 16  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-117 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.184 | 0.49     | 12  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-118 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.519 | 0.431    | 25  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-119 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.926 | 0.359    | 44  | No ( $N_L > 30$ )              |
| UT-120 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.166 | 0.493    | 6   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-121 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.597 | 0.417    | 13  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-122 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.872 | 0.369    | 21  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-123 | 50.00  | 0.11  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.393 | 0.453    | 14  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-124 | 50.00  | 0.11  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.148 | 0.496    | 7   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-125 | 50.00  | 0.11  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.878 | 0.367    | 27  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-126 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.591 | 0.418    | 22  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-127 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.184 | 0.49     | 8   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-128 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.453 | 0.442    | 14  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-129 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.848 | 0.373    | 30  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-130 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.28  | 0.473    | 6   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-131 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.651 | 0.408    | 13  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-132 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.878 | 0.367    | 22  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-133 | 100.00 | 0.11  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.124 | 0.5      | 4   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-134 | 100.00 | 0.11  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.447 | 0.443    | 7   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-135 | 100.00 | 0.11  | Direct Simple Shear | Undrain | 2.1     | 0.0  | 0.812 | 0.379    | 16  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-136 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.002 | 0.569    | 3   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-137 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.556 | 0.474    | 17  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-138 | 50.00  | 0.09  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.704 | 0.449    | 22  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-139 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.039 | 0.562    | 3   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-140 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.255 | 0.525    | 5   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-141 | 50.00  | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.797 | 0.433    | 19  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-142 | 50.00  | 0.11  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.101 | 0.552    | 2   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-143 | 50.00  | 0.11  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.249 | 0.527    | 3   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-144 | 50.00  | 0.11  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.741 | 0.442    | 9   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-145 | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.125 | 0.548    | 7   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-146 | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.255 | 0.525    | 9   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-147 | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.39  | 0.502    | 12  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-148 | 50.00  | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.643 | 0.459    | 29  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-149 | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.199 | 0.535    | 6   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-150 | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.366 | 0.506    | 12  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-151 | 100.00 | 0.08  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.575 | 0.471    | 20  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-152 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.138 | 0.545    | 3   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-153 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.292 | 0.519    | 6   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-154 | 100.00 | 0.09  | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.827 | 0.428    | 31  | No ( $N_L > 30$ )              |
| UT-155 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.107 | 0.551    | 3   | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-156 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.606 | 0.465    | 10  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-157 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.618 | 0.463    | 10  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-158 | 100.00 | 0.1   | Direct Simple Shear | Undrain | 0.36    | 0.0  | 0.858 | 0.422    | 21  | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-1   | 50.00  | 0.21  | Direct simple shear | Undrain | 0.00945 | 95.0 | 1.24  | 720      |     | No ( $N_L > 30$ )              |
| UT-2   | 50.00  | 0.44  | Direct simple shear | Undrain | 0.00945 | 91.0 | 1.35  | 4.2      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-3   | 50.00  | 0.38  | Direct simple shear | Undrain | 0.00945 | 93.0 | 1.38  | 8.2      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-4   | 50.00  | 0.33  | Direct simple shear | Undrain | 0.00945 | 92.0 | 1.35  | 11.3     |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-5   | 48.00  | 0.31  | Direct simple shear | Undrain | 0.00945 |      | 1.47  | 65.3     |     | No ( $N_L > 30$ )              |
| UT-6   | 50.00  | 0.33  | Direct simple shear | Undrain | 0.00945 |      | 1.5   | 24.8     |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-7   | 160.00 | 0.14  | Direct simple shear | Undrain | 0.01335 |      | 0.97  | 720      |     | No ( $N_L > 30$ )              |
| UT-8   | 160.00 | 0.29  | Direct simple shear | Undrain | 0.01335 | 86.0 | 0.95  | 4.2      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-9   | 160.00 | 0.25  | Direct simple shear | Undrain | 0.01335 | 81.0 | 0.92  | 26.2     |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-10  | 160.00 | 0.22  | Direct simple shear | Undrain | 0.01335 | 80.0 | 0.9   | 34.2     |     | No ( $N_L > 30$ )              |
| UT-11  | 160.00 | 0.27  | Direct simple shear | Undrain | 0.01335 | 99.0 | 0.98  | 3.2      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-12  | 160.00 | 0.27  | Direct simple shear | Undrain | 0.01335 |      | 1     | 4.2      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-13  | 160.00 | 0.26  | Direct simple shear | Undrain | 0.01335 | 98.0 | 0.89  | 10.7     |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-14  | 160.00 | 0.22  | Direct simple shear | Undrain | 0.01335 | 95.0 | 0.84  | 9.3      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-15  | 160.00 | 0.2   | Direct simple shear | Undrain | 0.01335 |      | 0.81  | 20.3     |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-16  | 160.00 | 0.18  | Direct simple shear | Undrain | 0.01335 | 98.0 | 0.87  | 39.2     |     | No ( $N_L > 30$ )              |
| UT-17  | 160.00 | 0.22  | Direct simple shear | Undrain | 0.01335 |      | 0.84  | 9.7      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-18  | 160.00 | 0.25  | Direct simple shear | Undrain | 0.01335 |      | 0.85  | 1.8      |     | Yes ( $\gamma_{DA} = 3.75\%$ ) |
| UT-1   | 100.00 | 0.149 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.558 | 0.75611  | 86  | No ( $N_L > 30$ )              |
| UT-2   | 100.00 | 0.148 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.561 | 0.754745 | 138 | No ( $N_L > 30$ )              |
| UT-3   | 100.00 | 0.152 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.505 | 0.780225 | 39  | No ( $N_L > 30$ )              |
| UT-4   | 100.00 | 0.152 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.517 | 0.774765 | 83  | No ( $N_L > 30$ )              |
| UT-5   | 100.00 | 0.195 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.539 | 0.764755 | 44  | No ( $N_L > 30$ )              |
| UT-6   | 100.00 | 0.195 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.574 | 0.74883  | 27  | Yes                            |
| UT-7   | 100.00 | 0.197 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.607 | 0.733815 | 62  | No ( $N_L > 30$ )              |
| UT-8   | 100.00 | 0.199 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.65  | 0.71425  | 132 | No ( $N_L > 30$ )              |
| UT-9   | 100.00 | 0.195 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.585 | 0.743825 | 41  | No ( $N_L > 30$ )              |
| UT-10  | 100.00 | 0.244 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.619 | 0.728355 | 19  | Yes                            |
| UT-11  | 100.00 | 0.246 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.6   | 0.737    | 10  | Yes                            |
| UT-12  | 100.00 | 0.301 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.67  | 0.70515  | 51  | No ( $N_L > 30$ )              |
| UT-13  | 100.00 | 0.164 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.562 | 0.74519  | 67  | No ( $N_L > 30$ )              |
| UT-14  | 100.00 | 0.195 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.584 | 0.74428  | 121 | No ( $N_L > 30$ )              |
| UT-15  | 100.00 | 0.259 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.575 | 0.748375 | 2   | Yes                            |
| UT-16  | 100.00 | 0.298 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.778 | 0.65601  | 90  | No ( $N_L > 30$ )              |
| UT-17  | 100.00 | 0.246 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.599 | 0.737455 | 4   | Yes                            |
| UT-18  | 100.00 | 0.295 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.577 | 0.747465 | 6   | Yes                            |
| UT-19  | 100.00 | 0.344 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.678 | 0.70151  | 12  | Yes                            |
| UT-20  | 100.00 | 0.194 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.509 | 0.778405 | 5   | Yes                            |
| UT-21  | 100.00 | 0.194 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.611 | 0.731995 | 32  | No ( $N_L > 30$ )              |
| UT-22  | 100.00 | 0.209 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.576 | 0.74792  | 46  | No ( $N_L > 30$ )              |
| UT-23  | 100.00 | 0.21  | Direct simple shear | Undrain | 0.35    | 0.0  | 0.667 | 0.706515 | 222 | No ( $N_L > 30$ )              |
| UT-24  | 100.00 | 0.255 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.534 | 0.76703  | 5   | Yes                            |
| UT-25  | 100.00 | 0.257 | Direct simple shear | Undrain | 0.35    | 0.0  | 0.584 | 0.74428  | 74  | No ( $N_L > 30$ )              |
| UT-    |        |       |                     |         |         |      |       |          |     |                                |

|        |        |       |          |         |      |      |             |       |           |                               |
|--------|--------|-------|----------|---------|------|------|-------------|-------|-----------|-------------------------------|
| UT-16  | 93.00  | 0.47  | Triaxial | Undrain | 0.2  | 13.0 | 0.678832117 | 2.38  | 6.95706   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-17  | 93.00  | 0.36  | Triaxial | Undrain | 0.2  | 13.0 | 0.693430657 | 2.36  | 10.85072  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-18  | 93.00  | 0.32  | Triaxial | Undrain | 0.2  | 13.0 | 0.518248175 | 2.6   | 18.05686  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-19  | 93.00  | 0.24  | Triaxial | Undrain | 0.2  | 13.0 | 0.328467153 | 2.86  | 75.00021  | No ( $N_L > 30$ )             |
| UT-20  | 100.00 | 0.21  | Triaxial | Undrain | 0.21 | 0.0  | 0.818181818 | 0.72  | 3.9459    | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-21  | 100.00 | 0.16  | Triaxial | Undrain | 0.21 | 0.0  | 0.818181818 | 0.72  | 9.90536   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-22  | 100.00 | 0.1   | Triaxial | Undrain | 0.21 | 0.0  | 0.757575758 | 0.74  | 346.50199 | No ( $N_L > 30$ )             |
| UT-23  | 100.00 | 0.24  | Triaxial | Undrain | 0.23 | 3.0  | 1.583333333 | 0.91  | 12.06921  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-24  | 100.00 | 0.16  | Triaxial | Undrain | 0.23 | 3.0  | 0.791666667 | 1.29  | 531.64758 | No ( $N_L > 30$ )             |
| UT-25  | 100.00 | 0.315 | Triaxial | Undrain | 0.23 | 3.0  | 0.604166667 | 1.38  | 14.13597  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-26  | 100.00 | 0.245 | Triaxial | Undrain | 0.24 | 1.0  | 0.638297872 | 1.32  | 14.13597  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-27  | 100.00 | 0.175 | Triaxial | Undrain | 0.24 | 1.0  | 1.170212766 | 1.07  | 76.80987  | No ( $N_L > 30$ )             |
| UT-28  | 100.00 | 0.31  | Triaxial | Undrain | 0.24 | 1.0  | 0.808510638 | 1.24  | 8.03631   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-29  | 100.00 | 0.26  | Triaxial | Undrain | 0.5  | 5.0  | 0.544444444 | 2.27  | 53.20851  | No ( $N_L > 30$ )             |
| UT-30  | 100.00 | 0.29  | Triaxial | Undrain | 0.5  | 5.0  | 1.066666667 | 1.8   | 6.12129   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-31  | 100.00 | 0.34  | Triaxial | Undrain | 0.5  | 5.0  | 1.222222222 | 1.66  | 5.05014   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-32  | 100.00 | 0.19  | Triaxial | Undrain | 0.4  | 2.0  | 1.739130435 | 0.79  | 23.92482  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-33  | 100.00 | 0.23  | Triaxial | Undrain | 0.4  | 2.0  | 1.275362319 | 1.11  | 6.05915   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-34  | 100.00 | 0.17  | Triaxial | Undrain | 0.4  | 2.0  | 1.507246377 | 0.95  | 88.74132  | No ( $N_L > 30$ )             |
| UT-35  | 100.00 | 0.24  | Triaxial | Undrain | 0.4  |      |             |       | 18.12415  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-36  | 100.00 | 0.31  | Triaxial | Undrain | 0.4  |      |             |       | 4.32927   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-37  | 100.00 | 0.33  | Triaxial | Undrain | 0.4  |      |             |       | 3.01135   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-38  | 100.00 | 0.16  | Triaxial | Undrain | 0.35 | 0.0  | 0.806451613 | 0.8   | 174.36355 | No ( $N_L > 30$ )             |
| UT-39  | 100.00 | 0.24  | Triaxial | Undrain | 0.35 | 0.0  | 0.741935484 | 0.82  | 12.8814   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-40  | 100.00 | 0.25  | Triaxial | Undrain | 0.25 | 2.0  | -0.76470568 | 1.42  | 7.93859   | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-41  | 100.00 | 0.215 | Triaxial | Undrain | 0.25 | 2.0  | -0.03030303 | 1     | 25.72459  | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-42  | 100.00 | 0.23  | Triaxial | Undrain | 0.36 | 0.0  | 0.033333333 | 0.89  | 70        | No ( $N_L > 30$ )             |
| UT-44  | 100.00 | 0.265 | Triaxial | Undrain | 0.36 | 0.0  | 0.6         | 0.72  | 6         | Yes ( $\epsilon_{DA} = 7\%$ ) |
| UT-46  | 100.00 | 0.245 | Triaxial | Undrain | 0.36 | 0.0  | -1.36666667 | 1.31  | 7         | Yes ( $\epsilon_{DA} = 7\%$ ) |
| CU-25  | 100.00 | 0.102 | Triaxial | Undrain | 0.42 | 0.0  | 0.28        | 0.644 | 120.9     | No ( $N_L > 30$ )             |
| CU-26  | 100.00 | 0.128 | Triaxial | Undrain | 0.42 | 0.0  | 0.3         | 0.64  | 33.9      | No ( $N_L > 30$ )             |
| CU-27  | 100.00 | 0.155 | Triaxial | Undrain | 0.42 | 0.0  | 0.31        | 0.639 | 12.0      | Yes                           |
| CU-28  | 100.00 | 0.149 | Triaxial | Undrain | 0.42 | 0.0  | 0.27        | 0.646 | 13.0      | Yes                           |
| CU-29  | 100.00 | 0.163 | Triaxial | Undrain | 0.42 | 0.0  | 0.4         | 0.625 | 10.9      | Yes                           |
| CU-30  | 100.00 | 0.12  | Triaxial | Undrain | 0.42 | 0.0  | 0.39        | 0.626 | 77.9      | No ( $N_L > 30$ )             |
| CU-31  | 100.00 | 0.145 | Triaxial | Undrain | 0.42 | 0.0  | 0.4         | 0.623 | 23.0      | Yes                           |
| CU-32  | 100.00 | 0.103 | Triaxial | Undrain | 0.42 | 0.0  | 0.37        | 0.629 | 117.4     | No ( $N_L > 30$ )             |
| CU-33  | 100.00 | 0.18  | Triaxial | Undrain | 0.42 | 0.0  | 0.54        | 0.601 | 13.9      | Yes                           |
| CU-34  | 100.00 | 0.128 | Triaxial | Undrain | 0.42 | 0.0  | 0.53        | 0.603 | 84.0      | No ( $N_L > 30$ )             |
| CU-35  | 100.00 | 0.153 | Triaxial | Undrain | 0.42 | 0.0  | 0.53        | 0.603 | 32.2      | No ( $N_L > 30$ )             |
| CU-36  | 100.00 | 0.102 | Triaxial | Undrain | 0.42 | 0.0  | 0.52        | 0.604 | 270.1     | No ( $N_L > 30$ )             |
| CU-37  | 100.00 | 0.191 | Triaxial | Undrain | 0.42 | 0.0  | 0.77        | 0.563 | 31.5      | No ( $N_L > 30$ )             |
| CU-38  | 100.00 | 0.204 | Triaxial | Undrain | 0.42 | 0.0  | 0.78        | 0.56  | 18.1      | Yes                           |
| CU-39  | 100.00 | 0.127 | Triaxial | Undrain | 0.42 | 0.0  | 0.8         | 0.558 | 159.2     | No ( $N_L > 30$ )             |
| CU-40  | 100.00 | 0.224 | Triaxial | Undrain | 0.42 | 0.0  | 0.79        | 0.56  | 7.0       | Yes                           |
| CU-41  | 100.00 | 0.078 | Triaxial | Undrain | 0.31 | 10.0 | 0.17        | 0.655 | 62.4      | No ( $N_L > 30$ )             |
| CU-42  | 100.00 | 0.129 | Triaxial | Undrain | 0.31 | 10.0 | 0.2         | 0.649 | 5.0       | Yes                           |
| CU-43  | 100.00 | 0.104 | Triaxial | Undrain | 0.31 | 10.0 | 0.17        | 0.655 | 16.0      | Yes                           |
| CU-44  | 100.00 | 0.104 | Triaxial | Undrain | 0.31 | 10.0 | 0.2         | 0.648 | 17.1      | Yes                           |
| CU-45  | 100.00 | 0.129 | Triaxial | Undrain | 0.31 | 10.0 | 0.2         | 0.649 | 6.0       | Yes                           |
| CU-46  | 100.00 | 0.103 | Triaxial | Undrain | 0.31 | 10.0 | 0.27        | 0.631 | 22.6      | Yes                           |
| CU-47  | 100.00 | 0.154 | Triaxial | Undrain | 0.31 | 10.0 | 0.27        | 0.632 | 5.2       | Yes                           |
| CU-48  | 100.00 | 0.052 | Triaxial | Undrain | 0.31 | 10.0 | 0.28        | 0.629 | 671.6     | No ( $N_L > 30$ )             |
| CU-49  | 100.00 | 0.102 | Triaxial | Undrain | 0.31 | 10.0 | 0.33        | 0.618 | 25.6      | Yes                           |
| CU-50  | 100.00 | 0.103 | Triaxial | Undrain | 0.31 | 10.0 | 0.3         | 0.625 | 30.8      | No ( $N_L > 30$ )             |
| CU-51  | 100.00 | 0.104 | Triaxial | Undrain | 0.31 | 10.0 | 0.44        | 0.59  | 48.6      | No ( $N_L > 30$ )             |
| CU-52  | 100.00 | 0.13  | Triaxial | Undrain | 0.31 | 10.0 | 0.46        | 0.586 | 16.3      | Yes                           |
| CU-53  | 100.00 | 0.155 | Triaxial | Undrain | 0.31 | 10.0 | 0.45        | 0.59  | 8.0       | Yes                           |
| CU-54  | 100.00 | 0.115 | Triaxial | Undrain | 0.31 | 10.0 | 0.47        | 0.585 | 24.9      | Yes                           |
| CU-55  | 100.00 | 0.188 | Triaxial | Undrain | 0.31 | 10.0 | 0.54        | 0.569 | 4.0       | Yes                           |
| CU-56  | 100.00 | 0.127 | Triaxial | Undrain | 0.31 | 10.0 | 0.53        | 0.571 | 66.8      | Yes                           |
| CU-57  | 100.00 | 0.155 | Triaxial | Undrain | 0.31 | 10.0 | 0.52        | 0.572 | 10.8      | Yes                           |
| CU-58  | 100.00 | 0.104 | Triaxial | Undrain | 0.31 | 10.0 | 0.54        | 0.568 | 72.8      | No ( $N_L > 30$ )             |
| CU-59  | 100.00 | 0.141 | Triaxial | Undrain | 0.31 | 10.0 | 0.72        | 0.523 | 37.9      | No ( $N_L > 30$ )             |
| CU-60  | 100.00 | 0.176 | Triaxial | Undrain | 0.31 | 10.0 | 0.71        | 0.528 | 14.9      | Yes                           |
| CU-61  | 100.00 | 0.102 | Triaxial | Undrain | 0.31 | 10.0 | 0.73        | 0.523 | 279.9     | No ( $N_L > 30$ )             |
| CU-62  | 100.00 | 0.197 | Triaxial | Undrain | 0.31 | 10.0 | 0.79        | 0.508 | 9.9       | Yes                           |
| CU-63  | 100.00 | 0.189 | Triaxial | Undrain | 0.31 | 10.0 | 0.78        | 0.51  | 15.9      | Yes                           |
| CU-64  | 100.00 | 0.128 | Triaxial | Undrain | 0.31 | 10.0 | 0.79        | 0.508 | 109.1     | No ( $N_L > 30$ )             |
| CU-65  | 100.00 | 0.102 | Triaxial | Undrain | 0.31 | 10.0 | 0.8         | 0.506 | 518.8     | No ( $N_L > 30$ )             |
| CU-66  | 100.00 | 0.269 | Triaxial | Undrain | 0.31 | 10.0 | 0.81        | 0.503 | 4.0       | Yes                           |
| CU-67  | 100.00 | 0.179 | Triaxial | Undrain | 0.31 | 10.0 | 0.81        | 0.504 | 35.4      | No ( $N_L > 30$ )             |
| CU-68  | 100.00 | 0.243 | Triaxial | Undrain | 0.31 | 10.0 | 0.8         | 0.505 | 7.1       | Yes                           |
| CU-69  | 100.00 | 0.103 | Triaxial | Undrain | 0.25 | 20.0 | 0.19        | 0.681 | 11.1      | Yes                           |
| CU-70  | 100.00 | 0.078 | Triaxial | Undrain | 0.25 | 20.0 | 0.19        | 0.682 | 50.7      | No ( $N_L > 30$ )             |
| CU-71  | 100.00 | 0.091 | Triaxial | Undrain | 0.25 | 20.0 | 0.31        | 0.64  | 32.7      | No ( $N_L > 30$ )             |
| CU-72  | 100.00 | 0.104 | Triaxial | Undrain | 0.25 | 20.0 | 0.29        | 0.646 | 14.8      | Yes                           |
| CU-73  | 100.00 | 0.077 | Triaxial | Undrain | 0.25 | 20.0 | 0.3         | 0.643 | 77.0      | No ( $N_L > 30$ )             |
| CU-74  | 100.00 | 0.052 | Triaxial | Undrain | 0.25 | 20.0 | 0.44        | 0.596 | 556.0     | No ( $N_L > 30$ )             |
| CU-75  | 100.00 | 0.077 | Triaxial | Undrain | 0.25 | 20.0 | 0.46        | 0.591 | 106.4     | No ( $N_L > 30$ )             |
| CU-76  | 100.00 | 0.103 | Triaxial | Undrain | 0.25 | 20.0 | 0.43        | 0.599 | 25.5      | Yes                           |
| CU-77  | 100.00 | 0.129 | Triaxial | Undrain | 0.25 | 20.0 | 0.44        | 0.596 | 12.1      | Yes                           |
| CU-78  | 100.00 | 0.142 | Triaxial | Undrain | 0.25 | 20.0 | 0.46        | 0.599 | 6.0       | Yes                           |
| CU-79  | 100.00 | 0.102 | Triaxial | Undrain | 0.25 | 20.0 | 0.67        | 0.521 | 108.7     | No ( $N_L > 30$ )             |
| CU-80  | 100.00 | 0.179 | Triaxial | Undrain | 0.25 | 20.0 | 0.66        | 0.524 | 12.0      | Yes                           |
| CU-81  | 100.00 | 0.141 | Triaxial | Undrain | 0.25 | 20.0 | 0.66        | 0.523 | 30.7      | No ( $N_L > 30$ )             |
| CU-82  | 100.00 | 0.183 | Triaxial | Undrain | 0.25 | 20.0 | 0.8         | 0.478 | 27.3      | Yes                           |
| CU-83  | 100.00 | 0.102 | Triaxial | Undrain | 0.25 | 20.0 | 0.8         | 0.477 | 695.0     | No ( $N_L > 30$ )             |
| CU-84  | 100.00 | 0.194 | Triaxial | Undrain | 0.25 | 20.0 | 0.81        | 0.472 | 13.0      | Yes                           |
| CU-85  | 100.00 | 0.128 | Triaxial | Undrain | 0.25 | 20.0 | 0.8         | 0.475 | 101.9     | No ( $N_L > 30$ )             |
| CU-86  | 100.00 | 0.229 | Triaxial | Undrain | 0.25 | 20.0 | 0.9         | 0.443 | 13.0      | Yes                           |
| CU-87  | 100.00 | 0.127 | Triaxial | Undrain | 0.25 | 20.0 | 0.91        | 0.441 | 832.1     | No ( $N_L > 30$ )             |
| CU-88  | 100.00 | 0.178 | Triaxial | Undrain | 0.25 | 20.0 | 0.91        | 0.439 | 70.6      | No ( $N_L > 30$ )             |
| CU-89  | 50.00  | 0.152 | Triaxial | Undrain | 0.42 | 0.0  | 0.52        | 0.605 | 40.0      | No ( $N_L > 30$ )             |
| CU-90  | 50.00  | 0.127 | Triaxial | Undrain | 0.42 | 0.0  | 0.52        | 0.603 | 89.4      | No ( $N_L > 30$ )             |
| CU-91  | 50.00  | 0.178 | Triaxial | Undrain | 0.42 | 0.0  | 0.54        | 0.602 | 20.1      | Yes                           |
| CU-92  | 50.00  | 0.102 | Triaxial | Undrain | 0.42 | 0.0  | 0.54        | 0.601 | 545.1     | No ( $N_L > 30$ )             |
| CU-93  | 100.00 | 0.18  | Triaxial | Undrain | 0.42 | 0.0  | 0.54        | 0.601 | 14.3      | Yes                           |
| CU-94  | 100.00 | 0.128 | Triaxial | Undrain | 0.42 | 0.0  | 0.53        | 0.603 | 83.4      | No ( $N_L > 30$ )             |
| CU-95  | 100.00 | 0.153 | Triaxial | Undrain | 0.42 | 0.0  | 0.53        | 0.603 | 32.6      | No ( $N_L > 30$ )             |
| CU-96  | 100.00 | 0.102 | Triaxial | Undrain | 0.42 | 0.0  | 0.52        | 0.604 | 268.8     | No ( $N_L > 30$ )             |
| CU-97  | 200.00 | 0.102 | Triaxial | Undrain | 0.42 | 0.0  | 0.51        | 0.606 | 123.5     | No ( $N_L > 30$ )             |
| CU-98  | 200.00 | 0.128 | Triaxial | Undrain | 0.42 | 0.0  | 0.52        | 0.604 | 71.9      | No ( $N_L > 30$ )             |
| CU-99  | 200.00 | 0.179 | Triaxial | Undrain | 0.42 | 0.0  | 0.51        | 0.606 | 11.0      | Yes                           |
| CU-100 | 200.00 | 0.154 | Triaxial | Undrain | 0.42 | 0.0  | 0.52        | 0.604 | 27.0      | Yes                           |
| CU-101 | 50.00  | 0.178 | Triaxial | Undrain | 0.31 | 10.0 | 0.74        | 0.52  | 17.1      | Yes                           |
| CU-102 | 50.00  | 0.143 | Triaxial | Undrain | 0.31 | 10.0 | 0.74        | 0.52  | 54.4      | No ( $N_L > 30$ )             |
| CU-103 | 50.00  | 0.102 | Triaxial | Undrain | 0.31 | 10.0 | 0.71        | 0.526 | 629.8     | No ( $N_L > 30$ )             |
| CU-104 | 100.00 | 0.141 | Triaxial | Undrain | 0.31 | 10.0 | 0.72        | 0.523 | 38.6      | No ( $N_L > 30$ )             |
| CU-105 | 100.00 | 0.176 | Triaxial | Undrain | 0.31 | 10.0 | 0.71        | 0.528 | 14.8      | Yes                           |
| CU-106 | 100.00 | 0.102 | Triaxial | Undrain | 0.31 | 10.0 | 0.73        | 0.523 | 288.7     | No ( $N_L > 30$ )             |
| CU-107 | 200.00 | 0.179 | Triaxial | Undrain | 0.31 | 10.0 | 0.73        |       |           |                               |

|        |        |       |              |         |       |     |             |       |       |                   |                   |
|--------|--------|-------|--------------|---------|-------|-----|-------------|-------|-------|-------------------|-------------------|
| CU-91  | 100.00 | 0.075 | Triaxial     | Undrain | 0.26  | 0.0 | 0.38        | 0.731 | 40    | No ( $N_L > 30$ ) |                   |
| CU-92  | 100.00 | 0.075 | Triaxial     | Undrain | 0.26  | 0.0 | 0.43        | 0.71  | 43    | No ( $N_L > 30$ ) |                   |
| CU-93  | 100.00 | 0.05  | Triaxial     | Undrain | 0.26  | 0.0 | 0.36        | 0.738 | 123   | No ( $N_L > 30$ ) |                   |
| CU-94  | 100.00 | 0.15  | Triaxial     | Undrain | 0.26  | 0.0 | 0.34        | 0.746 | 1     | Yes               |                   |
| CU-95  | 100.00 | 0.05  | Triaxial     | Undrain | 0.26  | 0.0 | 0.7         | 0.591 | 3228  | No ( $N_L > 30$ ) |                   |
| CU-96  | 300.00 | 0.017 | Triaxial     | Undrain | 0.26  | 0.0 | 0.32        | 0.759 | 11000 | No ( $N_L > 30$ ) |                   |
| CU-97  | 250.00 | 0.03  | Triaxial     | Undrain | 0.26  | 0.0 | 0.32        | 0.759 | 5900  | No ( $N_L > 30$ ) |                   |
| CU-98  | 300.00 | 0.05  | Triaxial     | Undrain | 0.26  | 0.0 | 0.28        | 0.777 | 128   | No ( $N_L > 30$ ) |                   |
| CU-99  | 300.00 | 0.017 | Triaxial     | Undrain | 0.26  | 0.0 | 0.43        | 0.71  | 20000 | No ( $N_L > 30$ ) |                   |
| CU-100 | 136.00 | 0.036 | Triaxial     | Undrain | 0.26  | 0   | 0.26        | 0.5   | 17    | Yes               |                   |
| CU-101 | 138.00 | 0.036 | Triaxial     | Undrain | 0.26  | 0   | 0.22        | 0.7   | 73    | No ( $N_L > 30$ ) |                   |
| CU-102 | 138.00 | 0.036 | Triaxial     | Undrain | 0.26  | 0.0 | 0.25        | 0.8   | 86    | No ( $N_L > 30$ ) |                   |
| CU-34  | 100    | 0.234 | Triaxial     | Undrain | 0.53  | 0   | 0.524355301 | 0.74  | 6.5   |                   | Yes               |
| CU-35  | 100    | 0.183 | Triaxial     | Undrain | 0.53  | 0   | 0.553008596 | 0.73  | 25.5  |                   | Yes               |
| CU-36  | 100    | 0.181 | Triaxial     | Undrain | 0.53  | 0   | 0.638968481 | 0.7   | 150.5 |                   | No ( $N_L > 30$ ) |
| CU-37  | 100    | 0.336 | Triaxial     | Undrain | 0.53  | 0   | 0.638968481 | 0.7   | 4.5   | Yes               |                   |
| CU-38  | 100    | 0.304 | Triaxial     | Undrain | 0.53  | 0   | 0.81088252  | 0.64  | 14.5  | Yes               |                   |
| CU-39  | 100    | 0.243 | Triaxial     | Undrain | 0.53  | 0   | 0.81088252  | 0.64  | 12.5  | Yes               |                   |
| CU-40  | 200    | 0.285 | Triaxial     | Undrain | 0.53  | 0   | 0.467048711 | 0.76  | 1.5   | Yes               |                   |
| CU-41  | 100    | 0.253 | Triaxial     | Undrain | 0.53  | 0   | 0.467048711 | 0.76  | 3.5   | Yes               |                   |
| CU-42  | 100    | 0.207 | Triaxial     | Undrain | 0.53  | 0   | 0.553008596 | 0.73  | 15.5  | Yes               |                   |
| CU-43  | 100    | 0.162 | Triaxial     | Undrain | 0.53  | 0   | 0.553008596 | 0.73  | 617.8 | No ( $N_L > 30$ ) |                   |
| CU-44  | 100    | 0.33  | Triaxial     | Undrain | 0.53  | 0   | 0.638968481 | 0.7   | 8.5   | Yes               |                   |
| CU-45  | 100    | 0.198 | Triaxial     | Undrain | 0.53  | 0   | 0.799426934 | 0.644 | 27.5  | Yes               |                   |
| CU-46  | 100    | 0.244 | Triaxial     | Undrain | 0.53  | 0   | 0.618911175 | 0.707 | 8.5   | Yes               |                   |
| CU-47  | 100    | 0.414 | Triaxial     | Undrain | 0.53  | 0   | 0.965616046 | 0.586 | 85    | No ( $N_L > 30$ ) |                   |
| CU-48  | 100    | 0.288 | Triaxial     | Undrain | 0.53  | 0   | 0.982808023 | 0.58  | 220   | No ( $N_L > 30$ ) |                   |
| CU-49  | 100    | 0.208 | Triaxial     | Undrain | 0.53  | 0   | 0.979942693 | 0.581 | 920   | No ( $N_L > 30$ ) |                   |
| CU-50  | 100    | 0.391 | Triaxial     | Undrain | 0.53  | 0   | 0.977077364 | 0.582 | 120   | No ( $N_L > 30$ ) |                   |
| CU-1   | 99.3   | 0.24  | Simple shear | Undrain | 0.26  | 0   | 0.7         | 0.71  | 18    | Yes               |                   |
| CU-2   | 102.1  | 0.29  | Simple shear | Undrain | 0.26  | 0   | 0.69        | 0.71  | 16    | Yes               |                   |
| CU-3   | 100.4  | 0.19  | Simple shear | Undrain | 0.26  | 0   | 0.6         | 0.75  | 33    | No ( $N_L > 30$ ) |                   |
| CU-4   | 101.1  | 0.14  | Simple shear | Undrain | 0.26  | 0   | 0.54        | 0.77  | 45    | No ( $N_L > 30$ ) |                   |
| CU-5   | 101.6  | 0.19  | Simple shear | Undrain | 0.26  | 0   | 0.54        | 0.78  | 10    | Yes               |                   |
| CU-6   | 101.9  | 0.16  | Simple shear | Undrain | 0.26  | 0   | 0.53        | 0.78  | 9     | Yes               |                   |
| CU-7   | 102.9  | 0.32  | Simple shear | Undrain | 0.26  | 0   | 0.75        | 0.69  | 11.5  | Yes               |                   |
| CU-8   | 103.1  | 0.14  | Simple shear | Undrain | 0.26  | 0   | 0.62        | 0.74  | 160   | No ( $N_L > 30$ ) |                   |
| CU-9   | 104.7  | 0.22  | Simple shear | Undrain | 0.26  | 0   | 0.55        | 0.77  | 6     | Yes               |                   |
| CU-10  | 101.5  | 0.26  | Simple shear | Undrain | 0.26  | 0   | 0.69        | 0.71  | 17    | Yes               |                   |
| CU-11  | 103.2  | 0.26  | Simple shear | Undrain | 0.26  | 0   | 0.52        | 0.78  | 3     | Yes               |                   |
| CU-12  | 102.8  | 0.34  | Simple shear | Undrain | 0.26  | 0   | 0.69        | 0.72  | 9     | Yes               |                   |
| CU-13  | 103.4  | 0.21  | Simple shear | Undrain | 0.26  | 0   | 0.7         | 0.71  | 24    | Yes               |                   |
| CU-14  | 102.8  | 0.26  | Simple shear | Undrain | 0.26  | 0   | 0.62        | 0.74  | 10    | Yes               |                   |
| CU-15  | 103.4  | 0.39  | Simple shear | Undrain | 0.26  | 0   | 0.8         | 0.67  | 14    | Yes               |                   |
| CU-16  | 103.6  | 0.14  | Simple shear | Undrain | 0.26  | 0   | 0.55        | 0.77  | 25    | Yes               |                   |
| CU-17  | 104.7  | 0.29  | Simple shear | Undrain | 0.26  | 0   | 0.59        | 0.76  | 4     | Yes               |                   |
| CU-18  | 103.1  | 0.17  | Simple shear | Undrain | 0.26  | 0   | 0.72        | 0.7   | 46    | No ( $N_L > 30$ ) |                   |
| CU-19  | 102    | 0.4   | Simple shear | Undrain | 0.26  | 0   | 0.75        | 0.59  | 8     | Yes               |                   |
| CU-20  | 103.6  | 0.28  | Simple shear | Undrain | 0.26  | 0   | 0.59        | 0.75  | 4     | Yes               |                   |
| CU-21  | 103.3  | 0.12  | Simple shear | Undrain | 0.26  | 0   | 0.57        | 0.76  | 36    | No ( $N_L > 30$ ) |                   |
| CU-22  | 102.3  | 0.19  | Simple shear | Undrain | 0.26  | 0   | 0.66        | 0.73  | 37    | No ( $N_L > 30$ ) |                   |
| CU-23  | 103.5  | 0.2   | Simple shear | Undrain | 0.26  | 0   | 0.67        | 0.72  | 22    | Yes               |                   |
| CU-24  | 100    | 0.2   | Simple shear | Undrain | 0.26  | 0   | 0.62        | 0.74  | 16    | Yes               |                   |
| CU-25  | 100.6  | 0.19  | Simple shear | Undrain | 0.122 | 0   | 0.64        | 0.87  | 3     | Yes               |                   |
| CU-26  | 100.8  | 0.13  | Simple shear | Undrain | 0.122 | 0   | 0.71        | 0.84  | 38.5  | No ( $N_L > 30$ ) |                   |
| CU-27  | 103.2  | 0.16  | Simple shear | Undrain | 0.122 | 0   | 0.73        | 0.83  | 11    | Yes               |                   |
| CU-28  | 100.2  | 0.19  | Simple shear | Undrain | 0.122 | 0   | 0.85        | 0.77  | 20    | Yes               |                   |
| CU-29  | 98.6   | 0.25  | Simple shear | Undrain | 0.122 | 0   | 0.81        | 0.79  | 4     | Yes               |                   |
| CU-30  | 99     | 0.17  | Simple shear | Undrain | 0.122 | 0   | 0.77        | 0.81  | 15    | Yes               |                   |
| CU-31  | 98.9   | 0.13  | Simple shear | Undrain | 0.122 | 0   | 0.78        | 0.8   | 97    | No ( $N_L > 30$ ) |                   |
| CU-32  | 99.1   | 0.15  | Simple shear | Undrain | 0.122 | 0   | 0.77        | 0.81  | 29    | Yes               |                   |
| CU-33  | 101.6  | 0.21  | Simple shear | Undrain | 0.122 | 0   | 0.75        | 0.82  | 6     | Yes               |                   |
| CU-34  | 105.8  | 0.25  | Simple shear | Undrain | 0.122 | 0   | 0.72        | 0.83  | 4     | Yes               |                   |
| CU-35  | 103.9  | 0.29  | Simple shear | Undrain | 0.122 | 0   | 0.74        | 0.82  | 3     | Yes               |                   |
| CU-44  | 100.3  | 0.2   | Simple shear | Undrain | 0.102 | 30  | 0.73        | 0.8   | 6     | Yes               |                   |
| CU-45  | 98.8   | 0.19  | Simple shear | Undrain | 0.102 | 30  | 0.77        | 0.77  | 9     | Yes               |                   |
| CU-46  | 100.6  | 0.16  | Simple shear | Undrain | 0.102 | 30  | 0.72        | 0.81  | 6     | Yes               |                   |
| CU-47  | 100.8  | 0.14  | Simple shear | Undrain | 0.102 | 30  | 0.75        | 0.78  | 23    | Yes               |                   |
| CU-48  | 101.9  | 0.16  | Simple shear | Undrain | 0.102 | 30  | 0.87        | 0.71  | 84    | No ( $N_L > 30$ ) |                   |
| CU-49  | 101.9  | 0.24  | Simple shear | Undrain | 0.102 | 30  | 0.79        | 0.76  | 7     | Yes               |                   |
| CU-50  | 102.8  | 0.18  | Simple shear | Undrain | 0.102 | 30  | 0.82        | 0.74  | 15    | Yes               |                   |
| CU-51  | 103.8  | 0.16  | Simple shear | Undrain | 0.102 | 30  | 0.83        | 0.73  | 35    | No ( $N_L > 30$ ) |                   |
| CU-52  | 101    | 0.32  | Simple shear | Undrain | 0.102 | 30  | 0.8         | 0.75  | 6     | Yes               |                   |
| CU-53  | 102    | 0.26  | Simple shear | Undrain | 0.102 | 30  | 0.76        | 0.78  | 4     | Yes               |                   |
| CU-54  | 103.1  | 0.17  | Simple shear | Undrain | 0.102 | 30  | 0.75        | 0.79  | 14    | Yes               |                   |
| CU-55  | 100    | 0.19  | Simple shear | Undrain | 0.071 | 53  | 0.79        | 0.74  | 9     | Yes               |                   |
| CU-56  | 102    | 0.17  | Simple shear | Undrain | 0.071 | 53  | 0.74        | 0.77  | 15    | Yes               |                   |
| CU-57  | 101.4  | 0.2   | Simple shear | Undrain | 0.071 | 53  | 0.84        | 0.71  | 12    | Yes               |                   |
| CU-58  | 102.9  | 0.16  | Simple shear | Undrain | 0.071 | 53  | 0.78        | 0.74  | 23    | Yes               |                   |
| CU-59  | 102.6  | 0.26  | Simple shear | Undrain | 0.071 | 53  | 0.82        | 0.72  | 6     | Yes               |                   |
| CU-60  | 101.4  | 0.13  | Simple shear | Undrain | 0.071 | 53  | 0.74        | 0.77  | 54    | No ( $N_L > 30$ ) |                   |
| CU-61  | 103.3  | 0.25  | Simple shear | Undrain | 0.071 | 53  | 0.73        | 0.77  | 4     | Yes               |                   |
| CU-62  | 107    | 0.31  | Simple shear | Undrain | 0.071 | 53  | 0.77        | 0.75  | 4     | Yes               |                   |
| CU-63  | 101.7  | 0.18  | Simple shear | Undrain | 0.026 | 100 | 0.87        | 0.81  | 8     | Yes               |                   |
| CU-64  | 103.1  | 0.13  | Simple shear | Undrain | 0.026 | 100 | 0.82        | 0.84  | 26    | Yes               |                   |
| CU-65  | 102.4  | 0.2   | Simple shear | Undrain | 0.026 | 100 | 0.84        | 0.82  | 5     | Yes               |                   |
| CU-66  | 104    | 0.15  | Simple shear | Undrain | 0.026 | 100 | 0.83        | 0.84  | 10    | Yes               |                   |
| CU-67  | 100.9  | 0.19  | Simple shear | Undrain | 0.201 | 30  | 0.66        | 0.61  | 13    | Yes               |                   |
| CU-68  | 98.7   | 0.25  | Simple shear | Undrain | 0.201 | 30  | 0.58        | 0.65  | 4     | Yes               |                   |
| CU-69  | 99.1   | 0.19  | Simple shear | Undrain | 0.201 | 30  | 0.53        | 0.67  | 5     | Yes               |                   |
| CU-70  | 101.4  | 0.14  | Simple shear | Undrain | 0.201 | 30  | 0.53        | 0.67  | 23    | Yes               |                   |
| CU-71  | 100.6  | 0.16  | Simple shear | Undrain | 0.201 | 30  | 0.66        | 0.61  | 37    | No ( $N_L > 30$ ) |                   |
| CU-72  | 101.2  | 0.16  | Simple shear | Undrain | 0.201 | 30  | 0.61        | 0.64  | 17    | Yes               |                   |
| CU-30  | 400    | 0.036 | Triaxial     | Undrain | 0.21  | 0   | 0.1         | 0.9   | 1000  | No ( $N_L > 30$ ) |                   |
| CU-31  | 400    | 0.06  | Triaxial     | Undrain | 0.21  | 0   | 0.1         | 0.9   | 23    | Yes               |                   |
| CU-32  | 400    | 0.1   | Triaxial     | Undrain | 0.21  | 0   | 0.1         | 0.9   | 7     | Yes               |                   |
| CU-33  | 400    | 0.18  | Triaxial     | Undrain | 0.21  | 0   | 0.5         | 0.74  | 8     | Yes               |                   |
| CU-34  | 400    | 0.14  | Triaxial     | Undrain | 0.21  | 0   | 0.5         | 0.74  |       |                   |                   |
| CU-35  | 400    | 0.13  | Triaxial     | Undrain | 0.21  | 0   | 0.5         | 0.74  |       |                   |                   |
| CU-1   | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.55        | 0.738 | 7     | Yes               |                   |
| CU-2   | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.55        | 0.735 | 25    | Yes               |                   |
| CU-3   | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.55        | 0.732 | 10    | Yes               |                   |
| CU-4   | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.55        | 0.732 | 17    | Yes               |                   |
| CU-5   | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.55        | 0.743 | 65    | No ( $N_L > 30$ ) |                   |
| CU-6   | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.47        | 0.881 | 6.5   | Yes               |                   |
| CU-7   | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.47        | 0.884 | 3     | Yes               |                   |
| CU-8   | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.47        | 0.889 | 12    | Yes               |                   |
| CU-9   | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.47        | 0.871 | 79    | No ( $N_L > 30$ ) |                   |
| CU-10  | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.47        | 0.859 | 58    | No ( $N_L > 30$ ) |                   |
| CU-11  | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.8         | 0.795 | 36    | No ( $N_L > 30$ ) |                   |
| CU-12  | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.8         | 0.79  | 55    | No ( $N_L > 30$ ) |                   |
| CU-13  | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.8         | 0.785 | 28    | Yes               |                   |
| CU-14  | 60     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.8         | 0.774 | 12    | Yes               |                   |
| CU-15  | 78     | 0     | Triaxial     | Undrain | 0.33  | 0   | 0.64        | 0.61  | 15.3  | Yes               |                   |
| CU-16  | 78     | 0     | Triaxial     | Undrain | 0.33  | 0   | 0.64        | 0.616 | 23    | Yes               |                   |
| CU-17  | 78     | 0     | Triaxial     | Undrain | 0.33  | 0   | 0.64        | 0.618 | 27    | Yes               |                   |
| CU-18  | 78     | 0     | Triaxial     | Undrain | 0.33  | 0   | 0.64        | 0.639 | 66.6  | No ( $N_L > 30$ ) |                   |
| CU-19  | 78     | 0     | Triaxial     | Undrain | 0.33  | 0   | 0.64        | 0.626 | 6.3   | Yes               |                   |
| CU-20  | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.55        | 0.738 | 7     | Yes               |                   |
| CU-21  | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.56        | 0.735 | 25    | Yes               |                   |
| CU-22  | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.57        | 0.732 | 10    | Yes               |                   |
| CU-23  | 75     | 0     | Triaxial     | Undrain | 0.15  | 0   | 0.57        | 0.732 | 17    | Yes               |                   |
| CU-24  | 75     |       |              |         |       |     |             |       |       |                   |                   |

|        |     |       |              |         |      |   |       |       |      |                   |
|--------|-----|-------|--------------|---------|------|---|-------|-------|------|-------------------|
| CU-38  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 19   | Yes               |
| CU-39  | 97  | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.43  | 0.68  | 23.5 | Yes               |
| CU-40  | 101 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.43  | 0.688 | 24   | Yes               |
| CU-41  | 98  | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.68  | 23   | Yes               |
| CU-42  | 103 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 24   | Yes               |
| CU-43  | 102 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.689 | 37   | No ( $N_v > 30$ ) |
| CU-44  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.42  | 0.685 | 39   | No ( $N_v > 30$ ) |
| CU-45  | 103 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 60   | No ( $N_v > 30$ ) |
| CU-46  | 100 | 0.135 | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 11.5 | Yes               |
| CU-47  | 100 | 0.112 | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.691 | 19   | Yes               |
| CU-48  | 100 | 0.095 | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 28   | Yes               |
| CU-49  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 7    | Yes               |
| CU-50  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.688 | 6    | Yes               |
| CU-51  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.689 | 7    | Yes               |
| CU-52  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.69  | 12   | Yes               |
| CU-53  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.689 | 16   | Yes               |
| CU-54  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.69  | 44   | No ( $N_v > 30$ ) |
| CU-55  | 100 | 0.2   | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.689 | 3    | Yes               |
| CU-56  | 100 | 0.175 | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.687 | 5    | Yes               |
| CU-57  | 100 | 0.147 | Triaxial     | Undrain | 0.4  | 0 | 0.415 | 0.688 | 26   | Yes               |
| CU-58  | 100 | 0.127 | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 37   | No ( $N_v > 30$ ) |
| CU-59  | 106 | 0.22  | Simple shear | Undrain | 0.4  | 0 | 0.38  | 0.696 | 1    | Yes               |
| CU-60  | 106 | 0.145 | Simple shear | Undrain | 0.4  | 0 | 0.39  | 0.696 | 6    | Yes               |
| CU-61  | 102 | 0.121 | Simple shear | Undrain | 0.4  | 0 | 0.34  | 0.712 | 16   | Yes               |
| CU-62  | 81  | 0.255 | Simple shear | Undrain | 0.4  | 0 | 0.32  | 0.717 | 1    | Yes               |
| CU-63  | 107 | 0.107 | Simple shear | Undrain | 0.4  | 0 | 0.38  | 0.699 | 26   | Yes               |
| CU-64  | 106 | 0.08  | Simple shear | Undrain | 0.4  | 0 | 0.415 | 0.687 | 155  | No ( $N_v > 30$ ) |
| CU-65  | 107 | 0.095 | Simple shear | Undrain | 0.4  | 0 | 0.41  | 0.689 | 53   | No ( $N_v > 30$ ) |
| CU-66  | 104 | 0.146 | Simple shear | Undrain | 0.4  | 0 | 0.38  | 0.699 | 5    | Yes               |
| CU-67  | 105 | 0.09  | Simple shear | Undrain | 0.4  | 0 | 0.41  | 0.689 | 150  | No ( $N_v > 30$ ) |
| CU-68  | 78  | 0.1   | Triaxial     | Undrain | 0.4  | 0 | 0.5   | 0.635 | 250  | No ( $N_v > 30$ ) |
| CU-69  | 78  | 0.14  | Triaxial     | Undrain | 0.4  | 0 | 0.49  | 0.638 | 45   | No ( $N_v > 30$ ) |
| CU-70  | 78  | 0.15  | Triaxial     | Undrain | 0.4  | 0 | 0.5   | 0.636 | 26   | Yes               |
| CU-71  | 78  | 0.175 | Triaxial     | Undrain | 0.33 | 0 | 0.51  | 0.633 | 16.5 | Yes               |
| CU-72  | 78  | 0.205 | Triaxial     | Undrain | 0.33 | 0 | 0.51  | 0.632 | 8    | Yes               |
| CU-73  | 78  | 0     | Triaxial     | Undrain | 0.33 | 0 | 0.52  | 0.626 | 6.3  | Yes               |
| CU-74  | 78  | 0     | Triaxial     | Undrain | 0.33 | 0 | 0.53  | 0.622 | 15.3 | Yes               |
| CU-75  | 78  | 0     | Triaxial     | Undrain | 0.33 | 0 | 0.53  | 0.621 | 23   | Yes               |
| CU-76  | 78  | 0     | Triaxial     | Undrain | 0.33 | 0 | 0.54  | 0.618 | 27   | Yes               |
| CU-77  | 78  | 0     | Triaxial     | Undrain | 0.33 | 0 | 0.49  | 0.639 | 66.6 | No ( $N_v > 30$ ) |
| CU-78  | 78  | 0.175 | Triaxial     | Undrain | 0.33 | 0 | 0.54  | 0.62  | 6    | Yes               |
| CU-79  | 78  | 0.125 | Triaxial     | Undrain | 0.33 | 0 | 0.53  | 0.622 | 15   | Yes               |
| CU-80  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.55  | 0.738 | 7    | Yes               |
| CU-81  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.56  | 0.735 | 25   | Yes               |
| CU-82  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.57  | 0.732 | 10   | Yes               |
| CU-83  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.57  | 0.732 | 17   | Yes               |
| CU-84  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.535 | 0.743 | 65   | No ( $N_v > 30$ ) |
| CU-85  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.55  | 0.738 | 3    | Yes               |
| CU-86  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.55  | 0.737 | 4    | Yes               |
| CU-87  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.545 | 0.74  | 7    | Yes               |
| CU-88  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.55  | 0.739 | 16   | Yes               |
| CU-89  | 75  | 0     | Triaxial     | Undrain | 0.15 | 0 | 0.545 | 0.74  | 29   | Yes               |
| CU-90  | 75  | 0.18  | Triaxial     | Undrain | 0.15 | 0 | 0.56  | 0.735 | 72   | Yes               |
| CU-91  | 75  | 0.209 | Triaxial     | Undrain | 0.15 | 0 | 0.557 | 0.736 | 28   | Yes               |
| CU-92  | 75  | 0.228 | Triaxial     | Undrain | 0.15 | 0 | 0.54  | 0.741 | 14   | Yes               |
| CU-93  | 75  | 0.241 | Triaxial     | Undrain | 0.15 | 0 | 0.545 | 0.74  | 10   | Yes               |
| CU-94  | 75  | 0.27  | Triaxial     | Undrain | 0.15 | 0 | 0.555 | 0.737 | 4    | Yes               |
| CU-95  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 7    | Yes               |
| CU-96  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.687 | 9.5  | Yes               |
| CU-97  | 96  | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 15   | Yes               |
| CU-98  | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 19   | Yes               |
| CU-99  | 97  | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.43  | 0.68  | 23.5 | Yes               |
| CU-100 | 101 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.43  | 0.688 | 24   | Yes               |
| CU-101 | 98  | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.68  | 23   | Yes               |
| CU-102 | 103 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 24   | Yes               |
| CU-103 | 102 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.689 | 37   | No ( $N_v > 30$ ) |
| CU-104 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.42  | 0.685 | 39   | No ( $N_v > 30$ ) |
| CU-105 | 103 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 60   | No ( $N_v > 30$ ) |
| CU-106 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 7    | Yes               |
| CU-107 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.688 | 6    | Yes               |
| CU-108 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.689 | 7    | Yes               |
| CU-109 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.69  | 12   | Yes               |
| CU-110 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.689 | 16   | Yes               |
| CU-111 | 100 | 0     | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.69  | 44   | No ( $N_v > 30$ ) |
| CU-112 | 100 | 0.2   | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.689 | 3    | Yes               |
| CU-113 | 100 | 0.175 | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.687 | 5    | Yes               |
| CU-114 | 100 | 0.147 | Triaxial     | Undrain | 0.4  | 0 | 0.41  | 0.688 | 26   | Yes               |
| CU-115 | 100 | 0.127 | Triaxial     | Undrain | 0.4  | 0 | 0.4   | 0.688 | 37   | No ( $N_v > 30$ ) |
| CU-116 | 100 | 0     | Simple shear | Undrain | 0.4  | 0 | 0.38  | 0.698 | 8    | Yes               |
| CU-117 | 100 | 0     | Simple shear | Undrain | 0.4  | 0 | 0.375 | 0.7   | 11   | Yes               |
| CU-118 | 100 | 0     | Simple shear | Undrain | 0.4  | 0 | 0.406 | 0.69  | 30   | Yes               |
| CU-119 | 100 | 0     | Simple shear | Undrain | 0.4  | 0 | 0.406 | 0.69  | 180  | No ( $N_v > 30$ ) |