

BYOSOFT Flash Update Release Notes

Document Revision 1.0
October 18, 2018
All Rights Reserved
Property of Byosoft Co., Ltd.



Byosoft Co., Ltd.

Byosoft Flash Update Release



Declaration

Copyright Notice

Byosoft copyrights this specification. No part of this specification may be reproduced, transcribed, stored in a retrieval system, or translated into any language or computer language, in any form or by any means, without the prior written consent of Byosoft. All texts, images, illustrations and other material on this specification are subject to copyright held by Byosoft Co., Ltd. Otherwise Byosoft will have the right to pursue legal responsibilities.

Disclaimer

This document is made by Byosoft Co., Ltd. The contents of this document are confidential and proprietary to Byosoft Company Limited. And the Byosoft Company makes no representation or warranties, either expressed or implied, with regard to the contents for this document, its merchantability, or fitness for any particular purpose. This document should not be disclosed to any third party.

This Document is preliminary and is subject to change at any time without notice. Byosoft assumes no responsibility for any errors contained herein and reader decisions based on such use. The company shall not be liable for any direct, indirect, incidental or consequential loss, expense or damage of any kind arising out of the use of this document or from the document's support.

Trademark and Copyright Informations

Copyright © 2006-2020, Byosoft Co., Ltd. All Rights Reserved.

Byosoft Co., Ltd. 11 Floor, Chuangzhi Building A No.17 Xinghuo Road Gaoxin Area Nanjing Jiangsu

If you have any question, Please call Byosoft Co., Ltd. at 025-58649728 for additional information.







TABLE OF CONTENTS

Change History	. 4
Overview	. 5
Audience	. 5
Operating System Support	. 5
Different Tool Components	. 5
Revison History	. 6
Known Issues	. 6
Fixed Issues in this Release Version	. 7



Byosoft Co., Ltd.

Byosoft Flash Update Release



Change History

Version	Description	Date
V 1.0	Byosoft Flash Update Release Notes created	2018.8.16





Overview

This document provides information about Byosoft Flash Tool releases, including revision information, bugs fixed, functions updates, known issues, compatibility updates etc. Byosoft Flash Tool requires to be supported on platforms with Byosoft BIOS firmware image installed.

Audience


Generic BIOS Engineers, OEM Engineers, Byosoft BIOS Customers.

Operating System Support

- Microsoft Window 10 (64 bit)
- Microsoft Window 10 (32 bit)
- Microsoft Window 8.1 (64 bit)
- Microsoft Window 8.1 (32 bit)
- Microsoft Window 8 (64 bit)
- Microsoft Window 8 (32 bit)
- Microsoft Window 7 (64 bit)
- Microsoft Window 7 (32 bit)
- EFI Shell
- Microsoft Windows Server 2019
- uos20-4.19.0-6
- CentOS-7.6.1810

Different Tool Components

Tool Name	OS Environment		
ByoShellFlash	Byosoft Firmware Update utility for Shell		
ByoWinFlash	Byosoft Firmware Update utility for Windows		
BYOFLASH Byosoft Firmware Update utility for DOS			
flash	Byosoft Firmware Update utility for Linux		






Revison History

Date	Revision	Description
2018-01-06	V3.0.0	Release of version 3.0.0
2018-10-16	V3.0.1	Release of version 3.0.1
2019-01-07	V3.0.2	Release of version 3.0.2
2019-01-29	V3.0.3	Release of version 3.0.3
2019-02-22	V3.0.4	Release of version 3.0.4
2019-05-06	V3.0.5	Release of version 3.0.5
2019-05-08	V3.10.0(ZX)	Release of version 3.10.0(ZX)
2019-05-15	V3.10.1(ZX)	Release of version 3.10.1(ZX)
2019-05-16	V3.10.2(ZX)	Release of version 3.10.2(ZX)
2019-05-16	V3.10.3(ZX)	Release of version 3.10.3(ZX)
2019-05-20	V3.10.4(ZX)	Release of version 3.10.4(ZX)
2019-06-18	V3.10.5(ZX)	Release of version 3.10.5(ZX)
2019-06-20	V3.10.6(ZX)	Release of version 3.10.6(ZX)
2019-06-28	V3.10.7(ZX)	Release of version 3.10.7(ZX)
2019-07-28	V3.10.8(ZX)	Release of version 3.10.8(ZX)
2019-08-19	V3.10.9(ZX)	Release of version 3.10.9(ZX)
2019-10-09	V3.10.10(ZX)	Release of version 3.10.10(ZX)
2019-11-08	V3.10.11(ZX)	Release of version 3.10.11(ZX)
2020-03-09	V3.10.12	Release of version 3.10.12
2020-03-23	V3.10.13	Release of version 3.10.13
2020-03-31	V3.10.14	Release of version 3.10.14
2020-04-03	V3.10.15	Release of version 3.10.15
2020-04-08	V3.10.16	Release of version 3.10.16
2020-06-01	V3.10.17	Release of version 3.10.17
2020-06-12	V3.10.18	Release of version 3.10.18

Known Issues


...





Fixed Issues in this Release Version


Tool Name	Version	OS	Issues Description
ByoFlash ByoShellFlash ByoLinuxFlash ByoWinFlash	V3.0.1	DOS Shell Linux Windows	 Remove the Pcd which depend on platform from tool. Revise error return code. Add show and compare bios version function. Revise windows ufu driver Sometimes incorrect return value.
ByoLinuxFlash ByoLinuxFlash	V3.0.2	Linux Shell	 Add keyboard input blocking feature when update bios in Linux. Change the method of allocate memory in Shell.
ByoFlash ByoShellFlash ByoLinuxFlash ByoWinFlash	V3.0.3	DOS Shell Linux Windows	 Fixed shows unexpect message"unable to find device 12/13" under Ubuntu17.10 after flash bios. Add SmmPort support for AMD and zhaoxin Shanghai. Tune buffer allocation for flash tool. Fixed Flash tool assert under EFI shell with debug bios.
ByoFlash ByoShellFlash ByoLinuxFlash ByoWinFlash	V3.0.4	DOS Shell Linux Windows	 Automatically create device number and device node of FlashUpdate Tool. Clear redundant code of FlashUpdate tool. Fix Dos version cannot run on AMD Platform.
ByoFlash ByoShellFlash ByoLinuxFlash ByoWinFlash	V3.0.5	DOS Shell Linux Windows	 Add backup file prompt. Add SLP2.0 Windows key support.
ByoFlash ByoShellFlash ByoLinuxFlash ByoWinFlash	V3.10.0(ZX)	DOS Shell Linux Windows	 Base on 3.0.5, create tool branch for ZX. Add dmi lock & unlock interface. Add long string update support for smbios type 11. (-msl)
ByoFlash ByoShellFlash ByoLinuxFlash ByoWinFlash	V3.10.1(ZX)	DOS Shell Linux Windows	 Support clear password and clear oem logo. support -resvoem and -resvnvm with -all even if there is no related bios info in byo bios info 2 table.







		T	
ByoShellFlash ByoWinFlash	V3.10.2(ZX)	Shell Windows	 auto request admin authority in windows version. add rmlogo and rstpwd prompt. Update dmi update parameter description. (-t and -o is hex)
ByoShellFlash ByoWinFlash	V3.10.3(ZX)	Shell Windows	In multi-command string update(type 11 with more than 64 byte), buffer should be cleared each time.
ByoShellFlash ByoWinFlash	V3.10.4(ZX)	Shell Windows	 Fix bug11295: Update type 11 successfully via flash tool when enter 257 characters(max 256) Update help info about dmi.
ByoShellFlash ByoWinFlash	V3.10.5(ZX)	Shell Windows	Update string from "Flash region has been locked, please unlock it in BIOS setup" to "Access denied".
ByoShellFlash ByoWinFlash	V3.10.6(ZX)	Shell Windows	There is a coding error in file reading under shell which may cause cpu exception sometimes.
ByoShellFlash ByoWinFlash	V3.10.7(ZX)	Shell Windows	Add new parameter "-locksts" to get current lock status.
ByoShellFlash ByoWinFlash	V3.10.8(ZX)	Shell Windows	 Send tool version to bios to support version match check. If bios return "-all" is not supported, directly exit and return "deny".
ByoShellFlash ByoWinFlash	V3.10.9(ZX)	Shell Windows	1. Add bios sign verify support.
ByoShellFlash ByoWinFlash	V3.10.10(ZX)	Shell Windows	 malloc memory type from nvs to bs data under UEFI tool. fix assert in debug version if bios file ext name is not "bin". do not read current bios if update mode is logo.
ByoShellFlash ByoWinFlash	V3.10.11(ZX)	Shell Windows	1. support ucode update.







ByoShellFlash ByoWinFlash	V3.10.12	Shell Windows	 remove parameter -resvoem and -resvnvm. copyright year 2020. prompt user before and after bios update. hide OA3 and smbios update interfaces in windows UI.
BYOFLASH ByoShellFlash flash ByoWinFlash	V3.10.13	DOS Shell Linux Windows	 copyright year 2020. Adapt to uos20-4.19.0-6 and CentOS-7.6.1810 Make tool can't update and add prompt message when no file is selected in windows UI. Fix compilation errors.
ByoWinFlash	V3.10.14	Windows	Fix that if we choice logo file, then do bios update, tool will not prompt NO BIOS FILE SELECTED.
ByoWinFlash	V3.10.15	Windows	 Fix bug that: a. Select logo file but not to update. b. Then select "Update to new BIOS" and select bios file but not to update. c. select again logo to update. d. Update failed and show error message.
ByoWinFlash	V3.10.16	DOS Shell Linux Windows	1. add warning message when flash update.("During bios updating, Please DO NOT shutdown or reset system")
ByoWinFlash	V3.10.17	DOS Shell Linux Windows	Default enables "resvoem" and "resvnvm" status to back compatible with old bios.
ByoWinFlash	V3.10.18	DOS Shell Linux Windows	1. if parameter is "-all", do not keep NVRAM and SMBIOS.

