

BYOSOFT System Configuration Utility Release Notes

Document Revision 1.0

October 16, 2018

All Rights Reserved

Property of Byosoft Co., Ltd.



Byosoft Co., Ltd. BYOSOFT System Configuration Utility Release Notes



Declaration

Copyright Notice

Byosoft copyrights this specification. No part of this specification may be reproduced, transcribed, stored in a retrieval system, or translated into any language or computer language, in any form or by any means, without the prior written consent of Byosoft. All texts, images, illustrations and other material on this specification are subject to copyright held by Byosoft Co., Ltd. Otherwise Byosoft will have the right to pursue legal responsibilities.

Disclaimer

This document is made by Byosoft Co., Ltd. The contents of this document are confidential and proprietary to Byosoft Company Limited. And the Byosoft Company makes no representation or warranties, either expressed or implied, with regard to the contents for this document, its merchantability, or fitness for any particular purpose. This document should not be disclosed to any third party.

This Document is preliminary and is subject to change at any time without notice. Byosoft assumes no responsibility for any errors contained herein and reader decisions based on such use. The company shall not be liable for any direct, indirect, incidental or consequential loss, expense or damage of any kind arising out of the use of this document or from the document's support.

Trademark and Copyright Informations

Copyright © 2018-2019, Byosoft Co., Ltd. All Rights Reserved.

Byosoft Co., Ltd. 11 Floor, Chuangzhi Building A No.17 Xinghuo Road Gaoxin Area Nanjing Jiangsu

If you have any question, Please call Byosoft Co., Ltd. at 025-58649728 for additional information.







TABLE OF CONTENTS

Change History	4
0verview	5
Audience	5
Operating System Support	5
Different Tool Components	5
Revison History	6
Known Issues	6
Fixed Issues in this Release Version	6




Byosoft Co., Ltd.

BYOSOFT System Configuration Utility Release Notes



Change History

Version	Description	Date
V 1.0	Byosoft System Configuration Utility Release Notes created	2018.10.16





Overview

This document provides information about Byosoft System Configuration Utility releases, including revision information, bugs fixed, functions updates, known issues, compatibility updates etc. Byosoft System Configuration Utility Tool requires to be supported on platforms with Byosoft BIOS firmware image installed.

Audience


Generic BIOS Engineers, OEM Engineers, Byosoft BIOS Customers.

Operating System Support

- ★ Microsoft Window 10 (64 bit)
- ★ EFI Shell
- ⋆ Ubuntu
- ★ CentOS

Different Tool Components

Tool Name	Version	OS Environment		
ByoShellScu 1.0.9		Byosoft System Configuration Utility for Shell		
ByoLinuxScu	1.0.9	Byosoft System Configuration Utility for Linux		
ByoWinScu 1.0.9		Byosoft System Configuration Utility for Windows		





Revison History

Date	Revision	Description
2018-11-07	V1.0.6	Release of version 1.0.6
2019-01-21	V1.0.7	Release of version 1.0.7
2019-01-28	V1.0.8	Release of version 1.0.8
2019-03-08	V1.0.9	Release of version 1.0.9

Known Issues

.....

Fixed Issues in this Release Version

Tool Name	Version	0S	Issues Description
ByoLinuxScu		Linux	Support SCU Tool can be used under Ubuntu 16.04
ByoShellScu	V1.0.7	Shell	Fixed SUT hang when load wrong xml file under Shell
ByoShellScu ByoLinuxScu ByoWinScu		Shell Linux Windows	Fixed Scu XML file cannot analysis with python
ByoLinuxScu	V1.0.8	Linux	SCU tool code integration and add Ubuntu17.10 code
ByoLinuxScu		Linux	Automatically create device number and device node of SCU Tool
ByoWinScu	V1.0.9	Windows	Fix BootOrder can not change under windows
ByoShellScu		Shell	Fixed SCU tool assert under EFI shell with debug bios

