


- 1. Select Gear > Network
- 2. ensure that the IP address under MA-Net Interface has a matching subnet with 2 port node
- 3. invite station and check that the PC and network node are highlighted green.



- 4. Select Gear > In and Out > OSC > Enable Input (should light up yellow)
- 5. Receive, Receive command & echo input switch to "Yes"
- 6. Interface set to laptop IP address
- 7. Set prefix to "gma3"
- 8. Set Page to "Page1"
- 9. Destination IP set to 2 port node IP address



10. On the main page, click on the blank space > Add window > All > type system monitor and select it



11. Cross check system monitor with Raspi

