

Sensors in Parallel Without Equilibar: Mean Removed Pressure Signals at Different RPMs
Upstream
Downstream
Upstream point
Downstream point
250 RPM (4.17 Hz)
500 RPM (8.33 Hz)
750 RPM (12.50 Hz)
1000 RPM (16.67 Hz)
Pressure fluctuation [bar]
0.2
0.1
0.0
−0.1
−0.2
0.00
0.05
0.10
0.15
0.20
0.25
Time [s]