
Sensors in Serie With Equilibar at 2250 mbar backpressure: Raw Pressure Signals at Different RPMs
Upstream
Downstream
Upstream point
Downstream point
250 RPM (4.17 Hz)
500 RPM (8.33 Hz)
750 RPM (12.50 Hz)
1000 RPM (16.67 Hz)
Pressure [bar]
3.0
2.5
2.0
1.5
1.0
0.5
0.0
0.00
0.05
0.10
0.15
0.20
0.25
Time [s]