

BC26 Release Notes

LPWA Module Series

Rev. BC26-NC_Firmware_Release_Notes_V0106

Date: 2019-03-29



1. Preamble

This document provides the Release Notes for BC26 firmware version **BC26NCR01A06**. It describes major changes compared to firmware version **BC26NCR01A03**. For a detailed listing of all changes, refer to the BC26 AT Command Set.

2. New Features

Item /Category	Brief Description	Since
DFOTA	Added DFOTA over CT IOT platform feature.	R01A06
MQTT	Added data mode transfer mechanism for MQTT.	R01A06
GENERAL	Supported all in one mode of OpenCPU and Standard module.	R01A06
RI	Added RI feature for URC indicating.	R01A06
TCPIP	Added data mode transfer mechanism for TCP/UDP.	R01A06
LwM2M	Added AT+QLWGETERROR command for quering the last error code of LwM2M operation.	R01A06
TCPIP	Added AT+QIDNSCFG command for DNS server configuration.	R01A06
OpenCPU	Supported upgrade APP bin file via DFOTA.	R01A06
OneNET	Supported OneNET DM2.0.	R01A06

3. Improved Features

Item/Category	Brief Description	Since
NETWOK	Improved the network searching mechanism of underlying modem protocol.	R01A06
TCPIP	Fixed the bug that IPV6 communication failed issue.	R01A06
GENERAL	Enhance the NVDM management policy for more robust stability.	R01A06
GENERAL	Fixed the bug that executing AT+QSCLK in lower case return error issue.	R01A06
NETWORK	Fixed the bug that SINR value frequency hopping issue.	R01A06



OpenCPU	Fixed the bug that some GPIOs level changed during boot-up phase.	R01A06
NETWORK	Fixed the bug that EARFCN abnormal decoded issue.	R01A06
OpenCPU	Unrestricted the time interval of ADC sampling, the minimum interval can be configured to 10ms.	R01A06
OpenCPU	Modified the implementation of QI_OS_GetMessage , the message of ADC sampling, normal EINT, software Timer will be handled internally in this function, not returned from this API any more.	R01A06
NETWORK	Fixed the abnormal behavior of AT+CGATT=1 issue.	R01A06
TCPIP	Fixed the bug that DNS parse failed by executing AT+QNTP.	R01A06
GENERAL	Fixed the bug that GPT timer low probability fails to trigger callback.	R01A06
OpenCPU	Fixed the bug that the UART will be stuck when receiving 1400 bytes in one time.	R01A06
OneNET	Fixed the bug that UE can still send CON type data when received RST from the server.	R01A06



4. Functions

	Function	
Bacir	FIINCTION	

OneNET

Υ

Protocol Function

TCP/UDP	NITZ	PING	NTP	LwM2M	MQTT
Υ	Υ	Υ	Υ	Υ	Υ

Special Function

DFOTA	PSM	OpenC PU
Υ	Υ	Υ

NOTES

- 1. Y means the firmware supports this function.
- 2. N means the firmware does not support this function.