

Client: Midwest Manufacturing Inc.	Date of Service: July 28, 2026 :
Site Location: Plant #3 - 1400 Industrial Pkwy, Gary, IN	Technician: David Miller (Tech ID: 8042)
Contact: Robert Vance (Maintenance Mgr)	Asset / Serial ID: CNC-Milling Unit #04 (SN: 883-9021)

1. Work Performed & Findings

Performed emergency diagnostic on main drive motor overheating issue. Replaced degraded thermal coupling, flushed cooling lines, and updated firmware to v4.2.1. System recalibrated and load-tested for 45 minutes under nominal factory conditions with zero thermal warnings.
--

2. Parts & Materials Used

Part #	Description	Qty	Status
TC-9042	High-Temp Thermal Coupling	1	Replaced
CL-1020	Synthetic Coolant Fluid (1L)	2	Consumed
FW-4200	Firmware Update Flash Memory	1	Installed

3. Job Status & Follow-Up

Job Status: Completed / Operable	Action Required: Routine inspection recommended in 90 days.
---	--

Technician Signature:David Millersignature:

Client Sign-Off:Robert Vanceeff: