Electrical Calibration Workload Matrix



			Shile Oalibustous										
					Fluke Calibrators			Electrical			Temperature/		
	Multi-Product Calibrators			Multifunction Calibrators		Oscilloscope Calibrators		Tester Calibrator	Power Standards		Pressure Calibrator	Notes & Comments	
Workload	5080A	9100	5500A	5522A	5700A	5720A	5820A	9500B	5320A	6100B	6105A	525B	
Analog/Panel meters													
High burden meters													
Low burden meters									V dc & V ac			V dc, I dc & R	
DMMs													
Basic DCV Accuracy	100 ppm	60 ppm	50 ppm	11 ppm	6.4 ppm	3.25 ppm	n/a	n/a	0.10 %	112 ppm	42 ppm	40 ppm	
3.5 digits (typ. ± 0.3 % dc V)									V dc & V ac			V dc, I dc & R	
4.5 digits (typ. ± 0.025 % dc V)													
5.5 digits (typ. ± 0.015 % dc V)													
6.5 digits (typ. ± 0.0024 % dc V)													
7.5 digits (typ. ± 12 ppm dc V)													
8.5 digits (typ. ± 3.9 ppm dc V)													Application Note for Special Metrology
Temperature/Pressure													
RTD Simulate													
RTD Measure								-					
Thermocouple Simulate													
Thermocouple Measure													
Pressure Modules				opt								opt	
Oscilloscopes			annel			T	1-5 ch	nannels				l	
200 MHz to 600 MHz	200 MHz opt	250 MHz or 600 MHz opt	300 MHz or 600 MHz opt	600 MHz opt			600 MHz	600 MHz					
1.1 GHz				opt			opt	opt					
2.1 GHz							opt	opt					
3.2 GHz								opt					
6 GHz								opt					
25 ps fast edge								opt					For scopes to 14 GHz
Safety testers													
Hipot													
Megohm meters	opt	opt											
Installation													
PATs													
Continuity	opt	opt											
Loop impedance													
Leakage current													
Ground bond													
RCD/GFCI													
Medical safety													
Power/Energy													
Wattmeters		opt											
Harmonic analyzers		opt											
Flicker meters				PQ opt									
Phase angle meters				PQ opt									
Power analyzers				PQ opt									
Power recorders		opt											
Secondary Energy Standards													
Watthour/Energy meters													
Other													
Clamp Meters													Could require optional 50T Coils
LCR Meters		RC only	RC only	RC only									-
Process Calibrators			2 2,										
Data Acquisition													
Non Sine waveforms													Example: square, triangle truncated sine, etc.
RF Millivolt Meters					opt	opt							Sinewave up to 30 MHz
# of calibrator functions	8	11	11	11	5	5	11+	11+	9	8	8	9	
or ourseless functions			••									,	