

Phone: 301-706-7951 Email: crofton@comcast.net

Date: 10-30-2016

Invoice #: 3671

TO: EURO MOTORCARS

0 VA

	Description	Qty	Rate	Amount
1.	12 ES350 C2473481 - STK# K5542 - REP FEE	1	150	150.00
2.	05 LS430 50180311 - STK# MB150547A - REP FEE	1	150	150.00
3.	09 MAXIMA 9C860320 - STK# A15095A - REP FEE	1	150	150.00
4.	07 FJ 70060930 - STK# C0584 - REP FEE	1	150	150.00
5.	07 FJ 70060930 - STK# C0584 - REP FEE	1	150	150.00
6.	08 SPORT 8A163760 - STK# MB150768A - REP FEE	1	150	150.00
7.	08 RANGE ROVER S/C 8A276614 - REP FEE	1	150	150.00
8.	10 CTS-V A0138783 - REP FEE	1	150	150.00
9.	09 128I CONV 9VJ76957 - REP FEE	1	150	150.00
10.	09 HIGHLANDER LIMITED 92075887 - REP FEE	1	150	150.00
11.	07 335I 7VH20594 - STK# MB150657A - REP FEE	1	150	150.00
12.	10 LACROSS AF180167 - STK# MB142184A - REP FEE	1	150	150.00
13.	09 A4 9N052096 - STK# MB150534B - REP FEE	1	150	150.00
14.	09 A4 9N052096 - STK# MB150534B - REP FEE	1	150	150.00
15.	12 MUSTANG C5242722 - STK# C0550A - REP FEE	1	150	150.00
16.	12 MUSTANG C5242722 - STK# C0550A - REP FEE	1	150	150.00
17.	11 CTS B0113676 - STK# K5521A - REP FEE	1	150	150.00
18.	12 PRIUS C1482152 - STK# S0415A - REP FEE	1	150	150.00
19.	12 ES350 C2501362 - STK# MB150770A - REP FEE	1	150	150.00
20.	13 A6 DN113872 - STK# MB150763A - REP FEE	1	150	150.00
21.	12 PRIUS C3126465 - STK# C0587 - REP FEE	1	150	150.00
22.	08 911 CAB 8S765906 - STK# C0515A - REP FEE	1	150	150.00
23.	08 911 CAB 8S765906 - STK# C0515A - REP FEE	1	150	150.00
24.	14 XV E8245320 - STK# MB150083C - REP FEE	1	150	150.00

Phone: 301-706-7951 Email: crofton@comcast.net

Date: 10-30-2016

Invoice #: 3671

26. 11 27. 14 28. 05 29. 05 30. 14 31. 03 32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	2 AVALANCHE CG120768 - REP FEE  1 X6 BLZ95683 - STK# A15112A - REP FEE  4 COROLLA S EC021931 - STK# S0483A - REP FEE  5 M3 COUPE 5PN61323 - STK# C0653 - REP FEE  6 M3 COUPE 5PN61323 - STK# C0653 - REP FEE  4 MAZDA GRAND TOURING E1100124 - STK# A15388 - REP FEE  3 325I 3KL88214 - STK# C0665 - REP FEE  2 135I COUPE CVM11823 - STK# C0661 - REP FEE  3 GS350 AWD D5012763 - STK# MB151234A - REP FEE  3 EVOQUE DH801750 - STK# C0679 - REP FEE  3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1 1 1 1 1 1 1 1 1	150 150 150 150 150 150 150 150 150	150.00 150.00 150.00 150.00 150.00 150.00 150.00 150.00 150.00
27. 14 28. 05 29. 05 30. 14 31. 03 32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	4 COROLLA S EC021931 - STK# S0483A - REP FEE 5 M3 COUPE 5PN61323 - STK# C0653 - REP FEE 5 M3 COUPE 5PN61323 - STK# C0653 - REP FEE 4 MAZDA GRAND TOURING E1100124 - STK# A15388 - REP FEE 3 325I 3KL88214 - STK# C0665 - REP FEE 2 135I COUPE CVM11823 - STK# C0661 - REP FEE 2 2500 C5716280 - STK# 150011A - REP FEE 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1 1 1 1 1	150 150 150 150 150 150 150	150.00 150.00 150.00 150.00 150.00 150.00 150.00
28. 05 29. 05 30. 14 31. 03 32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	5 M3 COUPE 5PN61323 - STK# C0653 - REP FEE 5 M3 COUPE 5PN61323 - STK# C0653 - REP FEE 4 MAZDA GRAND TOURING E1100124 - STK# A15388 - REP FEE 5 3 325I 3KL88214 - STK# C0665 - REP FEE 6 135I COUPE CVM11823 - STK# C0661 - REP FEE 6 2 2500 C5716280 - STK# 150011A - REP FEE 6 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 6 3 EVOQUE DH801750 - STK# C0679 - REP FEE 6 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1 1 1 1	150 150 150 150 150 150 150	150.00 150.00 150.00 150.00 150.00 150.00
29. 05 30. 14 31. 03 32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	5 M3 COUPE 5PN61323 - STK# C0653 - REP FEE 4 MAZDA GRAND TOURING E1100124 - STK# A15388 - REP FEE 3 325I 3KL88214 - STK# C0665 - REP FEE 2 135I COUPE CVM11823 - STK# C0661 - REP FEE 2 2500 C5716280 - STK# 150011A - REP FEE 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1 1 1	150 150 150 150 150 150	150.00 150.00 150.00 150.00 150.00
30. 14 31. 03 32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	4 MAZDA GRAND TOURING E1100124 - STK# A15388 - REP FEE 3 325I 3KL88214 - STK# C0665 - REP FEE 2 135I COUPE CVM11823 - STK# C0661 - REP FEE 2 2500 C5716280 - STK# 150011A - REP FEE 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1 1	150 150 150 150 150	150.00 150.00 150.00 150.00 150.00
31. 03 32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	3 325I 3KL88214 - STK# C0665 - REP FEE 2 135I COUPE CVM11823 - STK# C0661 - REP FEE 2 2500 C5716280 - STK# 150011A - REP FEE 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1	150 150 150 150	150.00 150.00 150.00 150.00
32. 12 33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	2 135I COUPE CVM11823 - STK# C0661 - REP FEE 2 2500 C5716280 - STK# 150011A - REP FEE 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1 1	150 150 150	150.00 150.00 150.00
33. 12 34. 13 35. 13 36. 13 37. 04 38. 11	2 2500 C5716280 - STK# 150011A - REP FEE 3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1 1 1	150 150	150.00 150.00
34. 13 35. 13 36. 13 37. 04 38. 11	3 GS350 AWD D5012763 - STK# MB151234A - REP FEE 3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1	150	150.00
35. 13 36. 13 37. 04 38. 11	3 EVOQUE DH801750 - STK# C0679 - REP FEE 3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE	1	-	
36. 13 37. 04 38. 11	3 XF SUPERCHARGED DMS69944 - STK# MB151257A - REP FEE		150	
37. 04 38. 11		1		150.00
38. 11	4 RANGE ROVER 4A160939 - STK# ML150973A - REP FEE		150	150.00
		1	150	150.00
39 07	1 335 CI BE599396 - STK# MB160085A - REP FEE	1	150	150.00
00.	7 A6 7N098538 - STK# A15545 - REP FEE	1	150	150.00
<i>40.</i> 12	2 RX350 CC153023 - STK# ML150938A - REP FEE	1	150	150.00
<i>41.</i> 13	3 ES300 D2023095 - STK# C0713 - REP FEE	1	150	150.00
<i>4</i> 2. 12	2 A4 CN014432 - STK# C0706 - REP FEE	1	150	150.00
<i>4</i> 3. 10	0 X5 AL277167 - STK# ML151127A - REP FEE	1	150	150.00
<i>44.</i> 12	2 A4 CN014432 - STK# C0706 - REP FEE	1	150	150.00
<i>4</i> 5. 13	3 HIGHLANDER DS182082 - STK# ML151127A - REP FEE	1	150	150.00
<i>46.</i> 08	8 CORVETTE CONVERTIBLE 85109882 - STK# A15336D - REP FEE	1	150	150.00
<i>47.</i> 10	O HIGHLANDER AS011386 - STK# ML151194B - REP FEE	1	150	150.00
<i>48.</i> 13	3 MUSTANG D5261511 - STK# C0744 - REP FEE	1	150	150.00
<i>4</i> 9. 12	2 S4 CA065671 - STK# C0727A - REP FEE	1	150	150.00
<i>50.</i> 08	8 M6 CONV 8CY79606 - STK# A15310B - REP FEE	1	150	150.00
<i>51.</i> 12	2 CRV CL002600 - STK# ML151237A - REP FEE	1	150	150.00
<i>5</i> 2. 08	8 CAYENNE GTS 8LA72240 - STK# C0762 - REP FEE	1	150	150.00
53. 06	6 QUATROPORTE 60023085 - REP FEE	1	150	150.00
<i>54.</i> 11	1 SIENNA BS015470 - STK# ML160009A - REP FEE	1	150	150.00
<i>55.</i> 14	4 6 E1147804 - STK# MB160246A - REP FEE	1	150	150.00

Phone: 301-706-7951 Email: crofton@comcast.net

Date: 10-30-2016

Invoice #: 3671

56.	44.0 E44.47004 OTK// MD4000404 DED EEE			
	14 6 E1147804 - STK# MB160246A - REP FEE	1	150	150.00
57.	07 GS350 70002362 - STK# MB160127A - REP FEE	1	150	150.00
58.	16 TAHOE GR104383 - STK# ML160076A - REP FEE	1	150	150.00
59.	11 A4 BA070534 - STK# ML151262A - REP FEE	1	150	150.00
60.	13 CX-5 D0132992 - STK# ML151289A - REP FEE	1	150	150.00
61.	12 CX9 C0350409 - STK# C0790 - REP FEE	1	150	150.00
62.	10 WRANGLER AL222068 - STK# C0798 - REP FEE	1	150	150.00
63.	10 WRANGLER AL222068 - STK# C0798 - REP FEE	1	150	150.00
64.	08 SPORT 8A131835 - STK# ML160104A - REP FEE	1	150	150.00
65.	11 CTS B0107638 - STK# MB160466A - REP FEE	1	150	150.00
66.	16 X3 G0M83565 - STK# ML160162A - REP FEE	1	150	150.00
67.	13 XTS D9102277 - STK# MB150910A - REP FEE	1	150	150.00
68.	13 EXPLORER DGA01084 - STK# ML160181A - REP FEE	1	150	150.00
69.	12 LR4 CA619542 - STK# ML160159A - REP FEE	1	150	150.00
70.	10 LS460 A5005755 - STK# MB160164A - REP FEE	1	150	150.00
71.	04 S2000 4T002568 - STK# C0800 - REP FEE	1	150	150.00
72.	14 ODYSSEY EB115495 - STK# ML160187A - REP FEE	1	150	150.00
73.	11 RAV4 BW092852 - STK# ML160229A - REP FEE	1	150	150.00
74.	07 GS350 70002362 - STK# MB160127A - REP FEE	1	150	150.00
75.	10 335XI COUPE AE271251 - STK# S0632A - REP FEE	1	150	150.00
76.	10 335XI COUPE AE271251 - STK# S0632A - REP FEE	1	150	150.00
77.	12 EXPLORER CGA71573 - STK# ML151319B - REP FEE	1	150	150.00
78.	13 X3 D0D04168 - STK# S0565B - REP FEE	1	150	150.00
79.	10 X5 AL311857 - STK# S0639A - REP FEE	1	150	150.00
80.	15 Q7 FD022875 - STK# ML160247A - REP FEE	1	150	150.00
81.	13 LR4 DA661600 - STK# MB160670A - REP FEE	1	150	150.00
82.	14 ENCORE EB739267 - STK# C0819 - REP FEE	1	150	150.00
83.	08 R32 8W225080 - STK# MB151253B - REP FEE	1	150	150.00
84.	12 528XI CDW03454 - STK# MB160063A - REP FEE	1	150	150.00
85.	14 CAMRY HYBRID SE LIMI EU134019 - STK# MB160362A - REP FEE	1	150	150.00
		1	150	150.00

Phone: 301-706-7951 Email: crofton@comcast.net

Date: 10-30-2016

Invoice #: 3671

87.	45 0DV 50500 400 OTKW 440000 DED 555			
	15 SRX FS529436 - STK# A16228 - REP FEE	1	150	150.00
88.	10 M6 ACY25163 - STK# A16303A - REP FEE	1	150	150.00
89.	12 Q5 CA123949 - STK# ML160456B - REP FEE	1	150	150.00
90.	12 MDX CH506954 - STK# ML151264A - REP FEE	1	150	150.00
91.	15 GX470 F5099171 - STK# S0699A - REP FEE	1	150	150.00
92.	14 QX60 EC518660 - STK# ML160416A - REP FEE	1	150	150.00
93.	11 328XI BE654974 - STK# A15806A - REP FEE	1	150	150.00
94.	13 ALTIMA DN400216 - STK# S0703A - REP FEE	1	150	150.00
95.	08 CORVETTE COUPE 85118585 - STK# MB160179B - REP FEE	1	150	150.00
96.	08 H2 8H101019 - STK# C0867 - REP FEE	1	150	150.00
97.	08 H2 8H101019 - STK# C0867 - REP FEE	1	150	150.00
98.	11 CAMARO B9203906 - STK# C0835 - REP FEE	1	150	150.00
99.	10 CAMARO A9164023 - STK# MB151465B - REP FEE	1	150	150.00
100.	13 CC DE506375 - STK# C0873 - REP FEE	1	150	150.00
101.	11 JETTA BM034059 - STK# S0635B - REP FEE	1	150	150.00
102.	13 GS350 D5002498 - STK# ML160577A - REP FEE	1	150	150.00
103.	15 COROLLA FC379460 - STK# C0874 - REP FEE	1	150	150.00
104.	11 CHEROKEE BC731589 - STK# A16452A - REP FEE	1	150	150.00
105.	11 SPORT BA273652 - STK# C0878 - REP FEE	1	150	150.00
106.	11 SPORT BA273652 - STK# C0878 - REP FEE	1	150	150.00
107.	11 CRV BL032820 - STK# ML160597A - REP FEE	1	150	150.00
108.	09 X5 3.0 9L270326 - STK# ML1604752A - REP FEE	1	150	150.00
109.	11 CHEROKEE BC731589 - STK# A16452A - REP FEE	1	150	150.00
110.	11 SPORT BA273652 - STK# C0878 - REP FEE	1	150	150.00
111.	11 SPORT BA273652 - STK# C0878 - REP FEE	1	150	150.00
112.	11 CRV BL032820 - STK# ML160597A - REP FEE	1	150	150.00
113.	09 X5 3.0 9L270326 - STK# ML160472A - REP FEE	1	150	150.00
114.	11 CHEROKEE BC731589 - STK# A16452A - REP FEE	1	150	150.00
115.	11 SPORT BA273652 - STK# C0878 - REP FEE	1	150	150.00
116.	11 SPORT BA273652 - STK# C0878 - REP FEE	1	150	150.00
117.	11 CRV BL032820 - STK# ML160597A - REP FEE	1	150	150.00

Phone: 301-706-7951 Email: crofton@comcast.net

Date: 10-30-2016

Invoice #: 3671

118.	09 X5 3.0 9L270326 - STK# ML160472A - REP FEE	1	150	150.00
119.	11 X5 35D BL661703 - STK# ML160670A - REP FEE	1	150	150.00
120.	13 ACCORD DA182594 - STK# ML160697A - REP FEE	1	150	150.00
121.	15 PILOT FB029824 - STK# ML160353A - REP FEE	1	150	150.00
122.	12 ROGUE CW396703 - STK# A16599A - REP FEE	1	150	150.00
123.	15 ROGUE FC920324 - STK# A16698A - REP FEE	1	150	150.00
124.	11 VENZA BU039509 - STK# ML160834A - REP FEE	1	150	150.00
125.	14 COMPASS ED582612 - STK# C0905 - REP FEE	1	150	150.00
126.	11 328IWGN BA191713 - STK# ML160808A - REP FEE	1	150	150.00
127.	15 RS7 FN901023 - REP FEE	1	150	150.00
128.	15 HSE FA530517 - STK# ML160844A - REP FEE	1	150	150.00
129.	10 Q5 AA095873 - STK# ML160682A - REP FEE	1	150	150.00
130.	15 F-TYPE F8K17692 - STK# A17065 - REP FEE	1	150	150.00
131.	15 NXT200T F2015380 - STK# MB161351A - REP FEE	1	150	150.00
132.	13 WRANGLER DL527647 - STK# MB151387A - REP FEE	1	150	150.00
133.	13 SPRINTER D5769112 - STK# K5463 - REP FEE	1	150	150.00
134.	15 AIRSTREAM F5951528 - STK# 150008 - REP FEE	1	150	150.00
135.	13 C250W DR297536 - STK# C0937 - REP FEE	1	150	150.00

Invoice Total: \$20,250.00