





com-
his is
COM
em.
DCE
gone
DSR
com-
output
input
ective-
n the
ection
signal
to the

Figure 10-5. DB-9 9-Pin Connector

Table 10-2: IBM PC DB-9 Signals

Pin	Description
1	Data carrier detect (DCD)
2	Received data (RxD)
3	Transmitted data (TxD)
4	Data terminal ready (DTR)
5	Signal ground (GND)
6	Data set ready (DSR)
7	Request to send (RTS)
8	Clear to send (CTS)
9	Ring indicator (RI)

07	12	21	37
08	16	22	32
06	18		
05			
03			
02			