


3.5mm Audio/Video Socket



Left - Tx Right -Rx Ground - Ground Video - Not Connected

Configure Earphone Port to Serial Console

sudo su

echo 0x01f02c10 0x00001320 > /sys/class/sunxi_dump/write

Restore Earphone Port

sudo su

echo 0x01f02c10 0x00001720 > /sys/class/sunxi_dump/write