
Coating integrity analysis

Main findings

Main factors that might contribute towards cracks are:

- Ni:S ratio, especially the nickel content itself



- Slight correlation with the cleaner bath voltage



- Slight correlation with the Decasel 5 dumps into the activator bath

