


Soldering Instructions


https://github.com/hydronics2/nrf52840-PCC-January-2020





qty(4) 100nF capacitors. not polarity specific. Push leads through PCB, solder, and trim excess leads.
















qty(3) capacitors 10uF. POLARITY!!! match the stripe to the negative symbol (-)



















qty(1) capacitors 100uF. **POLARITY!!!** match the stripe to the negative symbol (-)












qty(4) LEDs... any color. POLARITY!!! match the short leg to the flat side on the silkscreen















Solder 3 wires onto the potentiometer.