



A330
AIRPLANE FLIGHT MANUAL

EMERGENCY PROCEDURES

FIRE / SMOKE

ENG FIRE (IN FLIGHT)

Ident.: EMER-26-00005711.0001001 / 26 NOV 09

APPROVED

Criteria: A330

LAND ASAP

Shut down affected engine.

Push relevant FIRE pushbutton.

Turn off affected side engine bleed (if not automatically done).

Turn off APU bleed (if left side affected only).

Close crossbleed valve.

Discharge AGENT 1 after 10 s.

Notify ATC.

● If fire not extinguished after 30 s :

Discharge AGENT 2.

Note: Wing anti-ice is inoperative. Refer to ABN-30 A.ICE - WAI SYS FAULT or OFF.



A330
AIRPLANE FLIGHT MANUAL

EMERGENCY PROCEDURES

FIRE / SMOKE

ENG FIRE (ON GROUND)

Ident.: EMER-26-00005712.0005001 / 16 APR 10

APPROVED

Criteria: 330-200F

Set all thrust levers to idle.

● When aircraft stopped :

Set parking brake to ON.

Notify ATC.

Alert courier area occupants.

Shut down affected engine.

Push relevant FIRE pushbutton.

Discharge all fire agents of the affected engine.

● If MAN CAB PR has been used:

Check cabin differential pressure at zero before opening the doors.

Shut down other engine.

Push other engine FIRE pushbutton.

■ If evacuation required :

Initiate evacuation.

Shut down APU.

Turn off all batteries.

■ If evacuation not required :

Notify courier area occupants to remain seated.

APU FIRE

Ident.: EMER-26-00005713.0001001 / 26 NOV 09

APPROVED

Criteria: A330

LAND ASAP

Press APU FIRE pushbutton.

Discharge agent after 10 s.

Shut down APU.