

ID	0	Task Mode	Task Name	Duration	Start	Finish	12							29 Apr '12		
							M	Т	W		Т	F	S	S	М	Т
22		A ^P	Test and Verification Doc	0 days	Fri 04/05/12	Fri 04/05/12										
23		*	Develop Product	16 days	Mon 30/04/2	Sun 20/05/1								ı		-
24	İ	₹ [*]	Sensor Comm Protocol	1 day	Tue 01/05/12	Tue 01/05/12									ĺ	
25		*	Get Sensor Data	1 day	Tue 01/05/12	Tue 01/05/12									i	
26	i	*	Write to Tables	1 day	Wed 02/05/1	Wed 02/05/1										
27	į	*	Read Tables	1 day	Wed 02/05/1	Wed 02/05/1										
28	Ť	₹ [*]	Client/ Server Comm	3 days	Fri 04/05/12	Tue 08/05/12										
29		₹ [*]	Complete Server	3 days	Wed 09/05/1	Fri 11/05/12										
30		*	Server Complete	0 days	Sat 12/05/12	Sat 12/05/12										
31		*	Client Table access	3 days	Fri 04/05/12	Tue 08/05/12										
32	į	*	Client Data Display	3 days	Fri 04/05/12	Tue 08/05/12										
33	Ť	A.	Client Data Management	3 days	Wed 09/05/12	Fri 11/05/12										
34	Ť	*	Develop Client GUI	5 days	Mon 07/05/1	Fri 11/05/12										
35		*	GUI Complete	0 days	Sat 12/05/12	Sat 12/05/12										
36		₹ ·	Complete Client	5 days	Mon 14/05/1	Fri 18/05/12										
37		₹ ·	Client Complete	0 days	Sat 19/05/12	Sat 19/05/12										
38	İ	A CONTRACT	Final Tests	2 days	Sat 19/05/12	Sun 20/05/12										
39		*	Create Final Report	1 day	Mon 21/05/1	Mon 21/05/1										
40		*	Final Report	0 days	Tue 22/05/12	Tue 22/05/12										
41		*	Presentation	0 days	Tue 22/05/12	Tue 22/05/12										





