

长电科技 (除州) 有限公司

Changjiang Electronics Technology (chuzhou) Co. Ltd

Serial Number: CZ-201507049 2015/7/10 Data received: Data completed: 2015/7/11 Prepared By Checked By Approved By

朱文广	张涛	王震

[Information Of Product]

Customer	深圳康鸿微电子	Device	MMBTA92
Package type	SOT-23	Lot number	NA
Work Order	NA	Qty submitted	2
Fail rate	NA	Type of request	客诉

[Sample /Lot Failure Description]

- 1、客户投诉保护板产品组装测试时不能充电也不能放电,经分析为保护板上的MMBTA92产品不良导致,确认为板上A92产品C/E极 有漏电现象;
- 2、客户反馈2颗不良品,编号:1、2#;

[FA Summary]

- 1、样管已使用,外观无异常;
- 2、JUNO测试: 1、2#样管电参数均无异常;
- 3、图示仪验证发现: 1、2#样管漏电ICBO\ICEO\IEB曲线验证均无异常;
- 4、X-RAY检查: 未见焊线异常;


FA result:

客户反馈2颗样管,经分析电参数无异常;


[FA Step]

■ External package Analysis


样管已使用,外观无异常;




#-正面




#-反面



#-正面








■ ATE test

JUNO测试: 1、2#样管电参数均无异常;

Item Name:	1 CONT	2 VFBC	3 VFBE	4 ICEO	5 BVCBO	6 BVCEO	7 BVCEO	8 BVCEO	9 ICEO	10 DIVID	11 DELTA	12 BVEB	13 ICBO
Bias1:	IB=-1.00mA	IB=-10.0mA	IB=-10.0mA	VCE=-5.00V	IC=-100uA	IC=-1.00mA	IC=-100uA	IC=-30. OuA	VCE=-200V	Value1=#7	Value1=#7	IE=-100uA	VCB=-200V
Bias2:										Value2=#8	Value2=#8		
Bias3:					Vmax=-700V	Vmax=-600V	Vmax=-600V	Vmax=-600V				Vmax=-030V	
Min Limit:	00.00m	-0.300V	-0.300V	-	-315. OV	-310.0V	-310. OV	-310. OV		-	-10.00	-5. 500V	
Max Limit:	-200. OmV	-2.000V	-2.000V	-5.000mA	-699. OV	-590. OV	-590. OV	-590. 0V	-150. OnA	1.000	10.00	-29.00V	-100. OnA
Serial# Bin#													
1 5	-02.88mV	-743.8mV	-754.8mV	-4.583nA	-424. OV	-386.4V	-385.5V	-386. 2V	-2. 038nA	998.1m	000.7	-11.02V	-2. 360nA
2 5	-02.88mV	-770.7mV	-754.2mV	-4.433nA	-432.5V	-395.8V	-395.5V	-396. 1V	-2. 102nA	998.4m	000.6	-10.69V	-1.945nA


Curve trace


图示仪验证发现: 1、2#样管漏电ICBO\ICEO\IEB曲线验证均无异常;




■ X-ray Inspection

X-RAY检查:未见焊线异常;







The End

格式Format: 05-12-046-R02 版号Rev.:A