Bayshore Collision Center (fictional, for classroom use)

Repair Estimate

Estimate number: BCC-77215 Date: 2026-10-29
Customer: Jordan Ellis
Vehicle: 2021 Honda Civic, plate JXR-4417
Insurance: HarborClaim, policy HC-AUTO-5318

Parts

Rear bumper cover (OEM)	$612.00
Trunk lid (OEM)	$894.50
Left tail lamp assembly	$318.90
Clips, brackets and hardware	$86.00

Labor and paint

Body labor, 14.5 hours at $62.00	$899.00
Paint and materials	$540.00
Rear camera recalibration	$136.00

Total estimate $3,486.40

Estimate valid for 30 days. Hidden damage found during repair will be reported to the insurer before any additional work.