ДЛИНА ПЕЧИ L= 70.00 ВЫСОТА ПЕЧИ H=100.00 УД. ЭЛ. СОПРОТИВЛЕНИЕ RO = 1.500

### КООРДИНАТЫ ЭЛЕКТРОДОВ В ИСХОДНОЙ СИСТЕМЕ

U 33.00 33.00 33.00 33.00 -33.00 -33.00 -33.00 -33.00 -33.00

V 7.30 23.80 40.30 56.80 73.30 73.30 56.80 40.30 23.80 7.30

# РАДИУСЫ ЭЛЕКТРОДОВ

.19 .19 .19 .19 .19 .19 .19 .19

#### ДЛИНЫ ЭЛЕКТРОДОВ

КОЛИЧЕСТВО СИЛОВЫХ ГРУПП NP = 8 НАЧАЛЬНЫЕ НАПРЯЖЕНИЯ U0: 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 ИСХОДНЫЕ МОЩНОСТИ P0: 65000.0 65000.0 65000.0 65000.0 65000.0 65000.0 65000.0

## КОЭФФИЦИЕНТЫ НАПРЯЖЕНИЙ

B(1, 1, 1) = -1.00 B(2, 1, 2) = .50 B(2, 2, 2) = -.87 B(3, 1, 3) = .50 B(3, 2, 3) = .87 B(4, 1, 4) = -1.00 B(5, 1, 5) = -1.00 B(6, 1, 6) = .50 B(7, 2, 7) = .87 B(8, 1, 8) = -1.00 B(6, 1, 6) = .50

# КОЭФФИЦИЕНТЫ МОЩНОСТЕЙ

A(1, 1, 1, 1) = -1.00 A(2, 2, 2, 1) = .50 A(2, 2, 2, 2) = -.87 A(2, 2, 1, 1) = .50 A(2, 2, 1, 2) = -.87 A(3, 3, 3, 1) = .50 A(3, 3, 3, 2) = .87 A(3, 3, 2, 1) = .50 A(3, 3, 2, 2) = .87 A(3, 3, 1, 1) = .50 A(3, 3, 1, 2) = .87 A(4, 4, 5, 1) = 1.00 A(5, 5, 6, 1) = -1.00 A(6, 6, 7, 1) = .50 A(6, 6, 6, 7, 2) = -.87 A(6, 6, 6, 1) = .50 A(6, 6, 6, 2) = -.87 A(7, 7, 8, 2) = .87 A(7, 7, 7, 1) = .50 A(7, 7, 7, 2) = .87 A(7, 7, 7, 6, 1) = .50 A(7, 7, 7, 2) = .87 A(7, 7, 7, 6, 1) = .50 A(7, 7, 6, 2) = .87 A(8, 8, 10, 1) = 1.00 A(6, 6, 6, 2) = .50 A(7, 7, 6, 2) = .87 A(8, 8, 10, 1) = 1.00 A(8, 8, 10, 1) = 1.00 A(8, 8, 10, 1) = 1.00

 U0:
 208.804800
 225.519200
 225.054200
 202.273800

 202.273800
 225.054200
 225.519100
 206.804800

U(1, 2)=-206.8 - .0 U(2, 3)= 112.8 - -195.3 U(3, 4)= 112.5 - 194.9 U(4, 5)=-202.3 - .0 U(6, 7)=-202.3 - .0 U(7, 8)= 112.5 - -194.9 U(8, 9)= 112.8 - 195.3 U(9,10)=-206.8 - .0

ТОКИ 1 2 3 4 5 6 7 8 9 10

-312. 421. -4. -424. 319. -319. 424. 4. -421. 312.

-82. -186. 538. -184. -86. -86. -184. 538. -186. -82.

322. 460. 538. 462. 330. 330. 462. 538. 460. 322.