- 1. What gain parameters did you end up using for your PI controller?
 - a. We chose 8 and 3
 - Describe the response of the system to speed changes
 - When we increased the Ki the speed of the motor got to the expected speed faster. If we increase Ki alone the speed over corrected. When we increased Kp the motor speed was more linear when getting up to the expected speed.