


R = 48 Ohm; training / held-out







Held-out RMSE = 0.0476 A




Held-out RMSE = 0.00109 V




R = 96 Ohm; training / held-out





Held-out RMSE = 0.0609 A



Held-out RMSE = 0.000648 V

