



R = 20 Ohm; training / held-out






R = 40 Ohm; training / held-out







Held-out RMSE = 0.0238 A



Held-out RMSE = 0.0237 A



Held-out RMSE = 0.00559 V



Held-out RMSE = 0.00518 V

