QUALITY REPORT QR-ABC-2026
Supplier VEND-ABC
Material MAT-SEMI-1
Lot inspected at PL-IN-CHN
Defect: solder void above 8 percent on sample 12
Disposition: hold remaining lots; do not ship against PO-1842 until