

Daily Industrial Safety Report

Generated on: 08-07-2026 08:43

Metric	Value
Total Records	5000
Total Alerts	707
Critical Risks	206
High Risk Zones	Furnace Area, Chemical Storage, Zone-A
Worker Violations	859
Maintenance Issues	784
Permit Violations	1335
Average Gas Level	41.76
Average Temperature	38.11
Average Vibration	3.75

Latest High Priority Alerts

Time	Zone	Worker	Risk	Reason
2026-07-08 08:43	Furnace Area	Karan Singh	High (70)	High temperature in work area; High machine vibration
2026-07-08 07:06	Chemical Storage	Rahul Sharma	High (65)	High gas level detected; Worker present in high-risk
2026-07-08 05:28	Furnace Area	Anjali Das	High (67)	Temperature is slightly high; Machine vibration need
2026-07-08 04:28	Furnace Area	Vikram Rao	High (77)	Noise level may affect worker safety; PPE violation
2026-07-08 03:43	Furnace Area	Sneha Patel	Critical (85)	Temperature is slightly high; Machine vibration need
2026-07-08 02:58	Furnace Area	Meera Joshi	Critical (91)	Temperature is slightly high; Machine vibration need
2026-07-08 02:48	Furnace Area	Vikram Rao	Critical (90)	High temperature in work area; Machine vibration n
2026-07-08 02:18	Zone-B	Neha Verma	High (80)	Machine vibration needs attention; Maintenance is c
2026-07-08 01:58	Chemical Storage	Neha Verma	Critical (100)	High gas level detected; High machine vibration; Pr
2026-07-08 01:48	Chemical Storage	Neha Verma	High (82)	PPE violation found; Worker present in high-risk zon