
A window includes now
B window excludes now
C no window
(a)
RMS (m/s²)
1.25
1.00
0.75
0.50
0.25
0.00
CAUTION
baseline
motor off: RMS stays near 0.32, not 0
shaded: motor switched off
(b)
Spread (m/s²)
1
0.3
0.1
0.03
clear 0.204
STOPPED 0.102
69.3 s, stop prompt to first STOPPED
State
OK
STOPPED
OK
OFF SCHEDULE
OK
OK
0
100
200
300
400
500
Time from start of run (s)