Repair Recommendations:

The image shows a large hole in the fuselage of an aircraft. The hole is located near the tail of the aircraft, and it appears to have been caused by an impact with another object. The impact caused the fuselage to tear and peel away from the aircraft's frame. The repair of this damage will require a significant amount of time and money. The fuselage will need to be patched, and the aircraft will need to be repainted. The cost of the repair will depend on the extent of the damage and the type of aircraft. In addition to the cost of the repair, the airline will also need to consider the cost of lost revenue while the aircraft is out of service. The airline will also need to factor in the cost of any potential lawsuits that may arise from the incident. The repair of this damage is a complex and expensive process. However, it is essential to ensure the safety of the aircraft and its passengers.

Crack 1: 1.10 cm

Crack 2: 1.18 cm

Crack 3: 4.02 cm

Crack 4: 0.33 cm

Crack 5: 0.11 cm

Crack 6: 27.31 cm

Fault Detection Report

Result: Fault detected! Check the wiring.

Faulty: True

