
COOL
nozzle off
req
HEATING_UP
nozzle heating
$(T_n < T_{hi})_{>1}$
/ heated+ = false
$(T_n \geq T_{hi})_{>1}$
/ heated+ = true
COOLING
nozzle off
¬req
HEATED
nozzle heating
$T_n > T_{max}$
$T_n < T_{hi}$
TOO_HOT
COOLED_BUT_
NOT_SUPPOSED_TO